

## Issues

| #    | Project                          | Tracker   | Status   | Priority  | Subject  | Assignee   | Category | Due date   |
|------|----------------------------------|-----------|----------|-----------|--|------------|----------|------------|
| 1113 | _dev.xdevs.com                   | Bug       | Closed   | Immediate | Repository system security update  | tin        |          | 05/22/2014 |
| 873  | _dev.xdevs.com                   | Feature   | Closed   | Immediate | Update engine to 2.4.1   | tin        |          | 12/23/2013 |
| 263  | _dev.xdevs.com                   | Feature   | Closed   | Urgent    | Devsite crashes after few days   | tin        |          | 10/14/2012 |
| 292  | ALTERA 672 Checkout board repair | Support   | Closed   | High      | Search documentation for "ALTERA 672 Checkout board"   | tin        |          | 10/10/2012 |
| 291  | ALTERA 672 Checkout board repair | Bug       | Closed   | High      | VCC SSO замкнут на землю?  | lzerg      |          |            |
| 288  | Keithley 2001 repair             | Bug       | Closed   | High      | K4 - repair status.  | tin        |          | 02/28/2015 |
| 1089 | Nikon DSLR                       | Feature   | Closed   | High      | Repair D3  | tin        |          | 05/11/2014 |
| 807  | Tektronix TDS/CSA7000 (CSA7404)  | Support   | Closed   | High      | Tek CSA7404 scope repair article worklog   | tin        |          | 01/04/2014 |
| 1216 | _dev.xdevs.com                   | Support   | Closed   | High      | Update redmine to latest 3.0.x trunk   | tin        |          | 07/20/2015 |
| 338  | _dev.xdevs.com                   | Feature   | Closed   | High      | Monospace font for <pre> and repository source view  | tin        |          | 12/30/2012 |
| 333  | _dev.xdevs.com                   | Bug       | Rejected | High      | Caching working not right, need refresh page manually  | tin        |          |            |
| 242  | _dev.xdevs.com                   | Bug       | Closed   | High      | Users cannot login with current password, must use "lost password feature" due to security enhancement | tin        |          | 12/30/2011 |
| 1227 | content_mgmt                     | Feature   | Closed   | High      | NI HS-GPIB-USB review  | tin        | Article  | 08/16/2015 |
| 293  | ALTERA 672 Checkout board repair | Feature   | Closed   | Normal    | Power check - voltage in spec, power good - ok?  | lzerg      |          |            |
| 289  | ALTERA 672 Checkout board repair | Support   | Closed   | Normal    | Receive board from EMS   |            |          | 08/10/2012 |
| 119  | AM2                              | Bug       | Closed   | Normal    | R7,R8 - fix value to allow generator running   | tin        |          |            |
| 233  | ARM-camp                         | Feature   | Rejected | Normal    | Send development miniboard on AT91SAM7S128 to Adrian   | tin        |          | 12/28/2011 |
| 232  | ARM-camp                         | Feature   | Rejected | Normal    | Add Redmine guide and intro based on dev.xdevs.com project   | tin        |          | 12/30/2011 |
| 230  | ARM-camp                         | Feature   | Closed   | Normal    | Add mercurial DVCS intro to wiki   | ARandomOWI |          | 12/14/2011 |
| 229  | ARM-camp                         | Feature   | Rejected | Normal    | Add intro page about STM-Discovery to wiki, create first project                                       | tin        |          | 01/15/2012 |
| 740  | E-table 2                        | Feature   | Closed   | Normal    | Onboard workspace PC system  | tin        |          |            |
| 739  | E-table 2                        | Support   | Closed   | Normal    | Create initial design concept  | tin        |          | 04/26/2015 |
| 1361 | Fluke 720A repair                | Support   | Closed   | Normal    | Inspection, photos and check   | tin        |          | 08/09/2016 |
| 1289 | HP 3458A                         | Feature   | Closed   | Normal    | 1ppm/hour drift on new ADC board   | tin        |          |            |
| 1272 | HP 3458A                         | Feature   | Closed   | Normal    | Install memory option 001 back   | tin        |          | 11/30/2015 |
| 1261 | HP 3458A                         | Feature   | Closed   | Normal    | Make measurement on integrator and reference path on A3 A/D board                                      | tin        |          | 10/16/2015 |
| 1260 | HP 3458A                         | Feature   | Closed   | Normal    | ERROR 114 -- balanced multislope convergence   | tin        |          |            |
| 1259 | HP 3458A                         | Bug       | Closed   | Normal    | ERROR 114 -- multislope rundown convergence  | tin        |          |            |
| 1249 | HP 3458A                         | Feature   | Closed   | Normal    | Digikey order 2  | tin        |          |            |
| 1248 | HP 3458A                         | Rework    | Closed   | Normal    | Make CPLD logic replacement for PAL address decoder 03458-88804  | tin        |          |            |
| 1243 | HP 3458A                         | Feature   | Closed   | Normal    | Replace capacitors on A6 board.  | tin        |          |            |
| 1242 | HP 3458A                         | Feature   | Closed   | Normal    | Make 3D drawing for LTZ1000 plastic cap  | tin        |          | 10/05/2015 |
| 1237 | HP 3458A                         | Feature   | Closed   | Normal    | Order replacement parts from Keysight  | tin        |          |            |
| 1236 | HP 3458A                         | Rework    | Closed   | Normal    | Test mains power supply domain & transformer   | tin        |          |            |
| 1235 | HP 3458A                         | Rework    | Closed   | Normal    | Buy and install A9 reference board   | tin        |          |            |
| 1234 | HP 3458A                         | Feature   | Closed   | Normal    | Receive unit, initial inspection   | tin        |          | 09/17/2015 |
| 1065 | HP 4263B                         | Support   | Closed   | Normal    | Modify LCR probe according to Agilent connection spec.   | tin        |          | 04/20/2014 |
| 947  | HP 4263B                         | Feature   | Closed   | Normal    | PCB daughter board schematics recovery   | tin        |          | 03/02/2014 |
| 945  | HP 4263B                         | Feature   | Closed   | Normal    | Hack to enable Option 001 and 002  | tin        |          |            |
| 910  | HP 4263B                         | Feature   | Closed   | Normal    | Replace damaged components   | tin        |          |            |
| 907  | HP 4263B                         | Feature   | Rejected | Normal    | Add option updates for 001 and 002   | tin        |          | 01/12/2014 |
| 861  | HP 4263B                         | Feature   | Closed   | Normal    | Initial check and repair estimate  | tin        |          | 01/11/2014 |
| 860  | HP 4263B                         | Feature   | Closed   | Normal    | Pay for LCR meter  | tin        |          | 12/14/2013 |
| 639  | HP/Agilent 33120A                | Support   | Closed   | Normal    | Add related documentation  | tin        |          | 11/18/2012 |
| 638  | HP/Agilent 33120A                | Feature   | Closed   | Normal    | Inspect unit, diagnose and isolate problem   | tin        |          |            |
| 1266 | HP3245A                          | Feature   | Closed   | Normal    | Receive unit, initial inspection and tests   | tin        |          |            |
| 1088 | KX                               | Inventory | Closed   | Normal    | MAX6610AUT temp sensor SOT23-6 THD box 10pcs   | tin        |          |            |
| 1087 | KX                               | Inventory | Closed   | Normal    | LTC2057HS8 - 17pcs THD box   | tin        |          |            |
| 1066 | KX                               | Feature   | Closed   | Normal    | VPG resistor for prototype build   | tin        |          | 05/31/2014 |
| 998  | KX                               | Support   | Closed   | Normal    | Order PCBs for VREF A00 module   | tin        |          | 03/27/2014 |
| 941  | KX                               | Inventory | Closed   | Normal    | LTZ1000ACH SUPER-ZENER VREF  | tin        |          |            |
| 940  | KX                               | Inventory | Closed   | Normal    | LTC1043CSWPBF SOW18   Building block SW-CAP DUAL   | tin        |          |            |
| 939  | KX                               | Inventory | Closed   | Normal    | LT1116CS8  | tin        |          |            |
| 938  | KX                               | Inventory | Closed   | Normal    | LT1223CS8  | tin        |          |            |
| 934  | KX                               | Inventory | Closed   | Normal    | PMBFJ111-215 JFET NCH 40V 20mA SOT23-3   | tin        |          |            |
| 933  | KX                               | Inventory | Closed   | Normal    | PMBFJ620-115 NJFET DUAL 25V SOT363   | tin        |          |            |
| 930  | KX                               | Inventory | Closed   | Normal    | TL7705ACDR   | tin        |          |            |
| 927  | KX                               | Inventory | Closed   | Normal    | AD7490BRUZ   | tin        |          |            |
| 926  | KX                               | Inventory | Closed   | Normal    | LTC1050CS8   | tin        |          |            |
| 925  | KX                               | Inventory | Closed   | Normal    | LMV324I  | tin        |          |            |
| 1193 | Keithley 2000                    | Feature   | Closed   | Normal    | Buy parts for repair   | tin        |          | 05/30/2015 |
| 1160 | Keithley 2000                    | Support   | Closed   | Normal    | Backup EEPROM with programm memory A02   | tin        |          |            |
| 1159 | Keithley 2000                    | Rework    | Closed   | Normal    | Clean board and restore damaged traces from leaked electrolyte   | tin        |          | 09/22/2014 |
| 1158 | Keithley 2000                    | Feature   | Closed   | Normal    | Broken K2000 unit received, need repairs   | tin        |          |            |
| 874  | Keithley 2000                    | Feature   | Closed   | Normal    | Keithley 2000 schematics   | tin        |          | 12/23/2013 |
| 1188 | Keithley 2001 repair             | Feature   | Closed   | Normal    | Dump firmware B17 from 2001M   | tin        |          |            |
| 1185 | Keithley 2001 repair             | Bug       | Closed   | Normal    | Repair status for very first 2001 unit   | tin        |          |            |
| 1184 | Keithley 2001 repair             | Bug       | Closed   | Normal    | Repair status  | tin        |          |            |
| 1141 | Keithley 2001 repair             | Feature   | Closed   | Normal    | Восстановление источника тока и диапазонов измерения сопротивления                                     | tin        |          |            |

| #    | Project              | Tracker | Status   | Priority | Subject  | Assignee | Category | Due date   |
|------|----------------------|---------|----------|----------|--|----------|----------|------------|
| 1131 | Keithley 2001 repair | Support | Closed   | Normal   | Schematics for voltage reference LM399   | tin      |          | 07/11/2014 |
| 956  | Keithley 2001 repair | Feature | Closed   | Normal   | Calibration constants for K2001 units  | tin      |          | 02/15/2014 |
| 895  | Keithley 2001 repair | Feature | Closed   | Normal   | 304.x series self-test errors (Ohm)  | lzerg    |          | 01/05/2014 |
| 894  | Keithley 2001 repair | Support | Closed   | Normal   | iZerg Keithley serial number request   | lzerg    |          | 01/05/2014 |
| 891  | Keithley 2001 repair | Feature | Closed   | Normal   | Self-test errors diagnosis   | tin      |          | 01/05/2014 |
| 890  | Keithley 2001 repair | Support | Closed   | Normal   | Install DS1245Y for MEM2 option  | tin      |          | 01/04/2014 |
| 889  | Keithley 2001 repair | Bug     | Closed   | Normal   | Replace fan  | tin      |          | 01/05/2014 |
| 888  | Keithley 2001 repair | Feature | Closed   | Normal   | Send 2001 DMM for calibration to Tektronix Taiwan                                  | tin      |          | 01/12/2014 |
| 885  | Keithley 2001 repair | Feature | Closed   | Normal   | Keithley 2001 thermal evaluation   | tin      |          | 01/01/2014 |
| 884  | Keithley 2001 repair | Feature | Closed   | Normal   | UART protocol between front panel board and digital board.                         | tin      |          |            |
| 879  | Keithley 2001 repair | Bug     | Closed   | Normal   | Issue list update  | tin      |          |            |
| 871  | Keithley 2001 repair | Bug     | Closed   | Normal   | Replace C108 capacitor   | tin      |          | 12/31/2013 |
| 869  | Keithley 2001 repair | Feature | Closed   | Normal   | Spec test  | tin      |          | 12/15/2013 |
| 868  | Keithley 2001 repair | Feature | Closed   | Normal   | Assembly meter for function checks.  | tin      |          | 12/15/2013 |
| 867  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix error 410.1, 411.1, 411.2 - TRMS / TRMS Filter                                 | tin      |          | 12/29/2013 |
| 866  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix error 409.6 -- ÷750 correction factor; signal comparisons                      | tin      |          | 12/22/2013 |
| 865  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix errors 407.1, 407.2, 407.3 - Front end 2V/200V/750V                            | tin      |          | 12/22/2013 |
| 864  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix error 406.6 - Voltage comparison   | tin      |          | 12/22/2013 |
| 863  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix errors 405.2, 405.4, 405.6, 405.8, - Absolute value x10 gain comparison        | tin      |          | 12/22/2013 |
| 862  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix errors 404.1, 404.2, 404.3, 404.4, 404.5 - Absolute value (x1 gain);           | tin      |          | 12/22/2013 |
| 859  | Keithley 2001 repair | Feature | Closed   | Normal   | Схема аналоговой платы (Keithley 2001-102-04J)                                     | tin      |          | 07/11/2014 |
| 858  | Keithley 2001 repair | Bug     | Closed   | Normal   | VFD Power supply issues?   | tin      |          |            |
| 856  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix error 412.1 - AC amps switch   | tin      |          | 12/28/2013 |
| 855  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix error 403.1 - Signal switching; ground switch                                  | tin      |          | 12/21/2013 |
| 854  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix error 402.1 - Signal switching; frequency switch                               | tin      |          | 12/14/2013 |
| 852  | Keithley 2001 repair | Feature | Closed   | Normal   | LabView control panel development  | tin      |          | 02/28/2014 |
| 840  | Keithley 2001 repair | Support | Closed   | Normal   | 3 ADC modules shipped, receive and test rest units                                 | tin      |          | 11/09/2013 |
| 820  | Keithley 2001 repair | Support | Closed   | Normal   | Schematics for digital board (Keithley 2001-142-06H)                               | tin      |          | 10/31/2013 |
| 819  | Keithley 2001 repair | Support | Closed   | Normal   | Схема платы передней панели  | tin      |          | 10/08/2013 |
| 818  | Keithley 2001 repair | Support | Closed   | Normal   | Schematics for analog board (Keithley 2001-102-04L)                                | lzerg    |          | 07/21/2014 |
| 817  | Keithley 2001 repair | Support | Closed   | Normal   | Схема платы A/D (Keithley 2001-162-01G)  | tin      |          | 10/03/2013 |
| 816  | Keithley 2001 repair | Support | Closed   | Normal   | Schematics recovery for analog board Keithley 2001                                 | tin      |          | 07/21/2014 |
| 659  | Keithley 2001 repair | Bug     | Rejected | Normal   | Fix Test 412.1 - AC amps switch  | tin      |          | 01/13/2013 |
| 658  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix 401.1 - Signal switching; zero cal switch                                      | tin      |          | 01/13/2013 |
| 652  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix AC input mains curcuitry, replace electrolytic capacitors, replace transformer | tin      |          | 12/31/2012 |
| 642  | Keithley 2001 repair | Feature | Closed   | Normal   | Voltage reference block schematics recovery  | tin      |          | 12/17/2012 |
| 641  | Keithley 2001 repair | Feature | Closed   | Normal   | Finish AC input block schematics   | tin      |          | 12/18/2012 |
| 637  | Keithley 2001 repair | Support | Closed   | Normal   | Review 2001's inventory  | tin      |          | 02/16/2014 |
| 535  | Keithley 2001 repair | Bug     | Closed   | Normal   | AC voltage select unit fails   | tin      |          | 10/21/2012 |
| 343  | Keithley 2001 repair | Bug     | Closed   | Normal   | Send K2001 #5 to iZerg   | lzerg    |          | 10/31/2012 |
| 342  | Keithley 2001 repair | Bug     | Closed   | Normal   | Fix FE section on analog board   | tin      |          | 09/09/2012 |
| 297  | Keithley 2001 repair | Feature | Closed   | Normal   | Finish ADC board schematics.   | tin      |          | 12/11/2012 |
| 294  | Keithley 2001 repair | Feature | Closed   | Normal   | Read and decode firmwares for 2001 DMMs  | tin      |          | 08/10/2012 |
| 286  | Keithley 2001 repair | Feature | Closed   | Normal   | Calibrate unit (Tektronix calibration)   | tin      |          | 01/19/2014 |
| 285  | Keithley 2001 repair | Rework  | Closed   | Normal   | All functions and all ranges "Overflow"  | tin      |          | 08/05/2012 |
| 284  | Keithley 2001 repair | Rework  | Closed   | Normal   | Test digital board.  | tin      |          |            |
| 283  | Keithley 2001 repair | Rework  | Closed   | Normal   | No response from analog board  | tin      |          |            |
| 282  | Keithley 2001 repair | Rework  | Closed   | Normal   | Install display board  | tin      |          |            |
| 281  | Keithley 2001 repair | Feature | Closed   | Normal   | Display board move to unit #4  | tin      |          |            |
| 279  | Keithley 2001 repair | Feature | Closed   | Normal   | Schematics RE - analog board   | tin      |          | 07/31/2012 |
| 278  | Keithley 2001 repair | Feature | Closed   | Normal   | D2 - checks  |          |          |            |
| 277  | Keithley 2001 repair | Bug     | Closed   | Normal   | K2 - ERROR 405.2 - Absolute value x10 gain comparison; large +DAC output           | tin      |          |            |
| 276  | Keithley 2001 repair | Bug     | Closed   | Normal   | ERROR 404.1 - Absolute value (x1 gain); -full-scale DAC output                     | tin      |          |            |
| 275  | Keithley 2001 repair | Bug     | Closed   | Normal   | K2 - Error 402.1 - Frequency switch  | tin      |          |            |
| 274  | Keithley 2001 repair | Bug     | Closed   | Normal   | K2 : ERROR 401.1 - Signal switching; zero cal switch                               | tin      |          |            |
| 273  | Keithley 2001 repair | Support | Closed   | Normal   | Buy components for repair  | tin      |          | 07/30/2012 |
| 272  | Keithley 2001 repair | Support | Closed   | Normal   | K2 - repair status.  | tin      |          |            |
| 271  | Keithley 2001 repair | Feature | Closed   | Normal   | K2 : ERROR 304 Section   | tin      |          |            |
| 270  | Keithley 2001 repair | Bug     | Closed   | Normal   | K2 : ERROR 304.7 - Ohms sources; 4.4nA and 770nA                                   | tin      |          |            |
| 269  | Keithley 2001 repair | Bug     | Closed   | Normal   | K2 : ERROR 304.6 - Ohms sources; 70nA and 770nA                                    | tin      |          |            |
| 268  | Keithley 2001 repair | Bug     | Closed   | Normal   | K2 : ERROR 105.2 - System trigger bus  | tin      |          | 07/22/2012 |
| 1142 | Keithley 2002        | Feature | Closed   | Normal   | Measure LT1013+LTZ1000A VREF voltages  | tin      |          | 07/21/2014 |
| 973  | Keithley 2002        | Feature | Rejected | Normal   | Request correct repair manual for 2002   | tin      |          | 02/28/2014 |
| 958  | Keithley 2002        | Feature | Closed   | Normal   | Initial inspection for K2002 (331119346214)  | tin      |          | 02/10/2014 |
| 887  | Keithley 2400 repair | Bug     | Closed   | Normal   | Fix front panel keypad   | tin      |          | 01/01/2014 |
| 886  | Keithley 2400 repair | Support | Closed   | Normal   | Send 2400 SMU for calibration to Tektronix Taiwan                                  | tin      |          | 01/31/2014 |
| 287  | Keithley 2400 repair | Feature | Rejected | Normal   | Calibrate outputs  | tin      |          | 08/11/2012 |
| 1170 | Keithley 2510        | Feature | Closed   | Normal   | Calibrate unit   | tin      |          | 12/06/2014 |
| 1168 | Keithley 2510        | Feature | Closed   | Normal   | Get and flash correct firmware for 2510 into AT49F040 (U168)                       | tin      |          |            |
| 1167 | Keithley 2510        | Feature | Closed   | Normal   | Publish repair article about 2510 TEC SMU  | tin      |          | 12/07/2014 |
| 1166 | Keithley 2510        | Feature | Closed   | Normal   | Receive 2510 unit for repair   | tin      |          |            |

| #    | Project                         | Tracker | Status   | Priority | Subject  | Assignee | Category | Due date   |
|------|---------------------------------|---------|----------|----------|--|----------|----------|------------|
| 767  | Nikkor lens repair              | Rework  | Closed   | Normal   | Replace connection aperture ring   | tin      |          |            |
| 766  | Nikkor lens repair              | Bug     | Closed   | Normal   | Buy replacement parts for 17-35  | tin      |          | 05/31/2013 |
| 1112 | Nikon DSLR                      | Feature | Closed   | Normal   | Schematics for fake EN-EL4a battery  | tin      |          |            |
| 1080 | Nikon DSLR                      | Feature | Closed   | Normal   | Adjust EH-4 AC brick for 13VDC output for D3                               | tin      |          |            |
| 1070 | Nikon DSLR                      | Feature | Closed   | Normal   | Initial inspection   | tin      |          | 05/02/2014 |
| 4    | PWMC                            | Bug     | Closed   | Normal   | Firmware and hardware check  | tin      |          |            |
| 1299 | R&E                             | Feature | Closed   | Normal   | Help sonicyang to repair HP 34401A   | tin      |          | 01/16/2016 |
| 1123 | R&E                             | Support | Closed   | Normal   | Fluke 52 II thermometer calibration - 89020093                             | tin      |          | 06/10/2014 |
| 955  | R&E                             | Feature | Closed   | Normal   | EDC MV106 calibration  | tin      |          |            |
| 905  | R&E                             | Support | Closed   | Normal   | Buy parts for K2001 project repairs  | tin      |          | 01/05/2014 |
| 881  | R&E                             | Support | Closed   | Normal   | EDC MV106 DC Voltage standard backlog                                      | tin      |          | 12/31/2013 |
| 296  | R&E                             | Feature | Closed   | Normal   | iZerg support package  | lzerg    |          | 10/03/2012 |
| 85   | R&E                             | Feature | Closed   | Normal   | Make PCI-E videocard test power assemble kit                               | tin      |          | 11/28/2010 |
| 1108 | Raspberry Pi                    | Support | Closed   | Normal   | Update article to version 1.0  | tin      |          | 05/20/2014 |
| 1106 | Raspberry Pi                    | Feature | Closed   | Normal   | Add checksum checks/validation function                                    | tin      |          | 05/19/2014 |
| 1090 | Raspberry Pi                    | Feature | Closed   | Normal   | Install I2C support for RPI  | tin      |          |            |
| 1074 | Raspberry Pi                    | Feature | Closed   | Normal   | 3D model of DIMM adapter assembly  | tin      |          |            |
| 1073 | Raspberry Pi                    | Feature | Closed   | Normal   | Initial firmware to read/write SPD EEPROM (EC)                             | tin      |          | 05/21/2014 |
| 1072 | Raspberry Pi                    | Feature | Closed   | Normal   | Make DDR slot adapter for SPD read/write                                   | tin      |          | 05/09/2014 |
| 1071 | Raspberry Pi                    | Feature | Closed   | Normal   | Buy Raspberry Pi module  | tin      |          | 04/27/2014 |
| 880  | Tektronix TDS/CSA7000 (CSA7404) | Bug     | Closed   | Normal   | Trigger encoder shaft damaged - replace encoder Bourns EPS1E-F19 S53       | tin      |          |            |
| 857  | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed   | Normal   | Buy Tek P6205 probe for general voltage measurements (40V pk-pk)           | tin      |          | 01/31/2014 |
| 796  | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed   | Normal   | Upgrade CPU to Pentium III, add extra memory for NLX board, install DVD-RW | tin      |          |            |
| 795  | Tektronix TDS/CSA7000 (CSA7404) | Bug     | Closed   | Normal   | Channel 1 out of cal?  | tin      |          |            |
| 794  | Tektronix TDS/CSA7000 (CSA7404) | Bug     | Closed   | Normal   | Channel 2 and 3 not powering Tektronix P7380 probe, not working?           | tin      |          |            |
| 774  | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed   | Normal   | Pay for pair of Tektronix P7380 TekConnect differential 8GHz probes        | tin      |          | 06/04/2013 |
| 773  | Tektronix TDS/CSA7000 (CSA7404) | Rework  | Closed   | Normal   | Buy BR1632 3V battery for NVRAM DALLAS replacement with leads              | tin      |          |            |
| 772  | Tektronix TDS/CSA7000 (CSA7404) | Rework  | Closed   | Normal   | Install Windows 2000 SP4 Pro for test                                      | tin      |          |            |
| 771  | Tektronix TDS/CSA7000 (CSA7404) | Rework  | Rejected | Normal   | Install Windows 98 on another HDD for test.                                | tin      |          |            |
| 769  | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed   | Normal   | Try to run TDS7704B w/o connection between PPC and AQ boards?              | tin      |          | 06/02/2013 |
| 768  | Tektronix TDS/CSA7000 (CSA7404) | Feature | Closed   | Normal   | Install all system Tektronix drivers for devices on Win2000                | tin      |          | 06/30/2013 |
| 761  | Tektronix TDS/CSA7000 (CSA7404) | Rework  | Closed   | Normal   | Replace CD-ROM with DVD-RW drive   | tin      |          | 05/23/2013 |
| 760  | Tektronix TDS/CSA7000 (CSA7404) | Rework  | Closed   | Normal   | Download and write CD-R with Win98/2000                                    | tin      |          | 05/22/2013 |
| 759  | Tektronix TDS/CSA7000 (CSA7404) | Rework  | Closed   | Normal   | Replace HDD, try fresh install windows and Tek software                    | tin      |          | 05/23/2013 |
| 754  | Tektronix TDS/CSA7000 (CSA7404) | Rework  | Closed   | Normal   | Outer covers replacement parts needed                                      | tin      |          | 12/31/2013 |
| 753  | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed   | Normal   | Receive scope, initial inspection  | tin      |          | 05/31/2013 |
| 752  | Tektronix TDS/CSA7000 (CSA7404) | Feature | Closed   | Normal   | Pay for scope unit for parts   | tin      |          | 05/20/2013 |
| 872  | Tektronix TLA714                | Feature | Closed   | Normal   | Бюджет проекта   | tin      |          |            |
| 815  | Tektronix TLA714                | Feature | Closed   | Normal   | Unlock more memory for TLA7AA4   | tin      |          |            |
| 808  | Tektronix TLA714                | Feature | Closed   | Normal   | Backup NVRAM on TLA7AA4  | tin      |          | 09/20/2013 |
| 805  | Tektronix TLA714                | Bug     | Closed   | Normal   | Battery for CMOS died on PC board, date got reset                          | tin      |          | 09/15/2013 |
| 693  | Tektronix TLA714                | Feature | Closed   | Normal   | Firmware binary for TLA7AA4 5.5.003  | tin      |          |            |
| 692  | Tektronix TLA714                | Feature | Closed   | Normal   | Firmware binary for TLA7AA4 5.8.001  | tin      |          |            |
| 299  | Tektronix TLA714                | Feature | Closed   | Normal   | Add actual internal pics, add documentation                                | tin      |          | 08/25/2012 |
| 267  | Tektronix TLA714                | Feature | Closed   | Normal   | ТЕКТРОНИХ 020-2457-00 COMPRESSION PCB -to- MICTOR ADAPTER                  | tin      |          | 07/10/2012 |
| 266  | Tektronix TLA714                | Feature | Closed   | Normal   | [eBay] New in the box Tektronix Tek P6860 Probe Set A2-A3/D2-D3            | tin      |          | 07/16/2012 |
| 154  | WARP                            | Bug     | Failed   | Normal   | VNOM- not connected to ground  | tin      |          |            |
| 1336 | X-CAL                           | Feature | Closed   | Normal   | Software specification   |          |          |            |
| 1126 | _dev.xdevs.com                  | Bug     | Closed   | Normal   | Deployment issue with redmine engine                                       | tin      |          |            |
| 999  | _dev.xdevs.com                  | Support | Closed   | Normal   | Update redmine to 2.5.0  | tin      |          | 03/15/2014 |
| 898  | _dev.xdevs.com                  | Feature | Closed   | Normal   | Added issuefy importer   | tin      |          | 01/05/2014 |
| 878  | _dev.xdevs.com                  | Feature | Closed   | Normal   | Improve and bug fix for theme / stylesheets.                               | tin      |          | 12/29/2013 |
| 876  | _dev.xdevs.com                  | Feature | Rejected | Normal   | Merge with documentation site  | tin      |          |            |
| 770  | _dev.xdevs.com                  | Bug     | Closed   | Normal   | Notification emails are lost/not full                                      | tin      |          | 06/03/2013 |
| 670  | _dev.xdevs.com                  | Bug     | Closed   | Normal   | Redirects to dummy redmine host when modify items using HTTPS              | tin      |          |            |
| 654  | _dev.xdevs.com                  | Feature | Closed   | Normal   | Knowledge base module added  | tin      |          |            |
| 536  | _dev.xdevs.com                  | Feature | Closed   | Normal   | Update engine to 2.1.x branch  | tin      |          |            |
| 335  | _dev.xdevs.com                  | Bug     | Closed   | Normal   | Need elevated rights for plugins and attached files, why?                  | tin      |          |            |
| 334  | _dev.xdevs.com                  | Bug     | Closed   | Normal   | Stylesheet fix and color updates, fix footer, validate important pages     | tin      |          |            |
| 298  | _dev.xdevs.com                  | Feature | Closed   | Normal   | Graphviz not working, Error 500  | tin      |          |            |
| 264  | _dev.xdevs.com                  | Support | Closed   | Normal   | Update Redmine engine to 1.4.4   | tin      |          |            |
| 244  | _dev.xdevs.com                  | Bug     | Closed   | Normal   | Fix Gantt view (stylesheet or plugin)                                      | tin      |          | 12/31/2011 |
| 243  | _dev.xdevs.com                  | Feature | Closed   | Normal   | GZIP and cache static  | tin      |          | 12/31/2011 |
| 241  | _dev.xdevs.com                  | Bug     | Rejected | Normal   | Issue view, top header background upgrade                                  | tin      |          | 12/31/2011 |
| 240  | _dev.xdevs.com                  | Feature | Closed   | Normal   | Mercurial style  | tin      |          | 12/26/2011 |
| 239  | _dev.xdevs.com                  | Support | Closed   | Normal   | Update security certificate for crypted access to https://dev.xdevs.com    | tin      |          | 12/25/2011 |
| 238  | _dev.xdevs.com                  | Bug     | Closed   | Normal   | Update repository server   | tin      |          | 12/25/2011 |
| 237  | _dev.xdevs.com                  | Feature | Closed   | Normal   | Integrate graphviz   | tin      |          | 12/25/2011 |
| 236  | _dev.xdevs.com                  | Feature | Closed   | Normal   | Upgrade redmine site to latest trunk version                               | tin      |          | 12/25/2011 |
| 1262 | content_mgmt                    | Feature | Closed   | Normal   | Publish 3456A  | tin      | Article  | 10/25/2015 |
| 1233 | content_mgmt                    | Feature | Closed   | Normal   | Перевод https://xdevs.com/article/ddr4s/                                   | tin      | Article  | 09/23/2015 |

| #    | Project              | Tracker | Status   | Priority | Subject   | Assignee | Category | Due date   |
|------|----------------------|---------|----------|----------|---|----------|----------|------------|
| 1229 | content_mgmt         | Feature | Closed   | Normal   | Article for DMM noise measurement analysis              | tin      | Article  | 08/06/2015 |
| 1226 | content_mgmt         | Feature | Closed   | Normal   | ALTERA MAX II DEVBOARD review                           | tin      | Article  |            |
| 1206 | content_mgmt         | Feature | Closed   | Normal   | Article-review Parallax SmartPack 672                   | tin      | Article  |            |
| 1205 | content_mgmt         | Feature | Closed   | Normal   | Статья-обзор паяльной станции Ersa I-CON                | tin      | Article  |            |
| 1204 | content_mgmt         | Support | Closed   | Normal   | Rohde & Schwarz Signal generator SMT03 Repair           | tin      | Repairs  |            |
| 1201 | content_mgmt         | Feature | Closed   | Normal   | Fluke 51-II thermometer                                 | tin      | Article  |            |
| 1200 | content_mgmt         | Feature | Closed   | Normal   | Unlocking JLink article                                 | tin      | Repairs  |            |
| 1198 | content_mgmt         | Feature | Closed   | Normal   | Обзор прецизионного мультиметра Keithley 2001-M         | tin      | Article  |            |
| 1163 | content_mgmt         | Feature | Failed   | Normal   | Статьи к публикации                                     | tin      |          | 05/31/2014 |
| 1157 | content_mgmt         | Feature | Closed   | Normal   | Articles for September 2014                             | tin      |          |            |
| 1130 | content_mgmt         | Feature | Closed   | Normal   | Статьи на июль 2014                                     |          |          |            |
| 1039 | content_mgmt         | Feature | Failed   | Normal   | Статьи на май 2014                                      | tin      |          | 05/31/2014 |
| 1038 | content_mgmt         | Feature | Closed   | Normal   | Статьи на апрель 2014                                   | tin      |          | 04/30/2014 |
| 1059 | HP 4263B             | Support | Closed   | Low      | Improve LCD to inverse 40x2?                            | tin      |          | 04/30/2014 |
| 1178 | Keithley 2000        | Feature | Closed   | Low      | Check components on K2000 unit                          | tin      |          |            |
| 908  | Keithley 2400 repair | Bug     | Closed   | Low      | Front panel replacement quote?                          | tin      |          |            |
| 893  | Keithley 7001        | Support | Rejected | Low      | Front board taken for Keithley 2001, get replacement?   | tin      |          |            |
| 882  | R&E                  | Support | Closed   | Low      | Requested Tektronix quotation for calibration with data | tin      |          |            |
| 1092 | Raspberry Pi         | Feature | Closed   | Low      | DDR3/DDR4 SPD read tool for RPi+DDR4s                   | tin      |          | 05/25/2014 |