

Issues

| # | Project | Tracker | Status | Priority | Subject | Assignee | Category | Due date |
|------|----------------------------------|-----------|----------|----------|---|------------|----------|------------|
| 293 | ALTERA 672 Checkout board repair | Feature | Closed | Normal | Power check - voltage in spec, power good - ok? | Izerg | | |
| 289 | ALTERA 672 Checkout board repair | Support | Closed | Normal | Receive board from EMS | | | 08/10/2012 |
| 292 | ALTERA 672 Checkout board repair | Support | Closed | High | Search documentation for "ALTERA 672 Checkout board" | tin | | 10/10/2012 |
| 291 | ALTERA 672 Checkout board repair | Bug | Closed | High | VCC SSO замкнут на землю? | Izerg | | |
| 119 | AM2 | Bug | Closed | Normal | R7,R8 - fix value to allow generator running | tin | | |
| 232 | ARM-camp | Feature | Rejected | Normal | Add Redmine guide and intro based on dev.xdevs.com project | tin | | 12/30/2011 |
| 229 | ARM-camp | Feature | Rejected | Normal | Add intro page about STM-Discovery to wiki, create first project | tin | | 01/15/2012 |
| 230 | ARM-camp | Feature | Closed | Normal | Add mercurial DVCS intro to wiki | ARandomOWI | | 12/14/2011 |
| 233 | ARM-camp | Feature | Rejected | Normal | Send development miniboard on AT91SAM7S128 to Adrian | tin | | 12/28/2011 |
| 739 | E-table 2 | Support | Closed | Normal | Create initial design concept | tin | | 04/26/2015 |
| 740 | E-table 2 | Feature | Closed | Normal | Onboard workspace PC system | tin | | |
| 1361 | Fluke 720A repair | Support | Closed | Normal | Inspection, photos and check | tin | | 08/09/2016 |
| 1289 | HP 3458A | Feature | Closed | Normal | 1ppm/hour drift on new ADC board | tin | | |
| 1235 | HP 3458A | Rework | Closed | Normal | Buy and install A9 reference board | tin | | |
| 1249 | HP 3458A | Feature | Closed | Normal | Digikey order 2 | tin | | |
| 1260 | HP 3458A | Feature | Closed | Normal | ERROR 114 -- balanced multislope convergence | tin | | |
| 1259 | HP 3458A | Bug | Closed | Normal | ERROR 114 -- multislope rundown convergence | tin | | |
| 1272 | HP 3458A | Feature | Closed | Normal | Install memory option 001 back | tin | | 11/30/2015 |
| 1242 | HP 3458A | Feature | Closed | Normal | Make 3D drawing for LTZ1000 plastic cap | tin | | 10/05/2015 |
| 1248 | HP 3458A | Rework | Closed | Normal | Make CPLD logic replacement for PAL address decoder 03458-88804 | tin | | |
| 1261 | HP 3458A | Feature | Closed | Normal | Make measurement on integrator and reference path on A3 A/D board | tin | | 10/16/2015 |
| 1237 | HP 3458A | Feature | Closed | Normal | Order replacement parts from Keysight | tin | | |
| 1234 | HP 3458A | Feature | Closed | Normal | Receive unit, initial inspection | tin | | 09/17/2015 |
| 1243 | HP 3458A | Feature | Closed | Normal | Replace capacitors on A6 board. | tin | | |
| 1236 | HP 3458A | Rework | Closed | Normal | Test mains power supply domain & transformer | tin | | |
| 907 | HP 4263B | Feature | Rejected | Normal | Add option updates for 001 and 002 | tin | | 01/12/2014 |
| 945 | HP 4263B | Feature | Closed | Normal | Hack to enable Option 001 and 002 | tin | | |
| 1059 | HP 4263B | Support | Closed | Low | Improve LCD to inverse 40x2? | tin | | 04/30/2014 |
| 861 | HP 4263B | Feature | Closed | Normal | Initial check and repair estimate | tin | | 01/11/2014 |
| 1065 | HP 4263B | Support | Closed | Normal | Modify LCR probe according to Agilent connection spec. | tin | | 04/20/2014 |
| 947 | HP 4263B | Feature | Closed | Normal | PCB daughter board schematics recovery | tin | | 03/02/2014 |
| 860 | HP 4263B | Feature | Closed | Normal | Pay for LCR meter | tin | | 12/14/2013 |
| 910 | HP 4263B | Feature | Closed | Normal | Replace damaged components | tin | | |
| 639 | HP/Agilent 33120A | Support | Closed | Normal | Add related documentation | tin | | 11/18/2012 |
| 638 | HP/Agilent 33120A | Feature | Closed | Normal | Inspect unit, diagnose and isolate problem | tin | | |
| 1266 | HP3245A | Feature | Closed | Normal | Receive unit, initial inspection and tests | tin | | |
| 927 | KX | Inventory | Closed | Normal | AD7490BRUZ | tin | | |
| 925 | KX | Inventory | Closed | Normal | LMV324I | tin | | |
| 939 | KX | Inventory | Closed | Normal | LT1116CS8 | tin | | |
| 938 | KX | Inventory | Closed | Normal | LT1223CS8 | tin | | |
| 940 | KX | Inventory | Closed | Normal | LTC1043CSWPBF SOW18 Building block SW-CAP DUAL | tin | | |
| 926 | KX | Inventory | Closed | Normal | LTC1050CS8 | tin | | |
| 1087 | KX | Inventory | Closed | Normal | LTC2057HS8 - 17pcs THD box | tin | | |
| 941 | KX | Inventory | Closed | Normal | LTZ1000ACH SUPER-ZENER VREF | tin | | |
| 1088 | KX | Inventory | Closed | Normal | MAX6610AUT temp sensor SOT23-6 THD box 10pcs | tin | | |
| 998 | KX | Support | Closed | Normal | Order PCBs for VREF A00 module | tin | | 03/27/2014 |
| 934 | KX | Inventory | Closed | Normal | PMBFJ111-215 JFET NCH 40V 20mA SOT23-3 | tin | | |
| 933 | KX | Inventory | Closed | Normal | PMBFJ620-115 NJFET DUAL 25V SOT363 | tin | | |
| 930 | KX | Inventory | Closed | Normal | TL7705ACDR | tin | | |
| 1066 | KX | Feature | Closed | Normal | VPG resistor for prototype build | tin | | 05/31/2014 |
| 1160 | Keithley 2000 | Support | Closed | Normal | Backup EEPROM with programm memory A02 | tin | | |
| 1158 | Keithley 2000 | Feature | Closed | Normal | Broken K2000 unit received, need repairs | tin | | |
| 1193 | Keithley 2000 | Feature | Closed | Normal | Buy parts for repair | tin | | 05/30/2015 |
| 1178 | Keithley 2000 | Feature | Closed | Low | Check components on K2000 unit | tin | | |
| 1159 | Keithley 2000 | Rework | Closed | Normal | Clean board and restore damaged traces from leaked electrolyte | tin | | 09/22/2014 |
| 874 | Keithley 2000 | Feature | Closed | Normal | Keithley 2000 schematics | tin | | 12/23/2013 |
| 840 | Keithley 2001 repair | Support | Closed | Normal | 3 ADC modules shipped, receive and test rest units | tin | | 11/09/2013 |
| 895 | Keithley 2001 repair | Feature | Closed | Normal | 304.x series self-test errors (Ohm) | Izerg | | 01/05/2014 |
| 535 | Keithley 2001 repair | Bug | Closed | Normal | AC voltage select unit fails | tin | | 10/21/2012 |
| 285 | Keithley 2001 repair | Rework | Closed | Normal | All functions and all ranges "Overflow" | tin | | 08/05/2012 |
| 868 | Keithley 2001 repair | Feature | Closed | Normal | Assembly meter for function checks. | tin | | 12/15/2013 |
| 273 | Keithley 2001 repair | Support | Closed | Normal | Buy components for repair | tin | | 07/30/2012 |
| 286 | Keithley 2001 repair | Feature | Closed | Normal | Calibrate unit (Tektronix calibration) | tin | | 01/19/2014 |
| 956 | Keithley 2001 repair | Feature | Closed | Normal | Calibration constants for K2001 units | tin | | 02/15/2014 |
| 819 | Keithley 2001 repair | Support | Closed | Normal | Схема платы передней панели | tin | | 10/08/2013 |
| 278 | Keithley 2001 repair | Feature | Closed | Normal | D2 - checks | | | |
| 281 | Keithley 2001 repair | Feature | Closed | Normal | Display board move to unit #4 | tin | | |
| 1188 | Keithley 2001 repair | Feature | Closed | Normal | Dump firmware B17 from 2001M | tin | | |
| 276 | Keithley 2001 repair | Bug | Closed | Normal | ERROR 404.1 - Absolute value (x1 gain); -full-scale DAC output | tin | | |

| # | Project | Tracker | Status | Priority | Subject | Assignee | Category | Due date |
|------|----------------------|---------|----------|----------|--|----------|----------|------------|
| 641 | Keithley 2001 repair | Feature | Closed | Normal | Finish AC input block schematics | tin | | 12/18/2012 |
| 297 | Keithley 2001 repair | Feature | Closed | Normal | Finish ADC board schematics. | tin | | 12/11/2012 |
| 658 | Keithley 2001 repair | Bug | Closed | Normal | Fix 401.1 - Signal switching; zero cal switch | tin | | 01/13/2013 |
| 652 | Keithley 2001 repair | Bug | Closed | Normal | Fix AC input mains curcuitry, replace electrolytic capacitors, replace transformer | tin | | 12/31/2012 |
| 342 | Keithley 2001 repair | Bug | Closed | Normal | Fix FE section on analog board | tin | | 09/09/2012 |
| 659 | Keithley 2001 repair | Bug | Rejected | Normal | Fix Test 412.1 – AC amps switch | tin | | 01/13/2013 |
| 854 | Keithley 2001 repair | Bug | Closed | Normal | Fix error 402.1 - Signal switching; frequency switch | tin | | 12/14/2013 |
| 855 | Keithley 2001 repair | Bug | Closed | Normal | Fix error 403.1 – Signal switching; ground switch | tin | | 12/21/2013 |
| 864 | Keithley 2001 repair | Bug | Closed | Normal | Fix error 406.6 – Voltage comparison | tin | | 12/22/2013 |
| 866 | Keithley 2001 repair | Bug | Closed | Normal | Fix error 409.6 – ±750 correction factor; signal comparisons | tin | | 12/22/2013 |
| 867 | Keithley 2001 repair | Bug | Closed | Normal | Fix error 410.1, 411.1, 411.2 - TRMS / TRMS Filter | tin | | 12/29/2013 |
| 856 | Keithley 2001 repair | Bug | Closed | Normal | Fix error 412.1 – AC amps switch | tin | | 12/28/2013 |
| 862 | Keithley 2001 repair | Bug | Closed | Normal | Fix errors 404.1, 404.2, 404.3, 404.4, 404.5 - Absolute value (x1 gain); | tin | | 12/22/2013 |
| 863 | Keithley 2001 repair | Bug | Closed | Normal | Fix errors 405.2, 405.4, 405.6, 405.8, - Absolute value x10 gain comparison | tin | | 12/22/2013 |
| 865 | Keithley 2001 repair | Bug | Closed | Normal | Fix errors 407.1, 407.2, 407.3 - Front end 2V/200V/750V | tin | | 12/22/2013 |
| 890 | Keithley 2001 repair | Support | Closed | Normal | Install DS1245Y for MEM2 option | tin | | 01/04/2014 |
| 282 | Keithley 2001 repair | Rework | Closed | Normal | Install display board | tin | | |
| 879 | Keithley 2001 repair | Bug | Closed | Normal | Issue list update | tin | | |
| 277 | Keithley 2001 repair | Bug | Closed | Normal | K2 - ERROR 405.2 – Absolute value x10 gain comparison; large +DAC output | tin | | |
| 275 | Keithley 2001 repair | Bug | Closed | Normal | K2 - Error 402.1 - Frequency switch | tin | | |
| 272 | Keithley 2001 repair | Support | Closed | Normal | K2 - repair status. | tin | | |
| 268 | Keithley 2001 repair | Bug | Closed | Normal | K2 : ERROR 105.2 - System trigger bus | tin | | 07/22/2012 |
| 271 | Keithley 2001 repair | Feature | Closed | Normal | K2 : ERROR 304 Section | tin | | |
| 269 | Keithley 2001 repair | Bug | Closed | Normal | K2 : ERROR 304.6 - Ohms sources; 70nA and 770nA | tin | | |
| 270 | Keithley 2001 repair | Bug | Closed | Normal | K2 : ERROR 304.7 - Ohms sources; 4.4nA and 770nA | tin | | |
| 274 | Keithley 2001 repair | Bug | Closed | Normal | K2 : ERROR 401.1 - Signal switching; zero cal switch | tin | | |
| 288 | Keithley 2001 repair | Bug | Closed | High | K4 - repair status. | tin | | 02/28/2015 |
| 885 | Keithley 2001 repair | Feature | Closed | Normal | Keithley 2001 thermal evaluation | tin | | 01/01/2014 |
| 852 | Keithley 2001 repair | Feature | Closed | Normal | LabView control panel development | tin | | 02/28/2014 |
| 283 | Keithley 2001 repair | Rework | Closed | Normal | No response from analog board | tin | | |
| 294 | Keithley 2001 repair | Feature | Closed | Normal | Read and decode firmwares for 2001 DMMs | tin | | 08/10/2012 |
| 1184 | Keithley 2001 repair | Bug | Closed | Normal | Repair status | tin | | |
| 1185 | Keithley 2001 repair | Bug | Closed | Normal | Repair status for very first 2001 unit | tin | | |
| 871 | Keithley 2001 repair | Bug | Closed | Normal | Replace C108 capacitor | tin | | 12/31/2013 |
| 889 | Keithley 2001 repair | Bug | Closed | Normal | Replace fan | tin | | 01/05/2014 |
| 637 | Keithley 2001 repair | Support | Closed | Normal | Review 2001's inventory | tin | | 02/16/2014 |
| 279 | Keithley 2001 repair | Feature | Closed | Normal | Schematics RE - analog board | tin | | 07/31/2012 |
| 818 | Keithley 2001 repair | Support | Closed | Normal | Schematics for analog board (Keithley 2001-102-04L) | lzerg | | 07/21/2014 |
| 820 | Keithley 2001 repair | Support | Closed | Normal | Schematics for digital board (Keithley 2001-142-06H) | tin | | 10/31/2013 |
| 1131 | Keithley 2001 repair | Support | Closed | Normal | Schematics for voltage reference LM399 | tin | | 07/11/2014 |
| 816 | Keithley 2001 repair | Support | Closed | Normal | Schematics recovery for analog board Keithley 2001 | tin | | 07/21/2014 |
| 891 | Keithley 2001 repair | Feature | Closed | Normal | Self-test errors diagnosis | tin | | 01/05/2014 |
| 888 | Keithley 2001 repair | Feature | Closed | Normal | Send 2001 DMM for calibration to Tektronix Taiwan | tin | | 01/12/2014 |
| 343 | Keithley 2001 repair | Bug | Closed | Normal | Send K2001 #5 to lzerg | lzerg | | 10/31/2012 |
| 869 | Keithley 2001 repair | Feature | Closed | Normal | Spec test | tin | | 12/15/2013 |
| 284 | Keithley 2001 repair | Rework | Closed | Normal | Test digital board. | tin | | |
| 884 | Keithley 2001 repair | Feature | Closed | Normal | UART protocol between front panel board and digital board. | tin | | |
| 858 | Keithley 2001 repair | Bug | Closed | Normal | VFD Power supply issues? | tin | | |
| 642 | Keithley 2001 repair | Feature | Closed | Normal | Voltage reference block schematics recovery | tin | | 12/17/2012 |
| 894 | Keithley 2001 repair | Support | Closed | Normal | lzerg Keithley serial number request | lzerg | | 01/05/2014 |
| 1141 | Keithley 2001 repair | Feature | Closed | Normal | Восстановление источника тока и диапазонов измерения сопротивления | tin | | |
| 859 | Keithley 2001 repair | Feature | Closed | Normal | Схема аналоговой платы (Keithley 2001-102-04J) | tin | | 07/11/2014 |
| 817 | Keithley 2001 repair | Support | Closed | Normal | Схема платы A/D (Keithley 2001-162-01G) | tin | | 10/03/2013 |
| 958 | Keithley 2002 | Feature | Closed | Normal | Initial inspection for K2002 (331119346214) | tin | | 02/10/2014 |
| 1142 | Keithley 2002 | Feature | Closed | Normal | Measure LT1013+LTZ1000A VREF voltages | tin | | 07/21/2014 |
| 973 | Keithley 2002 | Feature | Rejected | Normal | Request correct repair manual for 2002 | tin | | 02/28/2014 |
| 287 | Keithley 2400 repair | Feature | Rejected | Normal | Calibrate outputs | tin | | 08/11/2012 |
| 887 | Keithley 2400 repair | Bug | Closed | Normal | Fix front panel keypad | tin | | 01/01/2014 |
| 908 | Keithley 2400 repair | Bug | Closed | Low | Front panel replacement quote? | tin | | |
| 886 | Keithley 2400 repair | Support | Closed | Normal | Send 2400 SMU for calibration to Tektronix Taiwan | tin | | 01/31/2014 |
| 1170 | Keithley 2510 | Feature | Closed | Normal | Calibrate unit | tin | | 12/06/2014 |
| 1168 | Keithley 2510 | Feature | Closed | Normal | Get and flash correct firmware for 2510 into AT49F040 (U168) | tin | | |
| 1167 | Keithley 2510 | Feature | Closed | Normal | Publish repair article about 2510 TEC SMU | tin | | 12/07/2014 |
| 1166 | Keithley 2510 | Feature | Closed | Normal | Receive 2510 unit for repair | tin | | |
| 893 | Keithley 7001 | Support | Rejected | Low | Front board taken for Keithley 2001, get replacement? | tin | | |
| 766 | Nikkor lens repair | Bug | Closed | Normal | Buy replacement parts for 17-35 | tin | | 05/31/2013 |
| 767 | Nikkor lens repair | Rework | Closed | Normal | Replace connection aperture ring | tin | | |
| 1080 | Nikon DSLR | Feature | Closed | Normal | Adjust EH-4 AC brick for 13VDC output for D3 | tin | | |
| 1070 | Nikon DSLR | Feature | Closed | Normal | Initial inspection | tin | | 05/02/2014 |
| 1089 | Nikon DSLR | Feature | Closed | High | Repair D3 | tin | | 05/11/2014 |
| 1112 | Nikon DSLR | Feature | Closed | Normal | Schematics for fake EN-EL4a battery | tin | | |

| # | Project | Tracker | Status | Priority | Subject | Assignee | Category | Due date |
|------|---------------------------------|---------|----------|-----------|--|----------|----------|------------|
| 4 | PWMC | Bug | Closed | Normal | Firmware and hardware check | tin | | |
| 905 | R&E | Support | Closed | Normal | Buy parts for K2001 project repairs | tin | | 01/05/2014 |
| 881 | R&E | Support | Closed | Normal | EDC MV106 DC Voltage standard backlog | tin | | 12/31/2013 |
| 955 | R&E | Feature | Closed | Normal | EDC MV106 calibration | tin | | |
| 1123 | R&E | Support | Closed | Normal | Fluke 52 II thermometer calibration - 89020093 | tin | | 06/10/2014 |
| 1299 | R&E | Feature | Closed | Normal | Help sonicyang to repair HP 34401A | tin | | 01/16/2016 |
| 85 | R&E | Feature | Closed | Normal | Make PCI-E videocard test power assemble kit | tin | | 11/28/2010 |
| 882 | R&E | Support | Closed | Low | Requested Tektronix quotation for calibration with data | tin | | |
| 296 | R&E | Feature | Closed | Normal | iZerg support package | lzerg | | 10/03/2012 |
| 1074 | Raspberry Pi | Feature | Closed | Normal | 3D model of DIMM adapter assembly | tin | | |
| 1106 | Raspberry Pi | Feature | Closed | Normal | Add checksum checks/validation function | tin | | 05/19/2014 |
| 1071 | Raspberry Pi | Feature | Closed | Normal | Buy Raspberry Pi module | tin | | 04/27/2014 |
| 1092 | Raspberry Pi | Feature | Closed | Low | DDR3/DDR4 SPD read tool for RPI+DDR4s | tin | | 05/25/2014 |
| 1073 | Raspberry Pi | Feature | Closed | Normal | Initial firmware to read/write SPD EEPROM (EC) | tin | | 05/21/2014 |
| 1090 | Raspberry Pi | Feature | Closed | Normal | Install I2C support for RPI | tin | | |
| 1072 | Raspberry Pi | Feature | Closed | Normal | Make DDR slot adapter for SPD read/write | tin | | 05/09/2014 |
| 1108 | Raspberry Pi | Support | Closed | Normal | Update article to version 1.0 | tin | | 05/20/2014 |
| 773 | Tektronix TDS/CSA7000 (CSA7404) | Rework | Closed | Normal | Buy BR1632 3V battery for NVRAM DALLAS replacement with leads | tin | | |
| 857 | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed | Normal | Buy Tek P6205 probe for general voltage measurements (40V pk-pk) | tin | | 01/31/2014 |
| 795 | Tektronix TDS/CSA7000 (CSA7404) | Bug | Closed | Normal | Channel 1 out of cal? | tin | | |
| 794 | Tektronix TDS/CSA7000 (CSA7404) | Bug | Closed | Normal | Channel 2 and 3 not powering Tektronix P7380 probe, not working? | tin | | |
| 760 | Tektronix TDS/CSA7000 (CSA7404) | Rework | Closed | Normal | Download and write CD-R with Win98/2000 | tin | | 05/22/2013 |
| 772 | Tektronix TDS/CSA7000 (CSA7404) | Rework | Closed | Normal | Install Windows 2000 SP4 Pro for test | tin | | |
| 771 | Tektronix TDS/CSA7000 (CSA7404) | Rework | Rejected | Normal | Install Windows 98 on another HDD for test. | tin | | |
| 768 | Tektronix TDS/CSA7000 (CSA7404) | Feature | Closed | Normal | Install all system Tektronix drivers for devices on Win2000 | tin | | 06/30/2013 |
| 754 | Tektronix TDS/CSA7000 (CSA7404) | Rework | Closed | Normal | Outer covers replacement parts needed | tin | | 12/31/2013 |
| 774 | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed | Normal | Pay for pair of Tektronix P7380 TekConnect differential 8GHz probes | tin | | 06/04/2013 |
| 752 | Tektronix TDS/CSA7000 (CSA7404) | Feature | Closed | Normal | Pay for scope unit for parts | tin | | 05/20/2013 |
| 753 | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed | Normal | Receive scope, initial inspection | tin | | 05/31/2013 |
| 761 | Tektronix TDS/CSA7000 (CSA7404) | Rework | Closed | Normal | Replace CD-ROM with DVD-RW drive | tin | | 05/23/2013 |
| 759 | Tektronix TDS/CSA7000 (CSA7404) | Rework | Closed | Normal | Replace HDD, try fresh install windows and Tek software | tin | | 05/23/2013 |
| 807 | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed | High | Tek CSA7404 scope repair article worklog | tin | | 01/04/2014 |
| 880 | Tektronix TDS/CSA7000 (CSA7404) | Bug | Closed | Normal | Trigger encoder shaft damaged - replace encoder Bourns EPS1E-F19 S53 | tin | | |
| 769 | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed | Normal | Try to run TDS7704B w/o connection between PPC and AQ boards? | tin | | 06/02/2013 |
| 796 | Tektronix TDS/CSA7000 (CSA7404) | Support | Closed | Normal | Upgrade CPU to Pentium III, add extra memory for NLX board, install DVD-RW | tin | | |
| 299 | Tektronix TLA714 | Feature | Closed | Normal | Add actual internal pics, add documentation | tin | | 08/25/2012 |
| 808 | Tektronix TLA714 | Feature | Closed | Normal | Backup NVRAM on TLA7AA4 | tin | | 09/20/2013 |
| 805 | Tektronix TLA714 | Bug | Closed | Normal | Battery for CMOS died on PC board, date got reset | tin | | 09/15/2013 |
| 693 | Tektronix TLA714 | Feature | Closed | Normal | Firmware binary for TLA7AA4 5.5.003 | tin | | |
| 692 | Tektronix TLA714 | Feature | Closed | Normal | Firmware binary for TLA7AA4 5.8.001 | tin | | |
| 267 | Tektronix TLA714 | Feature | Closed | Normal | TEKTRONIX 020-2457-00 COMPRESSION PCB -to- MICTOR ADAPTER | tin | | 07/10/2012 |
| 815 | Tektronix TLA714 | Feature | Closed | Normal | Unlock more memory for TLA7AA4 | tin | | |
| 266 | Tektronix TLA714 | Feature | Closed | Normal | [eBay] New in the box Tektronix Tek P6860 Probe Set A2-A3/D2-D3 | tin | | 07/16/2012 |
| 872 | Tektronix TLA714 | Feature | Closed | Normal | Бюджет проекта | tin | | |
| 154 | WARP | Bug | Failed | Normal | VNOM- not connected to ground | tin | | |
| 1336 | X-CAL | Feature | Closed | Normal | Software specification | | | |
| 898 | _dev.xdevs.com | Feature | Closed | Normal | Added issuefy importer | tin | | 01/05/2014 |
| 333 | _dev.xdevs.com | Bug | Rejected | High | Caching working not right, need refresh page manually | tin | | |
| 1126 | _dev.xdevs.com | Bug | Closed | Normal | Deployment issue with redmine engine | tin | | |
| 263 | _dev.xdevs.com | Feature | Closed | Urgent | Devsite crashes after few days | tin | | 10/14/2012 |
| 244 | _dev.xdevs.com | Bug | Closed | Normal | Fix Gantt view (stylesheet or plugin) | tin | | 12/31/2011 |
| 243 | _dev.xdevs.com | Feature | Closed | Normal | GZIP and cache static | tin | | 12/31/2011 |
| 298 | _dev.xdevs.com | Feature | Closed | Normal | Graphviz not working, Error 500 | tin | | |
| 878 | _dev.xdevs.com | Feature | Closed | Normal | Improve and bug fix for theme / stylesheets. | tin | | 12/29/2013 |
| 237 | _dev.xdevs.com | Feature | Closed | Normal | Integrate graphviz | tin | | 12/25/2011 |
| 241 | _dev.xdevs.com | Bug | Rejected | Normal | Issue view, top header background upgrade | tin | | 12/31/2011 |
| 654 | _dev.xdevs.com | Feature | Closed | Normal | Knowledge base module added | tin | | |
| 240 | _dev.xdevs.com | Feature | Closed | Normal | Mercurial style | tin | | 12/26/2011 |
| 876 | _dev.xdevs.com | Feature | Rejected | Normal | Merge with documentation site | tin | | |
| 338 | _dev.xdevs.com | Feature | Closed | High | Monospace font for <pre> and repository source view | tin | | 12/30/2012 |
| 335 | _dev.xdevs.com | Bug | Closed | Normal | Need elevated rights for plugins and attached files, why? | tin | | |
| 770 | _dev.xdevs.com | Bug | Closed | Normal | Notification emails are lost/not full | tin | | 06/03/2013 |
| 670 | _dev.xdevs.com | Bug | Closed | Normal | Redirects to dummy redmine host when modify items using HTTPS | tin | | |
| 1113 | _dev.xdevs.com | Bug | Closed | Immediate | Repository system security update | tin | | 05/22/2014 |
| 334 | _dev.xdevs.com | Bug | Closed | Normal | Stylesheet fix and color updates, fix footer, validate important pages | tin | | |
| 264 | _dev.xdevs.com | Support | Closed | Normal | Update Redmine engine to 1.4.4 | tin | | |
| 536 | _dev.xdevs.com | Feature | Closed | Normal | Update engine to 2.1.x branch | tin | | |
| 873 | _dev.xdevs.com | Feature | Closed | Immediate | Update engine to 2.4.1 | tin | | 12/23/2013 |
| 999 | _dev.xdevs.com | Support | Closed | Normal | Update redmine to 2.5.0 | tin | | 03/15/2014 |
| 1216 | _dev.xdevs.com | Support | Closed | High | Update redmine to latest 3.0.x trunk | tin | | 07/20/2015 |
| 238 | _dev.xdevs.com | Bug | Closed | Normal | Update repository server | tin | | 12/25/2011 |

| # | Project | Tracker | Status | Priority | Subject | Assignee | Category | Due date |
|------|----------------|---------|--------|----------|--|----------|----------|------------|
| 239 | _dev.xdevs.com | Support | Closed | Normal | Update security certificate for crypted access to https://dev.xdevs.com | tin | | 12/25/2011 |
| 236 | _dev.xdevs.com | Feature | Closed | Normal | Upgrade redmine site to latest trunk version | tin | | 12/25/2011 |
| 242 | _dev.xdevs.com | Bug | Closed | High | Users cannot login with current password, must use "lost password feature" due to security enhancement | tin | | 12/30/2011 |
| 1226 | content_mgmt | Feature | Closed | Normal | ALTERA MAX II DEVBOARD review | tin | Article | |
| 1229 | content_mgmt | Feature | Closed | Normal | Article for DMM noise measurement analysis | tin | Article | 08/06/2015 |
| 1206 | content_mgmt | Feature | Closed | Normal | Article-review Parallax SmartPack 672 | tin | Article | |
| 1157 | content_mgmt | Feature | Closed | Normal | Articles for September 2014 | tin | | |
| 1201 | content_mgmt | Feature | Closed | Normal | Fluke 51-II thermometer | tin | Article | |
| 1227 | content_mgmt | Feature | Closed | High | NI HS-GPIB-USB review | tin | Article | 08/16/2015 |
| 1262 | content_mgmt | Feature | Closed | Normal | Publish 3456A | tin | Article | 10/25/2015 |
| 1204 | content_mgmt | Support | Closed | Normal | Rohde & Schwarz Signal generator SMT03 Repair | tin | Repairs | |
| 1200 | content_mgmt | Feature | Closed | Normal | Unlocking JLink article | tin | Repairs | |
| 1198 | content_mgmt | Feature | Closed | Normal | Обзор прецизионного мультиметра Keithley 2001-M | tin | Article | |
| 1233 | content_mgmt | Feature | Closed | Normal | Перевод https://xdevs.com/article/ddr4s/ | tin | Article | 09/23/2015 |
| 1163 | content_mgmt | Feature | Failed | Normal | Статьи к публикации | tin | | 05/31/2014 |
| 1038 | content_mgmt | Feature | Closed | Normal | Статьи на апрель 2014 | tin | | 04/30/2014 |
| 1130 | content_mgmt | Feature | Closed | Normal | Статьи на июль 2014 | | | |
| 1039 | content_mgmt | Feature | Failed | Normal | Статьи на май 2014 | tin | | 05/31/2014 |
| 1205 | content_mgmt | Feature | Closed | Normal | Статья-обзор паяльной станции Ersa I-CON | tin | Article | |