

HP 3458A - Feature #1289

1ppm/hour drift on new ADC board

11/19/2015 06:47 PM - tin

| | |
|-------------------------|----------------------------------|
| Status: Closed | Start date: 11/19/2015 |
| Priority: Normal | Due date: |
| Assignee: tin | % Done: 0% |
| Category: | Estimated time: 0.00 hour |
| Target version: | |

Description
Was soldered parts:
U180 ASIC
CR401
R405
R406
U142

Replacement of integrating cap C119 did not change anything.

History

#1 - 12/27/2015 11:55 AM - tin

L TZ1000CH zener reading after ACAL 12/27 : 7.19119791

#2 - 12/29/2015 12:42 AM - tin

7.19118678VDC

#3 - 01/18/2016 01:49 PM - tin

- Status changed from New to Closed