

**Keithley 2001 repair - Bug #879**

**Issue list update**

12/27/2013 12:25 AM - tin

<b>Status:</b> Closed	<b>Start date:</b> 12/27/2013
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b> tin	<b>% Done:</b> 100%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b> Keithley 2001 #1	

**Description**  
Self-diag test result:  
309.1 - Amps  
401.1 Zero Cal Sw  
402.1  
403.1  
405.2 - sometimes pass after warmup  
405.4 - sometimes pass after warmup  
405.6  
405.8 - sometimes pass after warmup  
407.1 - sometimes pass after warmup  
407.2 - sometimes pass after warmup  
407.3 - sometimes pass after warmup  
410.1 - sometimes pass after warmup  
411.1 - sometimes pass after warmup  
411.2 - sometimes pass after warmup

---

**History**

#1 - 06/07/2016 01:22 AM - tin  
- Status changed from New to Closed  
- % Done changed from 0 to 100