

**Keithley 2001 repair - Feature #888**

**Send 2001 DMM for calibration to Tektronix Taiwan**

12/31/2013 12:23 AM - tin

<b>Status:</b> Closed	<b>Start date:</b> 01/05/2014
<b>Priority:</b> Normal	<b>Due date:</b> 01/12/2014
<b>Assignee:</b> tin	<b>% Done:</b> 100%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b> Keithley 2001 #7	
<b>Description</b> SN 0544257	

**Associated revisions**

**Revision 149:2d120709098c - 02/06/2014 10:07 AM - tin**

0544257 calibration done by Tek, ID close #888 close

**Revision 149:2d120709098c - 02/06/2014 10:07 AM - Ilya Tsemenko**

0544257 calibration done by Tek, ID close #888 close

**History**

**#1 - 12/31/2013 07:06 PM - tin**

- Status changed from *New* to *In Progress*

Calibration quotation 15590NTD + 5% tax

**#2 - 01/06/2014 03:53 AM - tin**

Unit ready for calibration service.

Current calibration was done in 1992, unit likely was never calibrated.

**#3 - 01/13/2014 08:30 PM - tin**

- Status changed from *In Progress* to *Resolved*

- % Done changed from 0 to 50

Unit sent

**#4 - 02/06/2014 10:11 AM - Anonymous**

- Status changed from *Resolved* to *Closed*

- % Done changed from 50 to 100

Applied in changeset [2d120709098c](#).

**#5 - 07/13/2014 01:33 AM - tin**

- Target version changed from *Keithley 2001 #5* to *Keithley 2001 #7*