

Keithley 2001 repair - Feature #895

Feature # 891 (Closed): Self-test errors diagnosis

304.x series self-test errors (Ohm)

03/01/2014 03:12 - tin

Status:	Closed	Start date:	03/01/2014
Priority:	Normal	Due date:	05/01/2014
Assignee:	Izerg	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:	Keithley 2001 #5		
Description			
+8VF and -8VF have incorrect signal			

History

#1 - 03/01/2014 03:32 - tin

- File *Keithley_2001J_03_FLOAT PSU.pdf* added

#2 - 04/01/2014 03:11 - tin

- File *top_rev_04_JAN_14.jpg* added

- Assignee changed from tin to Izerg

По схеме [на данный момент](#)

Проверить [участок](#)

#3 - 13/07/2014 02:08 - tin

- Target version changed from Keithley 2001 #4 to Keithley 2001 #5

#4 - 25/12/2014 08:31 - Izerg

- Status changed from In Progress to Suspended

#5 - 03/07/2015 04:42 - tin

- Status changed from Suspended to Closed

Files

compar-refok001.png	6.88 KB	03/01/2014	tin
compar-refok002.png	6.7 KB	03/01/2014	tin
compar-refok003.png	6.75 KB	03/01/2014	tin
compar-refok004.png	6.74 KB	03/01/2014	tin
Keithley_2001J_03_FLOAT PSU.pdf	123 KB	03/01/2014	tin
top_rev_04_JAN_14.jpg	6.36 MB	04/01/2014	tin