

HP 4263B - Feature #910

Replace damaged components

01/08/2014 04:43 AM - tin

Status: Closed	Start date: 01/08/2014
Priority: Normal	Due date:
Assignee: tin	% Done: 100%
Category:	Estimated time: 0.00 hour
Target version:	
Description	
4 x 1/2W resistors (need value for them)	
Broken in half tranzorb Z6010 - http://www.digikey.com/product-detail/en/1.5KE10C-E3%2F73/1.5KE10C-E3%2F73-ND/2140145 http://www.digikey.com/product-detail/en/1.5KE10-E3%2F73/1.5KE10-E3%2F73-ND/2140134 (unidirectional) http://www.digikey.com/product-detail/en/1N6374-E3%2F73/1N6374-E3%2F73GICT-ND/3847528 http://www.digikey.com/product-detail/en/ICTE8C-E3%2F54/ICTE8C-E3%2F54GICT-ND/3711909	
Burnt 1206 on main pcb (100 ohm?) 1%	
And on secondary module with pair of PNP/NPN, Bulged SOT23 with code Y23	

History

#1 - 04/17/2014 01:43 AM - tin

- Category set to 97
- Status changed from New to Resolved
- Assignee set to tin
- % Done changed from 0 to 100

All functions working well, components replaced.

#2 - 07/09/2014 12:11 AM - tin

- Status changed from Resolved to Closed