

Issues

| # | Project | Tracker | Status | Priority | Subject | Assignee | Category | Due date |
|------|---------------------------------|-----------|-------------|----------|--|----------|----------|------------|
| 1314 | Keithley 2002 | Rework | Resolved | Normal | Repair unit 2 | tin | | 03/25/2016 |
| 1302 | R&E | Feature | New | Normal | Wolf resistors | tin | | |
| 1296 | Keithley 2002 | Feature | Resolved | Normal | Test with different mains | tin | | |
| 1288 | content_mgmt | Feature | Feedback | Normal | TI ADS1262 EVM article series review | tin | Article | 01/18/2016 |
| 1285 | HP 3458A | Feature | In Progress | Normal | Measure stability per SN 18 | tin | | 11/26/2015 |
| 1283 | HP 3245A | Feature | New | Normal | Recalibrate unit after update to LTZ | tin | | |
| 1282 | HP 3245A | Feature | New | Normal | Test calibration, save calibration RAM | tin | | |
| 1281 | HP 3245A | Rework | New | Normal | Replace LM399 to LTZ1000 | tin | | |
| 1280 | KX-A | Feature | New | Normal | 2A current amp | tin | | |
| 1279 | HP 3458A | Feature | New | Normal | Usage items | tin | | |
| 1271 | HP 3458A | Feature | New | Normal | Install optics on external trigger on A6 PCBA | tin | | |
| 1270 | HP 3245A | Feature | New | Normal | Replace capacitors, take more photos of internal parts for article | tin | | 11/25/2015 |
| 1265 | HP 3245A | Feature | Resolved | Normal | Receive unit, initial inspection | tin | | 11/03/2015 |
| 1264 | content_mgmt | Feature | New | Normal | Style improvements for articles | tin | Article | |
| 1258 | HP 3458A | Feature | New | Normal | Adapter board for LMH6321 buffer | tin | | |
| 1257 | HP 3458A | Feature | In Progress | Normal | Adapter boards for Intersil comparators and EL22xxCM | tin | | |
| 1224 | content_mgmt | Feature | In Progress | Normal | Translate articles to both languages | tin | Article | 08/24/2015 |
| 1217 | _dev.xdevs.com | Support | Planning | Normal | Update header and footer on redmine to match django site. | tin | | 07/26/2015 |
| 1203 | content_mgmt | Feature | In Progress | Normal | Taking proper photographs of electronic hardware and PCBAs | tin | Article | |
| 1202 | content_mgmt | Feature | Resolved | Normal | HP 11177B - Calibration module from HP 3455A | tin | Article | |
| 1199 | content_mgmt | Feature | Planning | Normal | Second life for dead VGA cards - using as high-power power supply | tin | Article | |
| 1196 | Keithley 2001 repair | Feature | New | Normal | Analog interface protocol | tin | | |
| 1191 | KX-DAC | Feature | In Progress | Normal | Schematics design | tin | | 05/03/2015 |
| 1177 | REF-R | Feature | In Progress | Normal | 2 x VREFs sale | tin | | 02/23/2015 |
| 1175 | Tektronix TLA714 | Support | In Progress | Normal | Декодирование данных I2C с помощью TLA714 | tin | | 01/31/2015 |
| 1169 | Keithley 2510 | Feature | Suspended | Normal | X-K2510RH - resistor heater adapter design | tin | | |
| 1165 | KX-H : Low-noise amp | Feature | New | Normal | PCB layout for amp module KX-H | tin | | 11/09/2014 |
| 1164 | KX-H : Low-noise amp | Feature | In Progress | Normal | Schematics release for modular prototype | tin | | 10/31/2014 |
| 1155 | Tektronix TDS/CSA7000 (CSA7404) | Feature | In Progress | Normal | DSA71604 option | tin | | 09/05/2014 |
| 1132 | KX-H : Low-noise amp | Feature | New | Low | Collect existing solutions and applications. | tin | | |
| 1128 | REF-R | Feature | New | Normal | Order PCBs for VREF B01 module , VREF RATIO, Shorting plug | tin | | 06/28/2014 |
| 1117 | R&E | Feature | New | Normal | Article about measuring low capacitance with DMM | tin | | 05/25/2014 |
| 1111 | Raspberry Pi | Feature | New | Low | XMP parser / information tool | tin | | 05/25/2014 |
| 1107 | Raspberry Pi | Feature | New | Low | Add multiple module support on single RPI bus | tin | | 05/24/2014 |
| 1104 | TC-M | Feature | New | Normal | Bought components supply | tin | | |
| 1103 | Tektronix TDS/CSA7000 (CSA7404) | Feature | Resolved | Normal | Dead again, software hangs during bootup - fixed with new DS1245YP | tin | | |
| 1086 | KX | Inventory | New | Normal | Film SMD capacitor LDEC3100JA0N00 0.1uF 50VDC 1210 | tin | | |
| 1079 | Nikon DSLR | Feature | New | Normal | DB00 external power hack / ID workaround | tin | | |
| 1078 | KX | Feature | In Progress | Normal | PCB for low-thermal shorting plug | tin | | 06/29/2014 |
| 1077 | _dev.xdevs.com | Feature | Resolved | High | Page style issues for dev.xdevs.com | tin | | 04/27/2014 |
| 1075 | R&E | Feature | In Progress | Normal | Cadence tutorial feedback & review | tin | | |
| 1068 | KX | Feature | In Progress | Normal | Wire-wound precision resistors samples | tin | | |
| 1067 | KX | Support | New | Normal | References / 3rd-party resources | tin | | |
| 1063 | _dev.xdevs.com | Feature | Planning | Normal | Project index | tin | | 11/30/2015 |
| 1024 | REF-R | Support | In Progress | Normal | Module tracklog | tin | | |
| 1022 | REF-R | Bug | In Progress | Normal | VREF Board A01 errata | tin | | 04/05/2014 |
| 1018 | REF-R | Support | In Progress | Normal | Community feedback / units allocation | tin | | |
| 1014 | KX | Support | In Progress | Low | Components supply for project | tin | | |
| 1013 | R&E | Support | New | Normal | Заказать плату | tin | | |
| 1012 | R&E | Support | Resolved | Normal | Заказать компоненты | tin | | |
| 1011 | R&E | Support | In Progress | Normal | Добавить модели для Solidworks | tin | | |
| 1010 | R&E | Support | Resolved | Normal | Aquired ERSA I-CON1 soldering station | tin | | 03/20/2014 |
| 1007 | _dev.xdevs.com | Bug | Planning | Normal | Contacts plugin cause Internal error | tin | | |
| 1002 | _dev.xdevs.com | Feature | In Progress | Normal | Port articles to django site | tin | | 03/16/2014 |
| 993 | R&E | Support | In Progress | Normal | Cadence tutorial for Orcad (Component management) | tin | | |
| 981 | Tektronix TLA714 | Feature | Resolved | Normal | SPI Decode support library | tin | | 03/22/2014 |
| 980 | Tektronix TLA714 | Feature | In Progress | Normal | I2C decode support library | tin | | 03/15/2014 |
| 979 | Tektronix TLA714 | Feature | In Progress | Normal | Report issue regarding TLA Application under Winx64 | tin | | 03/10/2014 |
| 972 | Keithley 2002 | Feature | In Progress | Normal | Thermal photos for K2002 | tin | | 02/23/2014 |
| 971 | KX | Feature | New | Normal | Open-hardware transition | tin | | 02/23/2014 |
| 970 | REF-R | Feature | New | Normal | Battery power option for references | tin | | |
| 969 | Tektronix TDS/CSA7000 (CSA7404) | Bug | New | Low | Check write-protection switch mode | tin | | |
| 966 | Keithley 2002 | Support | Resolved | Normal | Схема платы A/D (Keithley 2002-xxx-01x) | tin | | 03/01/2014 |
| 965 | Keithley 2002 | Support | New | Normal | Восстановить схему для ремонта и отладки Keithley 2002 | tin | | 06/30/2014 |
| 964 | Keithley 2002 | Support | New | Normal | SCH Схема аналоговой платы (Keithley 2002-xxx-04x) | tin | | 06/30/2014 |
| 963 | Keithley 2002 | Feature | New | Normal | Calibration constants for K2002 | tin | | 02/23/2014 |
| 959 | Tektronix TDS/CSA7000 (CSA7404) | Feature | Resolved | Normal | TCA-1MEG review | tin | | 02/16/2014 |
| 954 | R&E | Feature | In Progress | Normal | Resistors test | tin | | 02/28/2014 |
| 952 | KX | Feature | New | Normal | Define spec for project | tin | | 02/01/2014 |

| # | Project | Tracker | Status | Priority | Subject | Assignee | Category | Due date |
|-----|---------------------------------|-----------|-------------|----------|--|----------|---------------|------------|
| 950 | KX | Inventory | Resolved | Normal | GU256X64-355 display | tin | | |
| 949 | KX | Feature | In Progress | Normal | Front panel design | tin | | 02/09/2014 |
| 948 | HP 4263B | Feature | New | Normal | Inputs protection curcuitry | tin | | 01/22/2014 |
| 946 | HP 4263B | Feature | In Progress | Normal | Recover inputs schematics and power modules schematics | tin | | 03/02/2014 |
| 937 | KX | Inventory | In Progress | Normal | LT1097S8 | tin | | |
| 906 | HP 4263B | Feature | In Progress | Normal | Review and teardown article | tin | | 01/18/2014 |
| 903 | content_mgmt | Support | Planning | Normal | Write tutorial about using redmine for projects | tin | Documentation | 01/31/2014 |
| 901 | Keithley 2002 | Support | In Progress | Normal | Collect photos of 2002 internals | tin | | |
| 900 | content_mgmt | Feature | New | Low | Add interactive plugin for common electronics calculations | tin | | 05/31/2014 |
| 899 | _dev.xdevs.com | Support | In Progress | Normal | Отзывы и замечания по новому UI redmine? | tin | | |
| 892 | Tektronix TDS/CSA7000 (CSA7404) | Feature | New | Normal | Clean and repair P6205 probe | tin | | |
| 883 | KX | Support | In Progress | Normal | Keithley 2001 ADC model, Multisim 12 project | tin | | 01/31/2014 |
| 877 | _dev.xdevs.com | Feature | Planning | Normal | Implement documetation portal | tin | | |
| 853 | Keithley 2001 repair | Support | Feedback | Normal | Бюджет проекта | tin | | |
| 822 | _dev.xdevs.com | Feature | New | Normal | Don't send suspended issues by email notifications | tin | | |
| 781 | Nikkor lens repair | Bug | New | Normal | SWM AF mechanism have issues when focusing | tin | | |
| 747 | Tektronix TLA714 | Feature | New | Normal | Mictor-2.54mm adapter board - LA-TP Board REV 01 www.sar-systems.com | tin | | 04/09/2013 |
| 671 | _dev.xdevs.com | Feature | Planning | Normal | Add RhodeCode to dev.xdevs.com | tin | | |
| 655 | _dev.xdevs.com | Feature | New | Normal | Separate theme/style to separate dedicated xdevs-blue theme module | tin | | 01/02/2013 |
| 337 | _dev.xdevs.com | Feature | Planning | Normal | Reformat issue view for easier usage. Slim design | tin | | |
| 336 | _dev.xdevs.com | Feature | New | Normal | autoupdate SCM in redmine for autotrack issues | tin | | |
| 295 | ALTERA SMB2 Repair | Rework | In Progress | Normal | Debug JTAG Stratix communication issue | tin | | |
| 234 | content_mgmt | Support | In Progress | Normal | Prepare and release xDevs.com coding standard | tin | Documentation | 01/11/2012 |
| 122 | content_mgmt | Feature | In Progress | Normal | Make article-review about voltage references. | tin | | |