Issues								
#	Project	Tracker	Status	Priority	Subject	Assignee	Category	Due date
85	R&E	Feature	Closed	Normal	Make PCI-E videocard test power assemble kit	tin		11/28/2010
330		+	Closed			ARandomOWI		12/14/2011
230	ARM-camp	Feature		Normal	Add mercurial DVCS intro to wiki	ARandomOWI		
239	_dev.xdevs.com	Support	Closed	Normal	Update security certificate for crypted access to https://dev.xdevs.com	tin		12/25/2011
238	_dev.xdevs.com	Bug	Closed	Normal	Update repository server	tin		12/25/2011
237	_dev.xdevs.com	Feature	Closed	Normal	Integrate graphviz	tin		12/25/2011
236	dev.xdevs.com	Feature	Closed	Normal	Upgrade redmine site to latest trunk version	tin		12/25/2011
240	_	+	Closed	Normal		tin		12/26/2011
	_dev.xdevs.com	Feature		+	Mercurial style	un		
233	ARM-camp	Feature	Rejected	Normal	Send development miniboard on AT91SAM7S128 to Adrian	tin		12/28/2011
232	ARM-camp	Feature	Rejected	Normal	Add Redmine guide and intro based on dev.xdevs.com project	tin		12/30/2011
242	_dev.xdevs.com	Bug	Closed	High	Users cannot login with current password, must use "lost password feature" due to security enhancement	tin		12/30/2011
244	dev.xdevs.com	Bug	Closed	Normal	Fix Gantt view (stylesheet or plugin)	tin		12/31/2011
243	_dev.xdevs.com	Feature	Closed	Normal	GZIP and cache static	tin		12/31/2011
		+		+		un		
241	_dev.xdevs.com	Bug	Rejected	Normal	Issue view, top header background upgrade	tin		12/31/2011
229	ARM-camp	Feature	Rejected	Normal	Add intro page about STM-Discovery to wiki, create first project	tin		01/15/2012
267	Tektronix TLA714	Feature	Closed	Normal	TEKTRONIX 020-2457-00 COMPRESSION PCB -to- MICTOR ADAPTER	tin		07/10/2012
266	Tektronix TLA714	Feature	Closed	Normal	[eBay] New in the box Tektronix Tek P6860 Probe Set A2-A3/D2-D3	tin		07/16/2012
		+				4in		
268	Keithley 2001 repair	Bug	Closed	Normal	K2 : ERROR 105.2 - System trigger bus	tin		07/22/2012
273	Keithley 2001 repair	Support	Closed	Normal	Buy components for repair	tin		07/30/2012
279	Keithley 2001 repair	Feature	Closed	Normal	Schematics RE - analog board	tin		07/31/2012
285	Keithley 2001 repair	Rework	Closed	Normal	All functions and all ranges "Overflow"	tin		08/05/2012
289	ALTERA 672 Checkout board repair	Support	Closed	Normal	Receive board from EMS			08/10/2012
	·	+				E.a.	-	
294	Keithley 2001 repair	Feature	Closed	Normal	Read and decode firmwares for 2001 DMMs	tin		08/10/2012
287	Keithley 2400 repair	Feature	Rejected	Normal	Calibrate outputs	tin		08/11/2012
299	Tektronix TLA714	Feature	Closed	Normal	Add actual internal pics, add documentation	tin		08/25/2012
342	Keithley 2001 repair	Bug	Closed	Normal	Fix FE section on analog board	tin	1	09/09/2012
296	R&E	+	+			Izera	+	10/03/2012
		Feature	Closed	Normal	iZerg support package	Izerg	1	
292	ALTERA 672 Checkout board repair	Support	Closed	High	Search documentation for "ALTERA 672 Checkout board"	tin		10/10/2012
263	_dev.xdevs.com	Feature	Closed	Urgent	Devsite crashes after few days	tin		10/14/2012
535	Keithley 2001 repair	Bug	Closed	Normal	AC voltage select unit fails	tin		10/21/2012
343	Keithley 2001 repair	Bug	Closed	Normal	Send K2001 #5 to iZerg	Izerg		10/31/2012
639	HP/Agilent 33120A	Support	Closed	Normal	Add related documentation	tin		11/18/2012
297	Keithley 2001 repair	Feature	Closed	Normal	Finish ADC board schematics.	tin		12/11/2012
642	Keithley 2001 repair	Feature	Closed	Normal	Voltage reference block schematics recovery	tin		12/17/2012
641	Keithley 2001 repair	Feature	Closed	Normal	Finish AC input block schematics	tin		12/18/2012
338	_dev.xdevs.com	Feature	Closed	High	Monospace font for <pre> and repository source view</pre>	tin		12/30/2012
	_							
652	Keithley 2001 repair	Bug	Closed	Normal	Fix AC input mains curcuitry, replace electrolytic capacitors, replace transformer	tin		12/31/2012
659	Keithley 2001 repair	Bug	Rejected	Normal	Fix Test 412.1 – AC amps switch	tin		01/13/2013
658	Keithley 2001 repair	Bug	Closed	Normal	Fix 401.1 - Signal switching; zero cal switch	tin		01/13/2013
752	Tektronix TDS/CSA7000 (CSA7404)	Feature	Closed	Normal	Pay for scope unit for parts	tin		05/20/2013
760	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Download and write CD-R with Win98/2000	tin		05/22/2013
	1 1	+						
761	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Replace CD-ROM with DVD-RW drive	tin		05/23/2013
759	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Replace HDD, try fresh install windows and Tek software	tin		05/23/2013
766	Nikkor lens repair	Bug	Closed	Normal	Buy replacement parts for 17-35	tin		05/31/2013
753	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Receive scope, initial inspection	tin		05/31/2013
769	Tektronix TDS/CSA7000 (CSA7404)		Closed		Try to run TDS7704B w/o connection between PPC and AQ boards?	tin		06/02/2013
	, ,	Support		Normal		uii		
770	_dev.xdevs.com	Bug	Closed	Normal	Notification emails are lost/not full	tin		06/03/2013
774	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Pay for pair of Tektronix P7380 TekConnect differential 8GHz probes	tin		06/04/2013
768	Tektronix TDS/CSA7000 (CSA7404)	Feature	Closed	Normal	Install all system Tektronix drivers for devices on Win2000	tin		06/30/2013
805	Tektronix TLA714	Bug	Closed	Normal	Battery for CMOS died on PC board, date got reset	tin		09/15/2013
		+		+		tin		
808	Tektronix TLA714	Feature	Closed	Normal	Backup NVRAM on TLA7AA4	un		09/20/2013
817	Keithley 2001 repair	Support	Closed	Normal	Схема платы A/D (Keithley 2001-162-01G)	tin		10/03/2013
819	Keithley 2001 repair	Support	Closed	Normal	Схема платы передней панели	tin		10/08/2013
820	Keithley 2001 repair	Support	Closed	Normal	Schematics for digital board (Keithley 2001-142-06H)	tin		10/31/2013
840	Keithley 2001 repair	Support	Closed	Normal	3 ADC modules shipped, receive and test rest units	tin		11/09/2013
		+		+		tin	+	
860	HP 4263B	Feature	Closed	Normal	Pay for LCR meter	un		12/14/2013
854	Keithley 2001 repair	Bug	Closed	Normal	Fix error 402.1 - Signal switching; frequency switch	tin		12/14/2013
869	Keithley 2001 repair	Feature	Closed	Normal	Spec test	tin		12/15/2013
868	Keithley 2001 repair	Feature	Closed	Normal	Assembly meter for function checks.	tin		12/15/2013
855	Keithley 2001 repair	+	Closed	Normal	Fix error 403.1 – Signal switching; ground switch	tin		12/21/2013
		Bug				e		
866	Keithley 2001 repair	Bug	Closed	Normal	Fix error 409.6 – ÷750 correction factor; signal comparisons	tın		12/22/2013
865	Keithley 2001 repair	Bug	Closed	Normal	Fix errors 407.1, 407.2, 407.3 - Front end 2V/200V/750V	tin		12/22/2013
864	Keithley 2001 repair	Bug	Closed	Normal	Fix error 406.6 – Voltage comparison	tin		12/22/2013
863	Keithley 2001 repair	Bug	Closed	Normal	Fix errors 405.2, 405.4, 405.6, 405.8, - Absolute value x10 gain comparison	tin		12/22/2013
						tin		
862	Keithley 2001 repair	Bug	Closed	Normal	Fix errors 404.1, 404.2, 404.3, 404.4, 404.5 - Absolute value (x1 gain);	UII		12/22/2013
874	Keithley 2000	Feature	Closed	Normal	Keithley 2000 schematics	tin		12/23/2013
873	_dev.xdevs.com	Feature	Closed	Immediate	Update engine to 2.4.1	tin		12/23/2013
856	Keithley 2001 repair	Bug	Closed	Normal	Fix error 412.1 – AC amps switch	tin		12/28/2013
867	Keithley 2001 repair	Bug	Closed	Normal	Fix error 410.1, 411.1, 411.2 - TRMS / TRMS Filter	tin		12/29/2013
						e.		
878	_dev.xdevs.com	Feature	Closed	Normal	Improve and bug fix for theme / stylesheets.	tın		12/29/2013

1/4

	Positivat	T 1	0.	D.i"		A	l
071	Project Koithley 2001 repair	Tracker	Status	Priority	Subject Penlace C108 capacitor	Assignee Category	Due date
871	Keithley 2001 repair R&E	Bug Support	Closed	Normal Normal	Replace C108 capacitor EDC MV106 DC Voltage standard backlog	tin	12/31/2013 12/31/2013
754	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Outer covers replacement parts needed	tin	12/31/2013
885	Keithley 2001 repair	Feature	Closed	-	Keithley 2001 thermal evaluation	tin	01/01/2014
887	Keithley 2400 repair	Bug	Closed	Normal	Fix front panel keypad	tin	01/01/2014
890	Keithley 2001 repair	Support	Closed	Normal	Install DS1245Y for MEM2 option	tin	01/04/2014
807	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	High	Tek CSA7404 scope repair article worklog	tin	01/04/2014
895	Keithley 2001 repair	Feature	Closed	Normal	304.x series self-test errors (Ohm)	Izerg	01/05/2014
894	Keithley 2001 repair	Support	Closed	+	iZerg Keithley serial number request	Izerg	01/05/2014
891	Keithley 2001 repair	Feature	Closed		Self-test errors diagnosis	tin	01/05/2014
889	Keithley 2001 repair	Bug	Closed	Normal	Replace fan	tin	01/05/2014
905 898	R&E	Support	Closed	Normal	Buy parts for K2001 project repairs Added issuefy importer	tin	01/05/2014
898	_dev.xdevs.com HP 4263B	Feature Feature	Closed	Normal Normal	Added issuefy importer Initial check and repair estimate	tin	01/05/2014
907	HP 4263B	Feature	Rejected	Normal	Add option updates for 001 and 002	tin	01/11/2014
888	Keithley 2001 repair	Feature	Closed	Normal	Send 2001 DMM for calibration to Tektronix Taiwan	tin	01/12/2014
286	Keithley 2001 repair	Feature	Closed	Normal	Calibrate unit (Tektronix calibration)	tin	01/19/2014
886	Keithley 2400 repair	Support	Closed	Normal	Send 2400 SMU for calibration to Tektronix Taiwan	tin	01/31/2014
857	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Buy Tek P6205 probe for general voltage measurements (40V pk-pk)	tin	01/31/2014
958	Keithley 2002	Feature	Closed	Normal	Initial inspection for K2002 (331119346214)	tin	02/10/2014
956	Keithley 2001 repair	Feature	Closed		Calibration constants for K2001 units	tin	02/15/2014
637	Keithley 2001 repair	Support	Closed	Normal	Review 2001's inventory	tin	02/16/2014
852	Keithley 2001 repair	Feature	Closed	Normal	LabView control panel development Paguaget correct repair manual for 2002	tin	02/28/2014
973	Keithley 2002 HP 4263B	Feature	Rejected	Normal	Request correct repair manual for 2002 PCR daughter board schematics recovery	tin	02/28/2014
999		Feature	Closed	Normal	PCB daughter board schematics recovery Lindate redmine to 2.5.0	tin	03/02/2014
999	_dev.xdevs.com	Support Support	Closed	Normal Normal	Update redmine to 2.5.0 Order PCBs for VREF A00 module	tin	03/15/2014
1065	HP 4263B	Support	Closed	Normal	Modify LCR probe according to Agilent connection spec.	tin	04/20/2014
1071	Raspberry Pi	Feature	Closed	Normal	Buy Raspberry Pi module	tin	04/27/2014
1059	HP 4263B	Support	Closed	Low	Improve LCD to inverse 40x2?	tin	04/30/2014
1038	content_mgmt	Feature	Closed	Normal	Статьи на апрель 2014	tin	04/30/2014
1070	Nikon DSLR	Feature	Closed	Normal	Initial inspection	tin	05/02/2014
1072	Raspberry Pi	Feature	Closed	Normal	Make DDR slot adapter for SPD read/write	tin	05/09/2014
1089	Nikon DSLR	Feature	Closed	High	Repair D3	tin	05/11/2014
1106	Raspberry Pi	Feature	Closed	Normal	Add checksum checks/validation function	tin	05/19/2014
1108	Raspberry Pi	Support	Closed	Normal	Update article to version 1.0	tin	05/20/2014
1073	Raspberry Pi	Feature	Closed	Normal	Initial firmware to read/write SPD EEPROM (EC)	tin	05/21/2014
1113	_dev.xdevs.com Raspberry Pi	Bug Feature	Closed	Immediate Low	Repository system security update DDR3/DDR4 SPD read tool for RPI+DDR4s	tin	05/22/2014 05/25/2014
1092	KX	Feature	Closed		VPG resistor for prototype build	tin	05/25/2014
1163	content_mgmt	Feature	Failed	Normal	Статьи к публикации	tin	05/31/2014
1039	content_mgmt	Feature	Failed	Normal	Статьи на май 2014	tin	05/31/2014
1123	R&E	Support	Closed	Normal	Fluke 52 II thermometer calibration - 89020093	tin	06/10/2014
1131	Keithley 2001 repair	Support	Closed	Normal	Schematics for voltage reference LM399	tin	07/11/2014
859	Keithley 2001 repair	Feature	Closed	Normal	Схема аналоговой платы (Keithley 2001-102-04J)	tin	07/11/2014
818	Keithley 2001 repair	Support	Closed	Normal	Schematics for analog board (Keithley 2001-102-04L)	Izerg	07/21/2014
816	Keithley 2001 repair	Support	Closed	Normal	Schematics recovery for analog board Keithley 2001	tin	07/21/2014
1142	Keithley 2002	Feature	Closed	Normal	Measure LT1013+LTZ1000A VREF voltages	tin	07/21/2014
1159	Keithley 2000	Rework	Closed	Normal	Clean board and restore damaged traces from leaked electrolyte	tin	09/22/2014
1170	Keithley 2510 Keithley 2510	Feature Feature	Closed	Normal	Calibrate unit Publish repair article about 2510 TEC SMU	tin	12/06/2014 12/07/2014
288	Keithley 2001 repair	Bug	Closed	High	K4 - repair status.	tin	02/28/2015
739	E-table 2	Support	Closed		Create initial design concept	tin	04/26/2015
1193	Keithley 2000	Feature	Closed	Normal	Buy parts for repair	tin	05/30/2015
1216	_dev.xdevs.com	Support	Closed	High	Update redmine to latest 3.0.x trunk	tin	07/20/2015
1229	content_mgmt	Feature	Closed	Normal	Article for DMM noise measurement analysis	tin Article	08/06/2015
1227	content_mgmt	Feature	Closed	High	NI HS-GPIB-USB review	tin Article	08/16/2015
1234	HP 3458A	Feature	Closed	Normal	Receive unit, initial inspection	tin	09/17/2015
1233	content_mgmt	Feature	Closed	Normal	Перевод https://xdevs.com/article/ddr4s/	tin Article	09/23/2015
1242	HP 3458A	Feature	Closed	Normal	Make 3D drawing for LTZ1000 plastic cap	tin	10/05/2015
1261	HP 3458A	Feature	Closed	Normal	Make measurement on integrator and reference path on A3 A/D board	tin	10/16/2015
1262	content_mgmt	Feature	Closed	Normal	Publish 3456A	tin Article	10/25/2015
1272	HP 3458A	Feature	Closed	Normal	Install memory option 001 back Help conjecting to repair HP 24401A	tin	11/30/2015 01/16/2016
1299 1361	R&E Fluke 720A repair	Feature Support	Closed	Normal Normal	Help sonicyang to repair HP 34401A Inspection, photos and check	tin	01/16/2016
293	ALTERA 672 Checkout board repair	Feature	Closed		Power check - voltage in spec, power good - ok?	Izerg	00/03/2010
291	ALTERA 672 Checkout board repair	Bug	Closed	High	VCC SSO замкнут на землю?	Izerg	
119	AM2	Bug	Closed		R7,R8 - fix value to allow generator running	tin	
740	E-table 2	Feature	Closed	Normal	Onboard workspace PC system	tin	
1289	HP 3458A	Feature	Closed	Normal	1ppm/hour drift on new ADC board	tin	
1260	HP 3458A	Feature	Closed	Normal	ERROR 114 balanced multislope convergence	tin	

12/02/2022

	Project	Tracker	Status	Priority	Subject	Assignee Category Due date
	HP 3458A	Bug	Closed		ERROR 114 multislope rundown convergence	tin
	HP 3458A	Feature	Closed	Normal	Digikey order 2	tin
	HP 3458A	Rework	Closed	Normal	Make CPLD logic replacement for PAL address decoder 03458-88804	tin
	HP 3458A	Feature	Closed	Normal	Replace capacitors on A6 board.	tin
	HP 3458A	Feature	Closed	Normal	Order replacement parts from Keysight	tin
	HP 3458A	Rework	Closed	Normal	Test mains power supply domain & transformer	tin
1235	HP 3458A	Rework	Closed	Normal	Buy and install A9 reference board	tin
945	HP 4263B	Feature	Closed	Normal	Hack to enable Option 001 and 002	tin
	HP 4263B	Feature	Closed	Normal	Replace damaged components	tin
_	HP/Agilent 33120A	Feature	Closed	Normal	Inspect unit, diagnose and isolate problem	tin
1266	HP3245A	Feature	Closed		Receive unit, initial inspection and tests	tin
1088	KX	Inventory	Closed	Normal	MAX6610AUT temp sensor SOT23-6 THD box 10pcs	tin
1087	KX	Inventory	Closed	Normal	LTC2057HS8 - 17pcs THD box	tin
941	KX	Inventory	Closed	Normal	LTZ1000ACH SUPER-ZENER VREF	tin
940	KX	Inventory	Closed	Normal	LTC1043CSWPBF SOW18 Building block SW-CAP DUAL	tin
939	KX	Inventory	Closed	Normal	LT1116CS8	tin
938	KX	Inventory	Closed	Normal	LT1223CS8	tin
934	KX	Inventory	Closed	Normal	PMBFJ111-215 JFET NCH 40V 20mA SOT23-3	tin
933	KX	Inventory	Closed		PMBFJ620-115 NJFET DUAL 25V SOT363	tin
930	KX	Inventory	Closed	Normal	TL7705ACDR	tin
927	KX	Inventory	Closed	Normal	AD7490BRUZ	tin
926	KX	Inventory	Closed	Normal	LTC1050CS8	tin .
925	KX	Inventory	Closed	Normal .	LMV324I	tin .
	Keithley 2000	Feature	Closed	Low	Check components on K2000 unit	tin
1160	Keithley 2000	Support	Closed	+	Backup EEPROM with programm memory A02	tin e
	Keithley 2000	Feature	Closed		Broken K2000 unit received, need repairs	tin diameter and the second se
	Keithley 2001 repair	Feature	Closed	Normal	Dump firmware B17 from 2001M	tin diameter
	Keithley 2001 repair	Bug	Closed	Normal	Repair status for very first 2001 unit	tin
	Keithley 2001 repair	Bug	Closed	Normal	Repair status	tin .
	Keithley 2001 repair	Feature	Closed	Normal	Восстановление источника тока и диапазонов измерения сопротивления	tin
	Keithley 2001 repair	Feature	Closed	Normal	UART protocol between front panel board and digital board.	tin
	Keithley 2001 repair	Bug	Closed	Normal	Issue list update	tin
858	Keithley 2001 repair	Bug	Closed	Normal	VFD Power supply issues?	tin
284	Keithley 2001 repair	Rework	Closed	Normal	Test digital board.	tin
	Keithley 2001 repair	Rework	Closed	Normal	No response from analog board	tin
	Keithley 2001 repair	Rework	Closed	Normal	Install display board	tin
	Keithley 2001 repair	Feature	Closed	Normal	Display board move to unit #4	tin
278	Keithley 2001 repair	Feature	Closed	Normal	D2 - checks	£
	Keithley 2001 repair	Bug	Closed		K2 - ERROR 405.2 – Absolute value x10 gain comparison; large +DAC output	tin diameter and the second se
	Keithley 2001 repair	Bug	Closed		ERROR 404.1 – Absolute value (x1 gain); -full-scale DAC output	tin tin
	Keithley 2001 repair	Bug	Closed		K2 - Error 402.1 - Frequency switch	un tin
	Keithley 2001 repair	Bug	Closed	Normal	K2 : ERROR 401.1 - Signal switching; zero cal switch	un tin
272	Keithley 2001 repair	Support	Closed		K2 - repair status.	tin diameter and the second se
	Keithley 2001 repair	Feature	Closed	Normal	K2 : ERROR 304 Section	tin 4:
	Keithley 2001 repair	Bug	Closed		K2 : ERROR 304.7 - Ohms sources; 4.4nA and 770nA	tin tin
	Keithley 2001 repair	Bug	Closed	Normal	K2 : ERROR 304.6 - Ohms sources; 70nA and 770nA	tin
	Keithley 2400 repair	Bug	Closed	Low	Front panel replacement quote? Get and flach correct firmware for 2510 into AT49E040 (L169)	tio
	Keithley 2510	Feature	Closed	+	Get and flash correct firmware for 2510 into AT49F040 (U168) Receive 2510 unit for repair	tio
1166 893	Keithley 2510 Keithley 7001	Feature	Closed Rejected	Normal Low	Receive 2510 unit for repair Front board taken for Keithley 2001, get replacement?	tin
	Nikkor lens repair	Support Rework	Closed	Normal		tin
	Nikon DSLR		Closed	Normal	Replace connection aperture ring Schematics for fake EN-EL4a battery	tin
	Nikon DSLR Nikon DSLR	Feature Feature	Closed	Normal	Adjust EH-4 AC brick for 13VDC output for D3	tin
4	PWMC		Closed	Normal		tin
882	R&E	Bug Support	Closed	Low	Firmware and hardware check Requested Tektronix quotation for calibration with data	tin
955		+_ *:				tin
	R&E Raspberry Pi	Feature Feature	Closed	Normal	Install I2C support for RPI	tin
		Feature	Closed	Normal	3D model of DIMM adapter assembly	tin
	Raspberry Pi		Closed			tio
796	Tektronix TDS/CSA7000 (CSA7404) Tektronix TDS/CSA7000 (CSA7404)	Bug Support	Closed	Normal Normal	Trigger encoder shaft damaged - replace encoder Bourns EPS1E-F19 S53 Upgrade CPU to Pentium III, add extra memory for NLX board, install DVD-RW	tin
796					Channel 1 out of cal?	tin
	Tektronix TDS/CSA7000 (CSA7404)	Bug	Closed	Normal	Channel 1 out of cal? Channel 2 and 3 not powering Tektronix P7380 probe, not working?	tio
	Tektronix TDS/CSA7000 (CSA7404)	Bug		Normal		tio
	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Buy BR1632 3V battery for NVRAM DALLAS replacement with leads	tio
	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Install Windows 2000 SP4 Pro for test	4:0
	Tektronix TDS/CSA7000 (CSA7404)	Rework	Rejected	Normal	Install Windows 98 on another HDD for test.	4:0
	Tektronix TLA714	Feature	Closed		Бюджет проекта	4:0
815	Tektronix TLA714	Feature	Closed	Normal	Unlock more memory for TLA7AA4	un a
-	Tektronix TLA714	Feature	Closed		Firmware binary for TLA7AA4 5.5.003	un tin
692	Tektronix TLA714 WARP	Feature	Closed	Normal	Firmware binary for TLA7AA4 5.8.001	un e
454		LRUM	Failed	Normal	VNOM- not connected to ground	jun
	X-CAL	Bug Feature	Closed	Normal	Software specification	

12/02/2022

#	Project	Tracker	Status	Priority	Subject	Assignee	Category	Due date
1126	_dev.xdevs.com	Bug	Closed	Normal	Deployment issue with redmine engine	tin		
876	_dev.xdevs.com	Feature	Rejected	Normal	Merge with documentation site	tin		
670	_dev.xdevs.com	Bug	Closed	Normal	Redirects to dummy redmine host when modify items using HTTPS	tin		
654	_dev.xdevs.com	Feature	Closed	Normal	Knowledge base module added	tin		
536	_dev.xdevs.com	Feature	Closed	Normal	Update engine to 2.1.x branch	tin		
335	_dev.xdevs.com	Bug	Closed	Normal	Need elevated rights for plugins and attached files, why?	tin		
334	_dev.xdevs.com	Bug	Closed	Normal	Stylesheet fix and color updates, fix footer, validate important pages	tin		
298	_dev.xdevs.com	Feature	Closed	Normal	Graphviz not working, Error 500	tin		
264	_dev.xdevs.com	Support	Closed	Normal	Update Redmine engine to 1.4.4	tin		
333	_dev.xdevs.com	Bug	Rejected	High	Caching working not right, need refresh page manually	tin		
1226	content_mgmt	Feature	Closed	Normal	ALTERA MAX II DEVBOARD review	tin	Article	
1206	content_mgmt	Feature	Closed	Normal	Article-review Parallax SmartPack 672	tin	Article	
1205	content_mgmt	Feature	Closed	Normal	Статья-обзор паяльной станции ERSA I-CON	tin	Article	
1204	content_mgmt	Support	Closed	Normal	Rohde & Schwarz Signal generator SMT03 Repair	tin	Repairs	
1201	content_mgmt	Feature	Closed	Normal	Fluke 51-II thermometer	tin	Article	
1200	content_mgmt	Feature	Closed	Normal	Unlocking JLink article	tin	Repairs	
1198	content_mgmt	Feature	Closed	Normal	Обзор прецизионного мультиметра Keithley 2001-M	tin	Article	
1157	content_mgmt	Feature	Closed	Normal	Articles for September 2014	tin		
1130	content_mgmt	Feature	Closed	Normal	Статьи на июль 2014			

12/02/2022