

Keithley 2000 - Rework #1159

Clean board and restore damaged traces from leaked electrolyte

09/22/2014 12:13 PM - tin

Status: Closed	Start date: 09/22/2014
Priority: Normal	Due date: 09/22/2014
Assignee: tin	% Done: 30%
Category:	Estimated time: 0.00 hour
Target version:	
Description Replace C146 (2200uF 16V), C131, C148 (1000uF 50V) Clean board from electrolyte Repair corroded traces Replace U118	

History

#1 - 09/22/2014 12:15 PM - tin

- File gunk1.jpg added
- File gunk2.jpg added
- File gunk3.jpg added

#2 - 09/23/2014 02:08 AM - tin

- % Done changed from 0 to 30

Replaced caps and +15V -15V regs

100.2, 201.1, 201.2, 300.1, 301.2, 303.2 errors fixed.

#3 - 08/05/2016 05:19 AM - tin

- Status changed from In Progress to Closed

Files

gunk1.jpg	279 KB	09/22/2014	tin
gunk2.jpg	300 KB	09/22/2014	tin
gunk3.jpg	261 KB	09/22/2014	tin