

HP 3458A - Rework #1248

Feature # 1238 (Resolved): Repairs

Make CPLD logic replacement for PAL address decoder 03458-88804

10/06/2015 05:48 PM - tin

Status: Closed	Start date: 10/06/2015
Priority: Normal	Due date:
Assignee: tin	% Done: 100%
Category:	Estimated time: 0.00 hour
Target version:	
Description	
Сигнал RSXGD- ведет себя подозрительно. pal.png	

History

#1 - 10/06/2015 07:16 PM - tin

http://xdevs.com/doc/HP_Agilent_Keysight/3458A/img/la/test_2.png

#2 - 10/06/2015 10:43 PM - lzerg

- % Done changed from 0 to 50

Сигнал - показывает что при декодировании адреса задействованы линии 19 и 17
ресет подтвержен сигналом выборки адреса.
нужна дополнительная проверка u700

#3 - 10/07/2015 10:18 AM - tin

- Status changed from In Progress to Resolved

OK, пока отложим.

#4 - 10/12/2015 07:15 PM - tin

- Status changed from Resolved to Suspended

- Assignee changed from lzerg to tin

#5 - 11/04/2015 04:32 AM - tin

- % Done changed from 50 to 100

#6 - 01/18/2016 01:50 PM - tin

- Status changed from Suspended to Closed