

## HP 3245A - Feature #1270

### Replace capacitors, take more photos of internal parts for article

04/11/2015 04:29 - tin

<b>Status:</b>	New	<b>Start date:</b>	18/11/2015
<b>Priority:</b>	Normal	<b>Due date:</b>	25/11/2015
<b>Assignee:</b>	tin	<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>			
<b>Description</b>			

#### History

---

#1 - 04/11/2015 04:34 - tin

HV board

2 x 200V 4.7uF 10x18mm