

HP 3245A - Rework #1281

Replace LM399 to LTZ1000

11/11/2015 03:27 AM - tin

| | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|
| Status: New | Start date: 11/11/2015 |
| Priority: Normal | Due date: |
| Assignee: tin | % Done: 0% |
| Category: | Estimated time: 0.00 hour |
| Target version: | |
| Description Remove U170 Remove R401 Shunt RP1008 pin 19 and pin 5 with 10K Fluke WW Remove R400 Install LTZ module, power +15V from U170 pin 3 Gnd to LTZ module from U170 pin 4 Add buffered LT1028A Triax output for VREF testing | |