

**Tektronix TDS/CSA7000 (CSA7404) - Bug #794**

**Channel 2 and 3 not powering Tektronix P7380 probe, not working?**

09/08/2013 01:49 PM - tin

<b>Status:</b> Closed	<b>Start date:</b> 09/08/2013
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b> tin	<b>% Done:</b> 100%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b>	
<b>Description</b>	

**History**

**#1 - 09/09/2013 03:56 AM - tin**

- Status changed from *New* to *Resolved*
- % Done changed from 0 to 100

Reinstalled Windows 2000 on another 20GB HDD.  
Installed TekScope 2.5.3 SW

No issues with channels 2 & 3.

**#2 - 12/29/2013 12:21 AM - tin**

- Status changed from *Resolved* to *Closed*