

Keithley 2001 repair - Bug #871

Replace C108 capacitor

12/15/2013 04:49 PM - tin

Status: Closed	Start date: 12/15/2013
Priority: Normal	Due date: 12/31/2013
Assignee: tin	% Done: 0%
Category:	Estimated time: 0.00 hour
Target version: Keithley 2001 #6	
Description	
Wrong spec! must be 1000uF 50V	

History

#1 - 07/13/2014 01:39 AM - tin

- Target version changed from Keithley 2001 #7 to Keithley 2001 #6

#2 - 04/11/2015 09:05 PM - tin

- Status changed from New to Closed