

## Keithley 2001 repair - Bug #879

### Issue list update

27/12/2013 00:25 - tin

<b>Status:</b>	Closed	<b>Start date:</b>	27/12/2013
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	tin	<b>% Done:</b>	100%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>	Keithley 2001 #1		
<b>Description</b>			
Self-diag test result:			
309.1 - Amps			
401.1 Zero Cal Sw			
402.1			
403.1			
405.2 - sometimes pass after warmup			
405.4 - sometimes pass after warmup			
405.6			
405.8 - sometimes pass after warmup			
407.1 - sometimes pass after warmup			
407.2 - sometimes pass after warmup			
407.3 - sometimes pass after warmup			
410.1 - sometimes pass after warmup			
411.1 - sometimes pass after warmup			
411.2 - sometimes pass after warmup			

### History

#1 - 07/06/2016 01:22 - tin

- Status changed from New to Closed

- % Done changed from 0 to 100