

**Keithley 2002 - Bug #902****Self-test fails**

01/04/2014 12:44 AM - tin

<b>Status:</b> New	<b>Start date:</b> 01/04/2014
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b>	<b>% Done:</b> 0%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b> plesa unit	

**Description**

304 Series

- 304.2 2MW Open-circuit Ohms Failed

306 Series Ohms

- 306.1 9.6mA Ohms Source Failed
- 306.2 1.92mA Ohms Source Failed

308 Series Overload

- 308.1 Overload HI OK
- 308.2 Overload Ohms Failed
- 308.3 2MW Overload Ohms OK

500 Series Amps/LO Ohms:

- 500.1 96mA Ohms/200mA DCA Range Failed
- 500.2 960mA Ohms/2mA DCA Range Failed
- 500.3 7.2mA Ohms/2mA DCA Range Failed
- 500.4 20mA DCA Range Failed
- 500.6 200mA DCA Range Failed
- 500.7 2A DCA Range Failed

501 Series Amps Protection:

- 501.1 Amps Protection Failed
- 501.2 Amps Bootstrap Failed

502 Series ACA Switch

- 502.1 AC Amps Switch Failed

**History**

#1 - 01/04/2014 12:45 AM - tin

- Description updated

#2 - 03/09/2014 05:42 PM - tin

- Category set to 111

- Target version set to plesa unit