

## Issues

| #    | Project                         | Tracker   | Status      | Priority | Subject  | Assignee | Category      | Due date   |
|------|---------------------------------|-----------|-------------|----------|--|----------|---------------|------------|
| 1217 | _dev.xdevs.com                  | Support   | Planning    | Normal   | Update header and footer on redmine to match django site.          | tin      |               | 07/26/2015 |
| 1199 | content_mgmt                    | Feature   | Planning    | Normal   | Second life for dead VGA cards - using as high-power power supply  | tin      | Article       |            |
| 1063 | _dev.xdevs.com                  | Feature   | Planning    | Normal   | Project index  | tin      |               | 11/30/2015 |
| 1007 | _dev.xdevs.com                  | Bug       | Planning    | Normal   | Contacts plugin cause Internal error                               | tin      |               |            |
| 903  | content_mgmt                    | Support   | Planning    | Normal   | Write tutorial about using redmine for projects                    | tin      | Documentation | 01/31/2014 |
| 877  | _dev.xdevs.com                  | Feature   | Planning    | Normal   | Implement documentatation portal                                   | tin      |               |            |
| 671  | _dev.xdevs.com                  | Feature   | Planning    | Normal   | Add RhodeCode to dev.xdevs.com                                     | tin      |               |            |
| 337  | _dev.xdevs.com                  | Feature   | Planning    | Normal   | Reformat issue view for easier usage. Slim design                  | tin      |               |            |
| 1169 | Keithley 2510                   | Feature   | Suspended   | Normal   | X-K2510RH - resistor heater adapter design                         | tin      |               |            |
| 1288 | content_mgmt                    | Feature   | Feedback    | Normal   | TI ADS1262 EVM article series review                               | tin      | Article       | 01/18/2016 |
| 853  | Keithley 2001 repair            | Support   | Feedback    | Normal   | Бюджет проекта   | tin      |               |            |
| 1314 | Keithley 2002                   | Rework    | Resolved    | Normal   | Repair unit 2  | tin      |               | 03/25/2016 |
| 1296 | Keithley 2002                   | Feature   | Resolved    | Normal   | Test with different mains  | tin      |               |            |
| 1265 | HP 3245A                        | Feature   | Resolved    | Normal   | Receive unit, initial inspection                                   | tin      |               | 11/03/2015 |
| 1202 | content_mgmt                    | Feature   | Resolved    | Normal   | HP 11177B - Calibration module from HP 3455A                       | tin      | Article       |            |
| 1103 | Tektronix TDS/CSA7000 (CSA7404) | Feature   | Resolved    | Normal   | Dead again, software hangs during bootup - fixed with new DS1245YP | tin      |               |            |
| 1077 | _dev.xdevs.com                  | Feature   | Resolved    | High     | Page style issues for dev.xdevs.com                                | tin      |               | 04/27/2014 |
| 1012 | R&E                             | Support   | Resolved    | Normal   | Заказать компоненты  | tin      |               |            |
| 1010 | R&E                             | Support   | Resolved    | Normal   | Aquired ERSA I-CON1 soldering station                              | tin      |               | 03/20/2014 |
| 981  | Tektronix TLA714                | Feature   | Resolved    | Normal   | SPI Decode support library   | tin      |               | 03/22/2014 |
| 966  | Keithley 2002                   | Support   | Resolved    | Normal   | Схема платы A/D (Keithley 2002-xxx-01x)                            | tin      |               | 03/01/2014 |
| 959  | Tektronix TDS/CSA7000 (CSA7404) | Feature   | Resolved    | Normal   | TCA-1MEG review  | tin      |               | 02/16/2014 |
| 950  | KX                              | Inventory | Resolved    | Normal   | GU256X64-355 display   | tin      |               |            |
| 1285 | HP 3458A                        | Feature   | In Progress | Normal   | Measure stability per SN 18  | tin      |               | 11/26/2015 |
| 1257 | HP 3458A                        | Feature   | In Progress | Normal   | Adapter boards for Intersil comparators and EL22xxCM               | tin      |               |            |
| 1224 | content_mgmt                    | Feature   | In Progress | Normal   | Translate articles to both languages                               | tin      | Article       | 08/24/2015 |
| 1203 | content_mgmt                    | Feature   | In Progress | Normal   | Taking proper photographs of electronic hardware and PCBAs         | tin      | Article       |            |
| 1191 | KX-DAC                          | Feature   | In Progress | Normal   | Schematics design  | tin      |               | 05/03/2015 |
| 1177 | REF-R                           | Feature   | In Progress | Normal   | 2 x VREFs sale   | tin      |               | 02/23/2015 |
| 1175 | Tektronix TLA714                | Support   | In Progress | Normal   | Декодирование данных I2C с помощью TLA714                          | tin      |               | 01/31/2015 |
| 1164 | KX-H : Low-noise amp            | Feature   | In Progress | Normal   | Schematics release for modular prototype                           | tin      |               | 10/31/2014 |
| 1155 | Tektronix TDS/CSA7000 (CSA7404) | Feature   | In Progress | Normal   | DSA71604 option  | tin      |               | 09/05/2014 |
| 1078 | KX                              | Feature   | In Progress | Normal   | PCB for low-thermal shorting plug                                  | tin      |               | 06/29/2014 |
| 1075 | R&E                             | Feature   | In Progress | Normal   | Cadence tutorial feedback & review                                 | tin      |               |            |
| 1068 | KX                              | Feature   | In Progress | Normal   | Wire-wound precision resistors samples                             | tin      |               |            |
| 1024 | REF-R                           | Support   | In Progress | Normal   | Module tracklog  | tin      |               |            |
| 1022 | REF-R                           | Bug       | In Progress | Normal   | VREF Board A01 errata  | tin      |               | 04/05/2014 |
| 1018 | REF-R                           | Support   | In Progress | Normal   | Community feedback / units allocation                              | tin      |               |            |
| 1014 | KX                              | Support   | In Progress | Low      | Components supply for project                                      | tin      |               |            |
| 1011 | R&E                             | Support   | In Progress | Normal   | Добавить модели для Solidworks                                     | tin      |               |            |
| 1002 | _dev.xdevs.com                  | Feature   | In Progress | Normal   | Port articles to django site                                       | tin      |               | 03/16/2014 |
| 993  | R&E                             | Support   | In Progress | Normal   | Cadence tutorial for Orcad (Component management)                  | tin      |               |            |
| 980  | Tektronix TLA714                | Feature   | In Progress | Normal   | I2C decode support library   | tin      |               | 03/15/2014 |
| 979  | Tektronix TLA714                | Feature   | In Progress | Normal   | Report issue regarding TLA Application under Winx64                | tin      |               | 03/10/2014 |
| 972  | Keithley 2002                   | Feature   | In Progress | Normal   | Thermal photos for K2002   | tin      |               | 02/23/2014 |
| 954  | R&E                             | Feature   | In Progress | Normal   | Resistors test   | tin      |               | 02/28/2014 |
| 949  | KX                              | Feature   | In Progress | Normal   | Front panel design   | tin      |               | 02/09/2014 |
| 946  | HP 4263B                        | Feature   | In Progress | Normal   | Recover inputs schematics and power modules schematics             | tin      |               | 03/02/2014 |
| 937  | KX                              | Inventory | In Progress | Normal   | LT1097S8   | tin      |               |            |
| 906  | HP 4263B                        | Feature   | In Progress | Normal   | Review and teardown article  | tin      |               | 01/18/2014 |
| 901  | Keithley 2002                   | Support   | In Progress | Normal   | Collect photos of 2002 internals                                   | tin      |               |            |
| 899  | _dev.xdevs.com                  | Support   | In Progress | Normal   | Отзывы и замечания по новому UI redmine?                           | tin      |               |            |
| 883  | KX                              | Support   | In Progress | Normal   | Keithley 2001 ADC model, Multisim 12 project                       | tin      |               | 01/31/2014 |
| 295  | ALTERA SMB2 Repair              | Rework    | In Progress | Normal   | Debug JTAG Stratix communication issue                             | tin      |               |            |
| 234  | content_mgmt                    | Support   | In Progress | Normal   | Prepare and release xDevs.com coding standard                      | tin      | Documentation | 01/11/2012 |
| 122  | content_mgmt                    | Feature   | In Progress | Normal   | Make article-review about voltage references.                      | tin      |               |            |
| 1302 | R&E                             | Feature   | New         | Normal   | Wolf resistors   | tin      |               |            |
| 1283 | HP 3245A                        | Feature   | New         | Normal   | Recalibrate unit after update to LTZ                               | tin      |               |            |
| 1282 | HP 3245A                        | Feature   | New         | Normal   | Test calibration, save calibration RAM                             | tin      |               |            |
| 1281 | HP 3245A                        | Rework    | New         | Normal   | Replace LM399 to LTZ1000   | tin      |               |            |
| 1280 | KX-A                            | Feature   | New         | Normal   | 2A current amp   | tin      |               |            |
| 1279 | HP 3458A                        | Feature   | New         | Normal   | Usage items  | tin      |               |            |
| 1271 | HP 3458A                        | Feature   | New         | Normal   | Install optics on external trigger on A6 PCBA                      | tin      |               |            |
| 1270 | HP 3245A                        | Feature   | New         | Normal   | Replace capacitors, take more photos of internal parts for article | tin      |               | 11/25/2015 |
| 1264 | content_mgmt                    | Feature   | New         | Normal   | Style improvements for articles                                    | tin      | Article       |            |
| 1258 | HP 3458A                        | Feature   | New         | Normal   | Adapter board for LMH6321 buffer                                   | tin      |               |            |
| 1196 | Keithley 2001 repair            | Feature   | New         | Normal   | Analog interface protocol  | tin      |               |            |
| 1165 | KX-H : Low-noise amp            | Feature   | New         | Normal   | PCB layout for amp module KX-H                                     | tin      |               | 11/09/2014 |
| 1132 | KX-H : Low-noise amp            | Feature   | New         | Low      | Collect existing solutions and applications.                       | tin      |               |            |

| #    | Project                         | Tracker   | Status | Priority | Subject  | Assignee | Category | Due date   |
|------|---------------------------------|-----------|--------|----------|--|----------|----------|------------|
| 1128 | REF-R                           | Feature   | New    | Normal   | Order PCBs for VREF B01 module , VREF RATIO, Shorting plug           | tin      |          | 06/28/2014 |
| 1117 | R&E                             | Feature   | New    | Normal   | Article about measuring low capacitance with DMM                     | tin      |          | 05/25/2014 |
| 1111 | Raspberry Pi                    | Feature   | New    | Low      | XMP parser / information tool  | tin      |          | 05/25/2014 |
| 1107 | Raspberry Pi                    | Feature   | New    | Low      | Add multiple module support on single RPI bus                        | tin      |          | 05/24/2014 |
| 1104 | TC-M                            | Feature   | New    | Normal   | Bought components supply   | tin      |          |            |
| 1086 | KX                              | Inventory | New    | Normal   | Film SMD capacitor LDECB3100JA0N00 0.1uF 50VDC 1210                  | tin      |          |            |
| 1079 | Nikon DSLR                      | Feature   | New    | Normal   | D800 external power hack / ID workaround                             | tin      |          |            |
| 1067 | KX                              | Support   | New    | Normal   | References / 3rd-party resources                                     | tin      |          |            |
| 1013 | R&E                             | Support   | New    | Normal   | Заказать плату   | tin      |          |            |
| 971  | KX                              | Feature   | New    | Normal   | Open-hardware transition   | tin      |          | 02/23/2014 |
| 970  | REF-R                           | Feature   | New    | Normal   | Battery power option for references                                  | tin      |          |            |
| 969  | Tektronix TDS/CSA7000 (CSA7404) | Bug       | New    | Low      | Check write-protection switch mode                                   | tin      |          |            |
| 965  | Keithley 2002                   | Support   | New    | Normal   | Восстановить схему для ремонта и отладки Keithley 2002               | tin      |          | 06/30/2014 |
| 964  | Keithley 2002                   | Support   | New    | Normal   | SCH   Схема аналоговой платы (Keithley 2002-xxx-04x)                 | tin      |          | 06/30/2014 |
| 963  | Keithley 2002                   | Feature   | New    | Normal   | Calibration constants for K2002                                      | tin      |          | 02/23/2014 |
| 952  | KX                              | Feature   | New    | Normal   | Define spec for project  | tin      |          | 02/01/2014 |
| 948  | HP 4263B                        | Feature   | New    | Normal   | Inputs protection curcuitry  | tin      |          | 01/22/2014 |
| 900  | content_mgmt                    | Feature   | New    | Low      | Add interactive plugin for common electronics calculations           | tin      |          | 05/31/2014 |
| 892  | Tektronix TDS/CSA7000 (CSA7404) | Feature   | New    | Normal   | Clean and repair P6205 probe   | tin      |          |            |
| 822  | _dev.xdevs.com                  | Feature   | New    | Normal   | Don't send suspended issues by email notifications                   | tin      |          |            |
| 781  | Nikkor lens repair              | Bug       | New    | Normal   | SWM AF mechanism have issues when focusing                           | tin      |          |            |
| 747  | Tektronix TLA714                | Feature   | New    | Normal   | Mictor-2.54mm adapter board - LA-TP Board REV 01 www.sar-systems.com | tin      |          | 04/09/2013 |
| 655  | _dev.xdevs.com                  | Feature   | New    | Normal   | Separate theme/style to separate dedicated xdevs-blue theme module   | tin      |          | 01/02/2013 |
| 336  | _dev.xdevs.com                  | Feature   | New    | Normal   | autoupdate SCM in redmine for autotrack issues                       | tin      |          |            |