Issues								
#	Project	Tracker	Status	Priority	Subject	Assignee	Category	Due date
230	ARM-camp	Feature	Closed	Normal	Add mercurial DVCS intro to wiki	ARandomOWI		12/14/2011
895	Keithley 2001 repair	Feature	Closed	Normal	304.x series self-test errors (Ohm)	Izerg		01/05/2014
293	ALTERA 672 Checkout board repair	Feature	Closed	Normal	Power check - voltage in spec, power good - ok?	Izerg		
	·	+	Closed					07/21/2014
818	Keithley 2001 repair	Support		Normal	Schematics for analog board (Keithley 2001-102-04L)	Izerg		_
	Keithley 2001 repair	Bug	Closed	Normal	Send K2001 #5 to iZerg	Izerg		10/31/2012
291	ALTERA 672 Checkout board repair	Bug	Closed	High	VCC SSO замкнут на землю?	Izerg		
894	Keithley 2001 repair	Support	Closed	Normal	iZerg Keithley serial number request	Izerg		01/05/2014
296	R&E	Feature	Closed	Normal	iZerg support package	Izerg		10/03/2012
1289	HP 3458A	Feature	Closed	Normal	1ppm/hour drift on new ADC board	tin		
840	Keithley 2001 repair	Support	Closed	Normal	3 ADC modules shipped, receive and test rest units	tin		11/09/2013
1074	Raspberry Pi	Feature	Closed	Normal	3D model of DIMM adapter assembly	tin		+
				+		tio		10/01/0010
535	Keithley 2001 repair	Bug	Closed	Normal	AC voltage select unit fails	un .		10/21/2012
927	KX	Inventory	Closed	Normal	AD7490BRUZ	tin		
1226	content_mgmt	Feature	Closed	Normal	ALTERA MAX II DEVBOARD review	tin	Article	
232	ARM-camp	Feature	Rejected	Normal	Add Redmine guide and intro based on dev.xdevs.com project	tin		12/30/2011
299	Tektronix TLA714	Feature	Closed	Normal	Add actual internal pics, add documentation	tin		08/25/2012
1106	Raspberry Pi	Feature	Closed	Normal	Add checksum checks/validation function	tin		05/19/2014
229	ARM-camp	Feature	Rejected	Normal	Add intro page about STM-Discovery to wiki, create first project	tin		01/15/2012
907	•	+	1	<u> </u>		tin	-	+
	HP 4263B	Feature	Rejected	Normal	Add option updates for 001 and 002	uil		01/12/2014
639	HP/Agilent 33120A	Support	Closed	Normal	Add related documentation	tin	-	11/18/2012
898	_dev.xdevs.com	Feature	Closed	Normal	Added issuefy importer	tin		01/05/2014
1080	Nikon DSLR	Feature	Closed	Normal	Adjust EH-4 AC brick for 13VDC output for D3	tin		
285	Keithley 2001 repair	Rework	Closed	Normal	All functions and all ranges "Overflow"	tin		08/05/2012
1229	content_mgmt	Feature	Closed	Normal	Article for DMM noise measurement analysis	tin	-	08/06/2015
1206	content_mgmt	Feature	Closed	Normal	Article-review Parallax SmartPack 672	tin	Article	1
						ation .	Aitioie	+
1157	content_mgmt	Feature	Closed	Normal	Articles for September 2014	uri		1
868	Keithley 2001 repair	Feature	Closed	Normal	Assembly meter for function checks.	tin		12/15/2013
1160	Keithley 2000	Support	Closed	Normal	Backup EEPROM with programm memory A02	tin		
808	Tektronix TLA714	Feature	Closed	Normal	Backup NVRAM on TLA7AA4	tin		09/20/2013
805	Tektronix TLA714	Bug	Closed	Normal	Battery for CMOS died on PC board, date got reset	tin		09/15/2013
1158	Keithley 2000	Feature	Closed	Normal	Broken K2000 unit received, need repairs	tin		
						Alian .		+
773	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Buy BR1632 3V battery for NVRAM DALLAS replacement with leads	tin		
1071	Raspberry Pi	Feature	Closed	Normal	Buy Raspberry Pi module	tin		04/27/2014
857	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Buy Tek P6205 probe for general voltage measurements (40V pk-pk)	tin		01/31/2014
1235	HP 3458A	Rework	Closed	Normal	Buy and install A9 reference board	tin		
273	Keithley 2001 repair	Support	Closed	Normal	Buy components for repair	tin		07/30/2012
905	R&E	Support	Closed	Normal	Buy parts for K2001 project repairs	tin		01/05/2014
1193	Keithley 2000	Feature	Closed	Normal	Buy parts for repair	tin		05/30/2015
	1							
766	Nikkor lens repair	Bug	Closed	Normal	Buy replacement parts for 17-35	tin		05/31/2013
333	_dev.xdevs.com	Bug	Rejected	High	Caching working not right, need refresh page manually	tin		
287	Keithley 2400 repair	Feature	Rejected	Normal	Calibrate outputs	tin		08/11/2012
1170	Keithley 2510	Feature	Closed	Normal	Calibrate unit	tin		12/06/2014
286	Keithley 2001 repair	Feature	Closed	Normal	Calibrate unit (Tektronix calibration)	tin		01/19/2014
956	Keithley 2001 repair	Feature	Closed	Normal	Calibration constants for K2001 units	tin		02/15/2014
						tin		102/10/2011
795	Tektronix TDS/CSA7000 (CSA7404)	Bug	Closed	Normal	Channel 1 out of cal?	uii .	<u></u>	+
794	Tektronix TDS/CSA7000 (CSA7404)	Bug	Closed	Normal	Channel 2 and 3 not powering Tektronix P7380 probe, not working?	un		
1178	Keithley 2000	Feature	Closed	Low	Check components on K2000 unit	tin		
1159	Keithley 2000	Rework	Closed	Normal	Clean board and restore damaged traces from leaked electrolyte	tin		09/22/2014
739	E-table 2	Support	Closed	Normal	Create initial design concept	tin		04/26/2015
819	Keithley 2001 repair	Support	Closed	Normal	Схема платы передней панели	tin		10/08/2013
1092	Raspberry Pi	Feature	Closed	Low	DDR3/DDR4 SPD read tool for RPI+DDR4s	tin		05/25/2014
1126	dev.xdevs.com		Closed	Normal	Deployment issue with redmine engine	tin		133
		Bug				ation and a second a second and	<u> </u>	10/11/00/0
263	_dev.xdevs.com	Feature	Closed	Urgent	Devsite crashes after few days	แก		10/14/2012
1249	HP 3458A	Feature	Closed	Normal	Digikey order 2	tin		
281	Keithley 2001 repair	Feature	Closed	Normal	Display board move to unit #4	tin		
760	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Download and write CD-R with Win98/2000	tin		05/22/2013
1188	Keithley 2001 repair	Feature	Closed	Normal	Dump firmware B17 from 2001M	tin		
881	R&E	Support	Closed	Normal	EDC MV106 DC Voltage standard backlog	tin		12/31/2013
	R&E		Closed	Normal	EDC MV106 be voltage standard backlog EDC MV106 calibration	tin		+======================================
955		Feature				uil .		+
1260	HP 3458A	Feature	Closed	Normal	ERROR 114 balanced multislope convergence	un		
1259	HP 3458A	Bug	Closed	Normal	ERROR 114 multislope rundown convergence	tin		
276	Keithley 2001 repair	Bug	Closed	Normal	ERROR 404.1 – Absolute value (x1 gain); -full-scale DAC output	tin		
641	Keithley 2001 repair	Feature	Closed	Normal	Finish AC input block schematics	tin		12/18/2012
297	Keithley 2001 repair	Feature	Closed	Normal	Finish ADC board schematics.	tin		12/11/2012
	PWMC	1	Closed	Normal		tin	 	1.2
1	[I VVIVIO	Bug	Oloseu		Firmware and hardware check	uil	<u> </u>	+
4	T Land Ti ATA C	F/	0.00	N.L.				1
693	Tektronix TLA714	Feature	Closed	Normal	Firmware binary for TLA7AA4 5.5.003	tin		
4 693 692	Tektronix TLA714 Tektronix TLA714	Feature Feature	Closed Closed	Normal Normal	Firmware binary for TLA7AA4 5.5.003 Firmware binary for TLA7AA4 5.8.001	tin		
					·	tin tin tin		01/13/2013
692	Tektronix TLA714	Feature	Closed	Normal	Firmware binary for TLA7AA4 5.8.001	tin tin tin	+	01/13/2013 12/31/2012

	-	_		1			
#	Project	Tracker	Status	Priority	Subject St. FF and the search of the search	Assignee Category	Due date
342	Keithley 2001 repair	Bug	Closed	Normal	Fix FE section on analog board Fix Coart view (attractor at a sturie)	tin tin	09/09/2012
659	_dev.xdevs.com Keithley 2001 repair	Bug	Closed Rejected	Normal	Fix Gantt view (stylesheet or plugin)	tin	12/31/2011 01/13/2013
854	Keithley 2001 repair	Bug	Closed	Normal Normal	Fix Test 412.1 – AC amps switch Fix error 402.1 - Signal switching: frequency switch	tin	12/14/2013
855	Keithley 2001 repair	Bug Bug	Closed	Normal	Fix error 402.1 - Signal switching; frequency switch Fix error 403.1 - Signal switching; ground switch	tin	12/21/2013
864	Keithley 2001 repair	Bug	Closed		Fix error 406.6 – Voltage comparison	tin	12/22/2013
866	Keithley 2001 repair	Bug	Closed	Normal	Fix error 409.6 – ÷750 correction factor; signal comparisons	tin	12/22/2013
867	Keithley 2001 repair	Bug	Closed	Normal	Fix error 410.1, 411.1, 411.2 - TRMS / TRMS Filter	tin	12/29/2013
856	Keithley 2001 repair	Bug	Closed	Normal	Fix error 412.1 – AC amps switch	tin	12/28/2013
862	Keithley 2001 repair	Bug	Closed	Normal	Fix errors 404.1, 404.2, 404.3, 404.4, 404.5 - Absolute value (x1 gain);	tin	12/22/2013
863	Keithley 2001 repair	Bug	Closed	Normal	Fix errors 405.2, 405.4, 405.6, 405.8, - Absolute value x10 gain comparison	tin	12/22/2013
865	Keithley 2001 repair	Bug	Closed	Normal	Fix errors 407.1, 407.2, 407.3 - Front end 2V/200V/750V	tin	12/22/2013
887	Keithley 2400 repair	Bug	Closed	+	Fix front panel keypad	tin	01/01/2014
1201	content_mgmt	Feature	Closed	Normal	Fluke 51-II thermometer	tin Article	
1123	R&E	Support	Closed	Normal	Fluke 52 II thermometer calibration - 89020093	tin	06/10/2014
893	Keithley 7001	Support	Rejected	Low	Front board taken for Keithley 2001, get replacement?	tin	
908	Keithley 2400 repair _dev.xdevs.com	Bug Feature	Closed	Low	Front panel replacement quote? GZIP and cache static	tin	12/31/2011
1168	Keithley 2510	Feature	Closed	Normal	Get and flash correct firmware for 2510 into AT49F040 (U168)	tin	12/01/2011
298	_dev.xdevs.com	Feature	Closed	Normal	Graphviz not working, Error 500	tin	
945	HP 4263B	Feature	Closed	Normal	Hack to enable Option 001 and 002	tin	
1299	R&E	Feature	Closed	Normal	Help sonicyang to repair HP 34401A	tin	01/16/2016
1059	HP 4263B	Support	Closed	Low	Improve LCD to inverse 40x2?	tin	04/30/2014
878	_dev.xdevs.com	Feature	Closed	Normal	Improve and bug fix for theme / stylesheets.	tin	12/29/2013
861	HP 4263B	Feature	Closed	Normal	Initial check and repair estimate	tin	01/11/2014
1073	Raspberry Pi	Feature	Closed	Normal	Initial firmware to read/write SPD EEPROM (EC)	tin	05/21/2014
1070	Nikon DSLR	Feature	Closed	Normal	Initial inspection	tin	05/02/2014
958	Keithley 2002	Feature	Closed	Normal	Initial inspection for K2002 (331119346214)	tin	02/10/2014
638	HP/Agilent 33120A	Feature	Closed	Normal	Inspect unit, diagnose and isolate problem	tin	00/00/00
1361	Fluke 720A repair	Support	Closed	Normal	Inspection, photos and check Install DS1245V for MEM2 entire	tin tin	08/09/2016
1090	Keithley 2001 repair	Support	Closed	Normal	Install DS1245Y for MEM2 option	un tin	01/04/2014
772	Raspberry Pi Tektronix TDS/CSA7000 (CSA7404)	Feature Rework	Closed	Normal	Install I2C support for RPI Install Windows 2000 SP4 Pro for test	tin	
771	Tektronix TDS/CSA7000 (CSA7404) Tektronix TDS/CSA7000 (CSA7404)	Rework	Rejected	Normal	Install Windows 98 on another HDD for test.	tin	
768	Tektronix TDS/CSA7000 (CSA7404) Tektronix TDS/CSA7000 (CSA7404)	Feature	Closed	Normal	Install all system Tektronix drivers for devices on Win2000	tin	06/30/2013
282	Keithley 2001 repair	Rework	Closed	Normal	Install display board	tin	
1272	HP 3458A	Feature	Closed	Normal	Install memory option 001 back	tin	11/30/2015
237	_dev.xdevs.com	Feature	Closed	Normal	Integrate graphviz	tin	12/25/2011
879	Keithley 2001 repair	Bug	Closed	Normal	Issue list update	tin	
241	_dev.xdevs.com	Bug	Rejected	Normal	Issue view, top header background upgrade	tin	12/31/2011
277	Keithley 2001 repair	Bug	Closed	Normal	K2 - ERROR 405.2 – Absolute value x10 gain comparison; large +DAC output	tin	
275	Keithley 2001 repair	Bug	Closed	Normal	K2 - Error 402.1 - Frequency switch	tin	
272	Keithley 2001 repair	Support	Closed	Normal	K2 - repair status.	tin	07/02/02
268	Keithley 2001 repair	Bug	Closed	Normal	K2 : ERROR 105.2 - System trigger bus	tin tin	07/22/2012
271	Keithley 2001 repair	Feature	Closed	Normal	K2 : ERROR 304 Section K3 : ERROR 304 6 - Ohms sources: 70nA and 770nA	tin tin	
269	Keithley 2001 repair Keithley 2001 repair	Bug	Closed	Normal Normal	K2 : ERROR 304.6 - Ohms sources; 70nA and 770nA K2 : ERROR 304.7 - Ohms sources; 4.4nA and 770nA	tin	
274	Keithley 2001 repair Keithley 2001 repair	Bug Bug	Closed	Normal	K2 : ERROR 401.1 - Signal switching; zero cal switch	tin	
288	Keithley 2001 repair	Bug	Closed	High	K4 - repair status.	tin	02/28/2015
874	Keithley 2000	Feature	Closed	Normal	Keithley 2000 schematics	tin	12/23/2013
885	Keithley 2001 repair	Feature	Closed	Normal	Keithley 2001 thermal evaluation	tin	01/01/2014
654	_dev.xdevs.com	Feature	Closed		Knowledge base module added	tin	
925	кх	Inventory	Closed	Normal	LMV324I	tin	
939	кх	Inventory	Closed	Normal	LT1116CS8	tin	
938	KX	Inventory	Closed	Normal	LT1223CS8	tin	
940	KX	Inventory	Closed		LTC1043CSWPBF SOW18 Building block SW-CAP DUAL	tin	
926	KX	Inventory	Closed	Normal	LTC1050CS8	tin	
1087	KX	Inventory	Closed	Normal	LTC2057HS8 - 17pcs THD box	tin	
941	KX KS	Inventory	Closed	Normal	LTZ1000ACH SUPER-ZENER VREF	tin	00/00/00
852	Keithley 2001 repair	Feature	Closed	Normal	LabView control panel development MAYSS10ALIT town conser SOT33 S THD box 10pcs	un tin	02/28/2014
1088	KX HP 3458A	Inventory Feature	Closed	Normal Normal	MAX6610AUT temp sensor SOT23-6 THD box 10pcs Make 3D drawing for LTZ1000 plastic cap	tin	10/05/2015
1242	HP 3458A	Rework	Closed	Normal	Make CPLD logic replacement for PAL address decoder 03458-88804	tin	10/03/2013
1072	Raspberry Pi	Feature	Closed	Normal	Make DDR slot adapter for SPD read/write	tin	05/09/2014
85	R&E	Feature	Closed	Normal	Make PCI-E videocard test power assemble kit	tin	11/28/2010
1261	HP 3458A	Feature	Closed	Normal	Make measurement on integrator and reference path on A3 A/D board	tin	10/16/2015
1142	Keithley 2002	Feature	Closed	Normal	Measure LT1013+LTZ1000A VREF voltages	tin	07/21/2014
240	_dev.xdevs.com	Feature	Closed	Normal	Mercurial style	tin	12/26/2011
876	_dev.xdevs.com	Feature	Rejected	Normal	Merge with documentation site	tin	
1065	HP 4263B	Support	Closed	Normal	Modify LCR probe according to Agilent connection spec.	tin	04/20/2014
338	_dev.xdevs.com	Feature	Closed	High	Monospace font for <pre> and repository source view</pre>	tin	12/30/2012

#	Project	Tracker	Status	Priority	Subject	Assignee	Category	Due date
1227	content_mgmt	Feature	Closed	High	NI HS-GPIB-USB review	tin	Article	08/16/2015
335	_dev.xdevs.com	Bug	Closed	Normal	Need elevated rights for plugins and attached files, why?	tin		
283	Keithley 2001 repair	Rework	Closed	Normal	No response from analog board	tin		
770	_dev.xdevs.com	Bug	Closed	Normal	Notification emails are lost/not full	tin		06/03/2013
740	E-table 2	Feature	Closed	Normal	Onboard workspace PC system	tin		
998	KX	Support	Closed	Normal	Order PCBs for VREF A00 module	tin		03/27/2014
1237	HP 3458A	Feature	Closed	Normal	Order replacement parts from Keysight	tin		
754	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Outer covers replacement parts needed	tin		12/31/2013
947	HP 4263B		Closed			tin		
		Feature		Normal	PCB daughter board schematics recovery	tin		03/02/2014
934	KX	Inventory	Closed	Normal	PMBFJ111-215 JFET NCH 40V 20mA SOT23-3	tin		
933	KX	Inventory	Closed	Normal	PMBFJ620-115 NJFET DUAL 25V SOT363	tin		
860	HP 4263B	Feature	Closed	Normal	Pay for LCR meter	tin		12/14/2013
774	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Pay for pair of Tektronix P7380 TekConnect differential 8GHz probes	tin		06/04/2013
752	Tektronix TDS/CSA7000 (CSA7404)	Feature	Closed	Normal	Pay for scope unit for parts	tin		05/20/2013
1262	content_mgmt	Feature	Closed	Normal	Publish 3456A	tin	Article	10/25/2015
1167	Keithley 2510	Feature	Closed	Normal	Publish repair article about 2510 TEC SMU	tin		12/07/2014
119	AM2	Bug	Closed	Normal	R7,R8 - fix value to allow generator running	tin		
294	Keithley 2001 repair	Feature	Closed	Normal	Read and decode firmwares for 2001 DMMs	tin		08/10/2012
						tin		00/10/2012
166	Keithley 2510	Feature	Closed	Normal	Receive 2510 unit for repair	un		
53	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Receive scope, initial inspection	tin		05/31/2013
234	HP 3458A	Feature	Closed	Normal	Receive unit, initial inspection	tin		09/17/2015
266	HP3245A	Feature	Closed	Normal	Receive unit, initial inspection and tests	tin		
70	_dev.xdevs.com	Bug	Closed	Normal	Redirects to dummy redmine host when modify items using HTTPS	tin		
089	Nikon DSLR	Feature	Closed	High	Repair D3	tin		05/11/2014
184	Keithley 2001 repair		Closed	Normal	Repair status	tin		33.1.72014
		Bug				uii Ain		
185	Keithley 2001 repair	Bug	Closed	Normal	Repair status for very first 2001 unit	un		
71	Keithley 2001 repair	Bug	Closed	Normal	Replace C108 capacitor	tin		12/31/2013
'61	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Replace CD-ROM with DVD-RW drive	tin		05/23/2013
59	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Replace HDD, try fresh install windows and Tek software	tin		05/23/2013
243	HP 3458A	Feature	Closed	Normal	Replace capacitors on A6 board.	tin		
	Nikkor lens repair	Rework	Closed	Normal	Replace connection aperture ring	tin		
0	HP 4263B	Feature	Closed	Normal	Replace damaged components	tin		
						tin		01/05/0014
39	Keithley 2001 repair	Bug	Closed	Normal	Replace fan	un		01/05/2014
13	_dev.xdevs.com	Bug	Closed	Immediate	Repository system security update	tin		05/22/2014
'3	Keithley 2002	Feature	Rejected	Normal	Request correct repair manual for 2002	tin		02/28/2014
32	R&E	Support	Closed	Low	Requested Tektronix quotation for calibration with data	tin		
37	Keithley 2001 repair	Support	Closed	Normal	Review 2001's inventory	tin		02/16/2014
204	content_mgmt	Support	Closed	Normal	Rohde & Schwarz Signal generator SMT03 Repair	tin	Repairs	
79	Keithley 2001 repair	Feature	Closed	Normal	Schematics RE - analog board	tin	-1-20	07/31/2012
				+		tin		
20	Keithley 2001 repair	Support	Closed	Normal	Schematics for digital board (Keithley 2001-142-06H)	un		10/31/2013
112	Nikon DSLR	Feature	Closed	Normal	Schematics for fake EN-EL4a battery	tin		
31	Keithley 2001 repair	Support	Closed	Normal	Schematics for voltage reference LM399	tin		07/11/2014
6	Keithley 2001 repair	Support	Closed	Normal	Schematics recovery for analog board Keithley 2001	tin		07/21/2014
2	ALTERA 672 Checkout board repair	Support	Closed	High	Search documentation for "ALTERA 672 Checkout board"	tin		10/10/2012
91	Keithley 2001 repair	Feature	Closed	Normal	Self-test errors diagnosis	tin		01/05/2014
88	Keithley 2001 repair	Feature	Closed	Normal	Send 2001 DMM for calibration to Tektronix Taiwan	tin		01/12/2014
						tin		
36	Keithley 2400 repair	Support	Closed	Normal	Send 2400 SMU for calibration to Tektronix Taiwan	un		01/31/2014
33	ARM-camp	Feature	Rejected	Normal	Send development miniboard on AT91SAM7S128 to Adrian	tin		12/28/2011
69	Keithley 2001 repair	Feature	Closed	Normal	Spec test	tin		12/15/2013
34	_dev.xdevs.com	Bug	Closed	Normal	Stylesheet fix and color updates, fix footer, validate important pages	tin		
7	Tektronix TLA714	Feature	Closed	Normal	TEKTRONIX 020-2457-00 COMPRESSION PCB -to- MICTOR ADAPTER	tin		07/10/2012
0	KX	Inventory	Closed	Normal	TL7705ACDR	tin		
)7	Tektronix TDS/CSA7000 (CSA7404)	-	Closed		Tek CSA7404 scope repair article worklog	tin		01/04/2014
		Support		High		uii		01/04/2014
34	Keithley 2001 repair	Rework	Closed	Normal	Test digital board.	un		
236	HP 3458A	Rework	Closed	Normal	Test mains power supply domain & transformer	tin		
	T-14	Bug	Closed	Normal	Trigger encoder shaft damaged - replace encoder Bourns EPS1E-F19 S53	tin		
0	Tektronix TDS/CSA7000 (CSA7404)			Named	Try to run TDS7704B w/o connection between PPC and AQ boards?	tin		06/02/2013
	Tektronix TDS/CSA7000 (CSA7404) Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Try to fair 150/1045 W/o contribution 150 and 140 Sounds.			
9		Support Feature	Closed Closed	Normal	UART protocol between front panel board and digital board.	tin		
1	Tektronix TDS/CSA7000 (CSA7404)	Feature	Closed	Normal	UART protocol between front panel board and digital board.	tin		
9 4 5	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714	Feature Feature	Closed Closed	Normal Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4	tin tin	Renaire	
9 4 5 00	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt	Feature Feature Feature	Closed Closed Closed	Normal Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article	tin tin	Repairs	
9 4 5 00 4	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt _dev.xdevs.com	Feature Feature Feature Support	Closed Closed Closed Closed	Normal Normal Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article Update Redmine engine to 1.4.4	tin tin tin	Repairs	
59 55 200 54	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt	Feature Feature Feature	Closed Closed Closed Closed Closed	Normal Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article	tin tin tin tin tin	Repairs	05/20/2014
69 34 15 200 64	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt _dev.xdevs.com	Feature Feature Feature Support	Closed Closed Closed Closed	Normal Normal Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article Update Redmine engine to 1.4.4	tin tin tin tin tin tin tin	Repairs	05/20/2014
5 5 200 64 08	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt _dev.xdevs.com Raspberry Pi	Feature Feature Support Support	Closed Closed Closed Closed Closed	Normal Normal Normal Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article Update Redmine engine to 1.4.4 Update article to version 1.0	tin tin tin tin tin tin tin tin	Repairs	05/20/2014
69 34 15 200 64 108 36	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt _dev.xdevs.com Raspberry Pi _dev.xdevs.com	Feature Feature Support Support Feature Feature Feature	Closed Closed Closed Closed Closed Closed Closed	Normal Normal Normal Normal Normal Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article Update Redmine engine to 1.4.4 Update article to version 1.0 Update engine to 2.1.x branch	tin	Repairs	
69 34 15 200 64 108 36 73	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt _dev.xdevs.com Raspberry Pi _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com	Feature Feature Support Support Feature Feature Support	Closed	Normal Normal Normal Normal Normal Normal Normal Normal Immediate Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article Update Redmine engine to 1.4.4 Update article to version 1.0 Update engine to 2.1.x branch Update engine to 2.4.1 Update redmine to 2.5.0	tin	Repairs	12/23/2013 03/15/2014
69 34 55 200 64 08 36 73 99 216	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt _dev.xdevs.com Raspberry Pi _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com	Feature Feature Support Support Feature Feature Support Support Support Support	Closed	Normal Normal Normal Normal Normal Normal Immediate Normal High	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article Update Redmine engine to 1.4.4 Update article to version 1.0 Update engine to 2.1.x branch Update engine to 2.4.1 Update redmine to 2.5.0 Update redmine to latest 3.0.x trunk	tin	Repairs	12/23/2013 03/15/2014 07/20/2015
69 34 15 200 64 108 36 73 99 216 38	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt _dev.xdevs.com Raspberry Pi _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com	Feature Feature Support Support Feature Feature Support Feature Support Support Support Support	Closed	Normal Normal Normal Normal Normal Normal High Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article Update Redmine engine to 1.4.4 Update article to version 1.0 Update engine to 2.1.x branch Update engine to 2.4.1 Update redmine to 2.5.0 Update redmine to latest 3.0.x trunk Update repository server	tin	Repairs	12/23/2013 03/15/2014 07/20/2015 12/25/2011
69 84 115 200 64 1108 36 73 99 216 38	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt _dev.xdevs.com Raspberry Pi _dev.xdevs.com	Feature Feature Support Support Feature Feature Support Feature Support Support Support Support Support	Closed	Normal Normal Normal Normal Normal Normal High Normal Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article Update Redmine engine to 1.4.4 Update article to version 1.0 Update engine to 2.1.x branch Update engine to 2.4.1 Update redmine to 2.5.0 Update redmine to latest 3.0.x trunk Update repository server Update security certificate for crypted access to https://dev.xdevs.com	tin	Repairs	12/23/2013 03/15/2014 07/20/2015
880 669 884 115 200 664 108 36 773 99 216 38 39	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt _dev.xdevs.com Raspberry Pi _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com _dev.xdevs.com	Feature Feature Support Support Feature Feature Support Feature Support Support Support Support	Closed	Normal Normal Normal Normal Normal Normal High Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article Update Redmine engine to 1.4.4 Update article to version 1.0 Update engine to 2.1.x branch Update engine to 2.4.1 Update redmine to 2.5.0 Update redmine to latest 3.0.x trunk Update repository server	tin	Repairs	12/23/2013 03/15/2014 07/20/2015 12/25/2011
69 84 115 200 64 1108 36 73 99 216 38	Tektronix TDS/CSA7000 (CSA7404) Keithley 2001 repair Tektronix TLA714 content_mgmt _dev.xdevs.com Raspberry Pi _dev.xdevs.com	Feature Feature Support Support Feature Feature Support Feature Support Support Support Support Support	Closed	Normal Normal Normal Normal Normal Normal High Normal Normal	UART protocol between front panel board and digital board. Unlock more memory for TLA7AA4 Unlocking JLink article Update Redmine engine to 1.4.4 Update article to version 1.0 Update engine to 2.1.x branch Update engine to 2.4.1 Update redmine to 2.5.0 Update redmine to latest 3.0.x trunk Update repository server Update security certificate for crypted access to https://dev.xdevs.com	tin	Repairs	12/23/2013 03/15/2014 07/20/2015 12/25/2011

#	Project	Tracker	Status	Priority	Subject	Assignee	Category	Due date
858	Keithley 2001 repair	Bug	Closed	Normal	VFD Power supply issues?	tin		
154	WARP	Bug	Failed	Normal	VNOM- not connected to ground	tin		
1066	кх	Feature	Closed	Normal	VPG resistor for prototype build	tin		05/31/2014
642	Keithley 2001 repair	Feature	Closed	Normal	Voltage reference block schematics recovery	tin		12/17/2012
266	Tektronix TLA714	Feature	Closed	Normal	[eBay] New in the box Tektronix Tek P6860 Probe Set A2-A3/D2-D3	tin		07/16/2012
872	Tektronix TLA714	Feature	Closed	Normal	Бюджет проекта	tin		
1141	Keithley 2001 repair	Feature	Closed	Normal	Восстановление источника тока и диапазонов измерения сопротивления	tin		
1198	content_mgmt	Feature	Closed	Normal	Обзор прецизионного мультиметра Keithley 2001-M	tin	Article	
1233	content_mgmt	Feature	Closed	Normal	Перевод https://xdevs.com/article/ddr4s/	tin	Article	09/23/2015
1163	content_mgmt	Feature	Failed	Normal	Статьи к публикации	tin		05/31/2014
1038	content_mgmt	Feature	Closed	Normal	Статьи на апрель 2014	tin		04/30/2014
1039	content_mgmt	Feature	Failed	Normal	Статьи на май 2014	tin		05/31/2014
1205	content_mgmt	Feature	Closed	Normal	Статья-обзор паяльной станции ERSA I-CON	tin	Article	
859	Keithley 2001 repair	Feature	Closed	Normal	Схема аналоговой платы (Keithley 2001-102-04J)	tin		07/11/2014
817	Keithley 2001 repair	Support	Closed	Normal	Схема платы A/D (Keithley 2001-162-01G)	tin		10/03/2013
278	Keithley 2001 repair	Feature	Closed	Normal	D2 - checks			
289	ALTERA 672 Checkout board repair	Support	Closed	Normal	Receive board from EMS			08/10/2012
1336	X-CAL	Feature	Closed	Normal	Software specification			
1130	content_mgmt	Feature	Closed	Normal	Статьи на июль 2014			