

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Category	Due date
293	ALTERA 672 Checkout board repair	Feature	Closed	Normal	Power check - voltage in spec, power good - ok?	Izerg		
289	ALTERA 672 Checkout board repair	Support	Closed	Normal	Receive board from EMS			08/10/2012
291	ALTERA 672 Checkout board repair	Bug	Closed	High	VCC SSO замкнут на землю?	Izerg		
292	ALTERA 672 Checkout board repair	Support	Closed	High	Search documentation for "ALTERA 672 Checkout board"	tin		10/10/2012
119	AM2	Bug	Closed	Normal	R7,R8 - fix value to allow generator running	tin		
233	ARM-camp	Feature	Rejected	Normal	Send development miniboard on AT91SAM7S128 to Adrian	tin		12/28/2011
232	ARM-camp	Feature	Rejected	Normal	Add Redmine guide and intro based on dev.xdevs.com project	tin		12/30/2011
229	ARM-camp	Feature	Rejected	Normal	Add intro page about STM-Discovery to wiki, create first project	tin		01/15/2012
230	ARM-camp	Feature	Closed	Normal	Add mercurial DVCS intro to wiki	ARandomOWI		12/14/2011
740	E-table 2	Feature	Closed	Normal	Onboard workspace PC system	tin		
739	E-table 2	Support	Closed	Normal	Create initial design concept	tin		04/26/2015
1361	Fluke 720A repair	Support	Closed	Normal	Inspection, photos and check	tin		08/09/2016
1249	HP 3458A	Feature	Closed	Normal	Digikey order 2	tin		
1248	HP 3458A	Rework	Closed	Normal	Make CPLD logic replacement for PAL address decoder 03458-88804	tin		
1261	HP 3458A	Feature	Closed	Normal	Make measurement on integrator and reference path on A3 A/D board	tin		10/16/2015
1289	HP 3458A	Feature	Closed	Normal	1ppm/hour drift on new ADC board	tin		
1272	HP 3458A	Feature	Closed	Normal	Install memory option 001 back	tin		11/30/2015
1260	HP 3458A	Feature	Closed	Normal	ERROR 114 -- balanced multislope convergence	tin		
1259	HP 3458A	Bug	Closed	Normal	ERROR 114 -- multislope rundown convergence	tin		
1243	HP 3458A	Feature	Closed	Normal	Replace capacitors on A6 board.	tin		
1242	HP 3458A	Feature	Closed	Normal	Make 3D drawing for LTZ1000 plastic cap	tin		10/05/2015
1236	HP 3458A	Rework	Closed	Normal	Test mains power supply domain & transformer	tin		
1237	HP 3458A	Feature	Closed	Normal	Order replacement parts from Keysight	tin		
1235	HP 3458A	Rework	Closed	Normal	Buy and install A9 reference board	tin		
1234	HP 3458A	Feature	Closed	Normal	Receive unit, initial inspection	tin		09/17/2015
1059	HP 4263B	Support	Closed	Low	Improve LCD to inverse 40x2?	tin		04/30/2014
945	HP 4263B	Feature	Closed	Normal	Hack to enable Option 001 and 002	tin		
910	HP 4263B	Feature	Closed	Normal	Replace damaged components	tin		
947	HP 4263B	Feature	Closed	Normal	PCB daughter board schematics recovery	tin		03/02/2014
1065	HP 4263B	Support	Closed	Normal	Modify LCR probe according to Agilent connection spec.	tin		04/20/2014
861	HP 4263B	Feature	Closed	Normal	Initial check and repair estimate	tin		01/11/2014
907	HP 4263B	Feature	Rejected	Normal	Add option updates for 001 and 002	tin		01/12/2014
860	HP 4263B	Feature	Closed	Normal	Pay for LCR meter	tin		12/14/2013
639	HP/Agilent 33120A	Support	Closed	Normal	Add related documentation	tin		11/18/2012
638	HP/Agilent 33120A	Feature	Closed	Normal	Inspect unit, diagnose and isolate problem	tin		
1266	HP3245A	Feature	Closed	Normal	Receive unit, initial inspection and tests	tin		
1088	KX	Inventory	Closed	Normal	MAX6610AUT temp sensor SOT23-6 THD box 10pcs	tin		
1087	KX	Inventory	Closed	Normal	LTC2057HS8 - 17pcs THD box	tin		
941	KX	Inventory	Closed	Normal	LTZ1000ACH SUPER-ZENER VREF	tin		
940	KX	Inventory	Closed	Normal	LTC1043CSWPBF SOW18 Building block SW-CAP DUAL	tin		
939	KX	Inventory	Closed	Normal	LT1116CS8	tin		
938	KX	Inventory	Closed	Normal	LT1223CS8	tin		
934	KX	Inventory	Closed	Normal	PMBFJ111-215 JFET NCH 40V 20mA SOT23-3	tin		
933	KX	Inventory	Closed	Normal	PMBFJ620-115 NJFET DUAL 25V SOT363	tin		
930	KX	Inventory	Closed	Normal	TL7705ACDR	tin		
927	KX	Inventory	Closed	Normal	AD7490BRUZ	tin		
926	KX	Inventory	Closed	Normal	LTC1050CS8	tin		
925	KX	Inventory	Closed	Normal	LMV324I	tin		
1066	KX	Feature	Closed	Normal	VPG resistor for prototype build	tin		05/31/2014
998	KX	Support	Closed	Normal	Order PCBs for VREF A00 module	tin		03/27/2014
1178	Keithley 2000	Feature	Closed	Low	Check components on K2000 unit	tin		
1193	Keithley 2000	Feature	Closed	Normal	Buy parts for repair	tin		05/30/2015
1160	Keithley 2000	Support	Closed	Normal	Backup EEPROM with programm memory A02	tin		
1159	Keithley 2000	Rework	Closed	Normal	Clean board and restore damaged traces from leaked electrolyte	tin		09/22/2014
1158	Keithley 2000	Feature	Closed	Normal	Broken K2000 unit received, need repairs	tin		
874	Keithley 2000	Feature	Closed	Normal	Keithley 2000 schematics	tin		12/23/2013
956	Keithley 2001 repair	Feature	Closed	Normal	Calibration constants for K2001 units	tin		02/15/2014
852	Keithley 2001 repair	Feature	Closed	Normal	LabView control panel development	tin		02/28/2014
816	Keithley 2001 repair	Support	Closed	Normal	Schematics recovery for analog board Keithley 2001	tin		07/21/2014
637	Keithley 2001 repair	Support	Closed	Normal	Review 2001's inventory	tin		02/16/2014
272	Keithley 2001 repair	Support	Closed	Normal	K2 - repair status.	tin		
868	Keithley 2001 repair	Feature	Closed	Normal	Assembly meter for function checks.	tin		12/15/2013
879	Keithley 2001 repair	Bug	Closed	Normal	Issue list update	tin		
1188	Keithley 2001 repair	Feature	Closed	Normal	Dump firmware B17 from 2001M	tin		
1185	Keithley 2001 repair	Bug	Closed	Normal	Repair status for very first 2001 unit	tin		
891	Keithley 2001 repair	Feature	Closed	Normal	Self-test errors diagnosis	tin		01/05/2014
863	Keithley 2001 repair	Bug	Closed	Normal	Fix errors 405.2, 405.4, 405.6, 405.8, - Absolute value x10 gain comparison	tin		12/22/2013
278	Keithley 2001 repair	Feature	Closed	Normal	D2 - checks			
273	Keithley 2001 repair	Support	Closed	Normal	Buy components for repair	tin		07/30/2012

#	Project	Tracker	Status	Priority	Subject	Assignee	Category	Due date
1184	Keithley 2001 repair	Bug	Closed		Repair status	tin		
867	Keithley 2001 repair	Bug	Closed	Normal	Fix error 410.1, 411.1, 411.2 - TRMS / TRMS Filter	tin		12/29/2013
865	Keithley 2001 repair	Bug	Closed	Normal	Fix errors 407.1, 407.2, 407.3 - Front end 2V/200V/750V	tin		12/22/2013
864	Keithley 2001 repair	Bug	Closed	Normal	Fix error 406.6 – Voltage comparison	tin		12/22/2013
866	Keithley 2001 repair	Bug	Closed	Normal	Fix error 409.6 – ±750 correction factor; signal comparisons	tin		12/22/2013
862	Keithley 2001 repair	Bug	Closed	Normal	Fix errors 404.1, 404.2, 404.3, 404.4, 404.5 - Absolute value (x1 gain);	tin		12/22/2013
856	Keithley 2001 repair	Bug	Closed	Normal	Fix error 412.1 – AC amps switch	tin		12/28/2013
854	Keithley 2001 repair	Bug	Closed	Normal	Fix error 402.1 - Signal switching; frequency switch	tin		12/14/2013
658	Keithley 2001 repair	Bug	Closed	Normal	Fix 401.1 - Signal switching; zero cal switch	tin		01/13/2013
652	Keithley 2001 repair	Bug	Closed	Normal	Fix AC input mains curcuitry, replace electrolytic capacitors, replace transformer	tin		12/31/2012
895	Keithley 2001 repair	Feature	Closed	Normal	304.x series self-test errors (Ohm)	lzerg		01/05/2014
885	Keithley 2001 repair	Feature	Closed	Normal	Keithley 2001 thermal evaluation	tin		01/01/2014
858	Keithley 2001 repair	Bug	Closed	Normal	VFD Power supply issues?	tin		
869	Keithley 2001 repair	Feature	Closed	Normal	Spec test	tin		12/15/2013
871	Keithley 2001 repair	Bug	Closed	Normal	Replace C108 capacitor	tin		12/31/2013
818	Keithley 2001 repair	Support	Closed	Normal	Schematics for analog board (Keithley 2001-102-04L)	lzerg		07/21/2014
884	Keithley 2001 repair	Feature	Closed	Normal	UART protocol between front panel board and digital board.	tin		
855	Keithley 2001 repair	Bug	Closed	Normal	Fix error 403.1 – Signal switching; ground switch	tin		12/21/2013
859	Keithley 2001 repair	Feature	Closed	Normal	Схема аналоговой платы (Keithley 2001-102-04J)	tin		07/11/2014
1141	Keithley 2001 repair	Feature	Closed	Normal	Восстановление источника тока и диапазонов измерения сопротивления	tin		
1131	Keithley 2001 repair	Support	Closed	Normal	Schematics for voltage reference LM399	tin		07/11/2014
820	Keithley 2001 repair	Support	Closed	Normal	Schematics for digital board (Keithley 2001-142-06H)	tin		10/31/2013
817	Keithley 2001 repair	Support	Closed	Normal	Схема платы A/D (Keithley 2001-162-01G)	tin		10/03/2013
642	Keithley 2001 repair	Feature	Closed	Normal	Voltage reference block schematics recovery	tin		12/17/2012
641	Keithley 2001 repair	Feature	Closed	Normal	Finish AC input block schematics	tin		12/18/2012
297	Keithley 2001 repair	Feature	Closed	Normal	Finish ADC board schematics.	tin		12/11/2012
294	Keithley 2001 repair	Feature	Closed	Normal	Read and decode firmwares for 2001 DMMs	tin		08/10/2012
286	Keithley 2001 repair	Feature	Closed	Normal	Calibrate unit (Tektronix calibration)	tin		01/19/2014
281	Keithley 2001 repair	Feature	Closed	Normal	Display board move to unit #4	tin		
277	Keithley 2001 repair	Bug	Closed	Normal	K2 - ERROR 405.2 – Absolute value x10 gain comparison; large +DAC output	tin		
276	Keithley 2001 repair	Bug	Closed	Normal	ERROR 404.1 – Absolute value (x1 gain); -full-scale DAC output	tin		
275	Keithley 2001 repair	Bug	Closed	Normal	K2 - Error 402.1 - Frequency switch	tin		
274	Keithley 2001 repair	Bug	Closed	Normal	K2 : ERROR 401.1 - Signal switching; zero cal switch	tin		
271	Keithley 2001 repair	Feature	Closed	Normal	K2 : ERROR 304 Section	tin		
270	Keithley 2001 repair	Bug	Closed	Normal	K2 : ERROR 304.7 - Ohms sources; 4.4nA and 770nA	tin		
269	Keithley 2001 repair	Bug	Closed	Normal	K2 : ERROR 304.6 - Ohms sources; 70nA and 770nA	tin		
268	Keithley 2001 repair	Bug	Closed	Normal	K2 : ERROR 105.2 - System trigger bus	tin		07/22/2012
343	Keithley 2001 repair	Bug	Closed	Normal	Send K2001 #5 to iZerg	lzerg		10/31/2012
659	Keithley 2001 repair	Bug	Rejected	Normal	Fix Test 412.1 – AC amps switch	tin		01/13/2013
342	Keithley 2001 repair	Bug	Closed	Normal	Fix FE section on analog board	tin		09/09/2012
889	Keithley 2001 repair	Bug	Closed	Normal	Replace fan	tin		01/05/2014
890	Keithley 2001 repair	Support	Closed	Normal	Install DS1245Y for MEM2 option	tin		01/04/2014
888	Keithley 2001 repair	Feature	Closed	Normal	Send 2001 DMM for calibration to Tektronix Taiwan	tin		01/12/2014
819	Keithley 2001 repair	Support	Closed	Normal	Схема платы передней панели	tin		10/08/2013
535	Keithley 2001 repair	Bug	Closed	Normal	AC voltage select unit fails	tin		10/21/2012
894	Keithley 2001 repair	Support	Closed	Normal	iZerg Keithley serial number request	lzerg		01/05/2014
840	Keithley 2001 repair	Support	Closed	Normal	3 ADC modules shipped, receive and test rest units	tin		11/09/2013
279	Keithley 2001 repair	Feature	Closed	Normal	Schematics RE - analog board	tin		07/31/2012
284	Keithley 2001 repair	Rework	Closed	Normal	Test digital board.	tin		
285	Keithley 2001 repair	Rework	Closed	Normal	All functions and all ranges "Overflow"	tin		08/05/2012
283	Keithley 2001 repair	Rework	Closed	Normal	No response from analog board	tin		
282	Keithley 2001 repair	Rework	Closed	Normal	Install display board	tin		
288	Keithley 2001 repair	Bug	Closed	High	K4 - repair status.	tin		02/28/2015
1142	Keithley 2002	Feature	Closed	Normal	Measure LT1013+LTZ1000A VREF voltages	tin		07/21/2014
973	Keithley 2002	Feature	Rejected	Normal	Request correct repair manual for 2002	tin		02/28/2014
958	Keithley 2002	Feature	Closed	Normal	Initial inspection for K2002 (331119346214)	tin		02/10/2014
908	Keithley 2400 repair	Bug	Closed	Low	Front panel replacement quote?	tin		
887	Keithley 2400 repair	Bug	Closed	Normal	Fix front panel keypad	tin		01/01/2014
886	Keithley 2400 repair	Support	Closed	Normal	Send 2400 SMU for calibration to Tektronix Taiwan	tin		01/31/2014
287	Keithley 2400 repair	Feature	Rejected	Normal	Calibrate outputs	tin		08/11/2012
1170	Keithley 2510	Feature	Closed	Normal	Calibrate unit	tin		12/06/2014
1168	Keithley 2510	Feature	Closed	Normal	Get and flash correct firmware for 2510 into AT49F040 (U168)	tin		
1166	Keithley 2510	Feature	Closed	Normal	Receive 2510 unit for repair	tin		
1167	Keithley 2510	Feature	Closed	Normal	Publish repair article about 2510 TEC SMU	tin		12/07/2014
893	Keithley 7001	Support	Rejected	Low	Front board taken for Keithley 2001, get replacement?	tin		
767	Nikkor lens repair	Rework	Closed	Normal	Replace connection aperture ring	tin		
766	Nikkor lens repair	Bug	Closed	Normal	Buy replacement parts for 17-35	tin		05/31/2013
1112	Nikon DSLR	Feature	Closed	Normal	Schematics for fake EN-EL4a battery	tin		
1080	Nikon DSLR	Feature	Closed	Normal	Adjust EH-4 AC brick for 13VDC output for D3	tin		
1070	Nikon DSLR	Feature	Closed	Normal	Initial inspection	tin		05/02/2014
1089	Nikon DSLR	Feature	Closed	High	Repair D3	tin		05/11/2014

#	Project	Tracker	Status	Priority	Subject	Assignee	Category	Due date
4	PWMC	Bug	Closed	Normal	Firmware and hardware check	tin		
882	R&E	Support	Closed	Low	Requested Tektronix quotation for calibration with data	tin		
955	R&E	Feature	Closed	Normal	EDC MV106 calibration	tin		
905	R&E	Support	Closed	Normal	Buy parts for K2001 project repairs	tin		01/05/2014
1299	R&E	Feature	Closed	Normal	Help sonicyang to repair HP 34401A	tin		01/16/2016
1123	R&E	Support	Closed	Normal	Fluke 52 II thermometer calibration - 89020093	tin		06/10/2014
881	R&E	Support	Closed	Normal	EDC MV106 DC Voltage standard backlog	tin		12/31/2013
296	R&E	Feature	Closed	Normal	iZerg support package	lzerg		10/03/2012
85	R&E	Feature	Closed	Normal	Make PCI-E videocard test power assemble kit	tin		11/28/2010
1092	Raspberry Pi	Feature	Closed	Low	DDR3/DDR4 SPD read tool for RPi+DDR4s	tin		05/25/2014
1073	Raspberry Pi	Feature	Closed	Normal	Initial firmware to read/write SPD EEPROM (EC)	tin		05/21/2014
1074	Raspberry Pi	Feature	Closed	Normal	3D model of DIMM adapter assembly	tin		
1108	Raspberry Pi	Support	Closed	Normal	Update article to version 1.0	tin		05/20/2014
1106	Raspberry Pi	Feature	Closed	Normal	Add checksum checks/validation function	tin		05/19/2014
1072	Raspberry Pi	Feature	Closed	Normal	Make DDR slot adapter for SPD read/write	tin		05/09/2014
1090	Raspberry Pi	Feature	Closed	Normal	Install I2C support for RPi	tin		
1071	Raspberry Pi	Feature	Closed	Normal	Buy Raspberry Pi module	tin		04/27/2014
857	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Buy Tek P6205 probe for general voltage measurements (40V pk-pk)	tin		01/31/2014
768	Tektronix TDS/CSA7000 (CSA7404)	Feature	Closed	Normal	Install all system Tektronix drivers for devices on Win2000	tin		06/30/2013
754	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Outer covers replacement parts needed	tin		12/31/2013
880	Tektronix TDS/CSA7000 (CSA7404)	Bug	Closed	Normal	Trigger encoder shaft damaged - replace encoder Bourns EPS1E-F19 S53	tin		
753	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Receive scope, initial inspection	tin		05/31/2013
759	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Replace HDD, try fresh install windows and Tek software	tin		05/23/2013
796	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Upgrade CPU to Pentium III, add extra memory for NLX board, install DVD-RW	tin		
795	Tektronix TDS/CSA7000 (CSA7404)	Bug	Closed	Normal	Channel 1 out of cal?	tin		
794	Tektronix TDS/CSA7000 (CSA7404)	Bug	Closed	Normal	Channel 2 and 3 not powering Tektronix P7380 probe, not working?	tin		
774	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Pay for pair of Tektronix P7380 TekConnect differential 8GHz probes	tin		06/04/2013
773	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Buy BR1632 3V battery for NVRAM DALLAS replacement with leads	tin		
769	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	Normal	Try to run TDS7704B w/o connection between PPC and AQ boards?	tin		06/02/2013
761	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Replace CD-ROM with DVD-RW drive	tin		05/23/2013
760	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Download and write CD-R with Win98/2000	tin		05/22/2013
772	Tektronix TDS/CSA7000 (CSA7404)	Rework	Closed	Normal	Install Windows 2000 SP4 Pro for test	tin		
771	Tektronix TDS/CSA7000 (CSA7404)	Rework	Rejected	Normal	Install Windows 98 on another HDD for test.	tin		
752	Tektronix TDS/CSA7000 (CSA7404)	Feature	Closed	Normal	Pay for scope unit for parts	tin		05/20/2013
807	Tektronix TDS/CSA7000 (CSA7404)	Support	Closed	High	Tek CSA7404 scope repair article worklog	tin		01/04/2014
299	Tektronix TLA714	Feature	Closed	Normal	Add actual internal pics, add documentation	tin		08/25/2012
872	Tektronix TLA714	Feature	Closed	Normal	Бюджет проекта	tin		
815	Tektronix TLA714	Feature	Closed	Normal	Unlock more memory for TLA7AA4	tin		
267	Tektronix TLA714	Feature	Closed	Normal	TEKTRONIX 020-2457-00 COMPRESSION PCB -to- MICTOR ADAPTER	tin		07/10/2012
266	Tektronix TLA714	Feature	Closed	Normal	[eBay] New in the box Tektronix Tek P6860 Probe Set A2-A3/D2-D3	tin		07/16/2012
693	Tektronix TLA714	Feature	Closed	Normal	Firmware binary for TLA7AA4 5.5.003	tin		
692	Tektronix TLA714	Feature	Closed	Normal	Firmware binary for TLA7AA4 5.8.001	tin		
808	Tektronix TLA714	Feature	Closed	Normal	Backup NVRAM on TLA7AA4	tin		09/20/2013
805	Tektronix TLA714	Bug	Closed	Normal	Battery for CMOS died on PC board, date got reset	tin		09/15/2013
154	WARP	Bug	Failed	Normal	VNOM- not connected to ground	tin		
1336	X-CAL	Feature	Closed	Normal	Software specification	tin		
876	_dev.xdevs.com	Feature	Rejected	Normal	Merge with documentation site	tin		
1126	_dev.xdevs.com	Bug	Closed	Normal	Deployment issue with redmine engine	tin		
999	_dev.xdevs.com	Support	Closed	Normal	Update redmine to 2.5.0	tin		03/15/2014
878	_dev.xdevs.com	Feature	Closed	Normal	Improve and bug fix for theme / stylesheets.	tin		12/29/2013
334	_dev.xdevs.com	Bug	Closed	Normal	Stylesheet fix and color updates, fix footer, validate important pages	tin		
770	_dev.xdevs.com	Bug	Closed	Normal	Notification emails are lost/not full	tin		06/03/2013
898	_dev.xdevs.com	Feature	Closed	Normal	Added issuefy importer	tin		01/05/2014
335	_dev.xdevs.com	Bug	Closed	Normal	Need elevated rights for plugins and attached files, why?	tin		
654	_dev.xdevs.com	Feature	Closed	Normal	Knowledge base module added	tin		
670	_dev.xdevs.com	Bug	Closed	Normal	Redirects to dummy redmine host when modify items using HTTPS	tin		
237	_dev.xdevs.com	Feature	Closed	Normal	Integrate graphviz	tin		12/25/2011
241	_dev.xdevs.com	Bug	Rejected	Normal	Issue view, top header background upgrade	tin		12/31/2011
536	_dev.xdevs.com	Feature	Closed	Normal	Update engine to 2.1.x branch	tin		
264	_dev.xdevs.com	Support	Closed	Normal	Update Redmine engine to 1.4.4	tin		
298	_dev.xdevs.com	Feature	Closed	Normal	Graphviz not working, Error 500	tin		
244	_dev.xdevs.com	Bug	Closed	Normal	Fix Gantt view (stylesheet or plugin)	tin		12/31/2011
243	_dev.xdevs.com	Feature	Closed	Normal	GZIP and cache static	tin		12/31/2011
236	_dev.xdevs.com	Feature	Closed	Normal	Upgrade redmine site to latest trunk version	tin		12/25/2011
240	_dev.xdevs.com	Feature	Closed	Normal	Mercurial style	tin		12/26/2011
238	_dev.xdevs.com	Bug	Closed	Normal	Update repository server	tin		12/25/2011
239	_dev.xdevs.com	Support	Closed	Normal	Update security certificate for crypted access to https://dev.xdevs.com	tin		12/25/2011
1216	_dev.xdevs.com	Support	Closed	High	Update redmine to latest 3.0.x trunk	tin		07/20/2015
333	_dev.xdevs.com	Bug	Rejected	High	Caching working not right, need refresh page manually	tin		
338	_dev.xdevs.com	Feature	Closed	High	Monospace font for <pre> and repository source view	tin		12/30/2012
242	_dev.xdevs.com	Bug	Closed	High	Users cannot login with current password, must use "lost password feature" due to security enhancement	tin		12/30/2011

#	Project	Tracker	Status	Priority	Subject	Assignee	Category	Due date
263	_dev.xdevs.com	Feature	Closed	Urgent	Devsite crashes after few days	tin		10/14/2012
1113	_dev.xdevs.com	Bug	Closed	Immediate	Repository system security update	tin		05/22/2014
873	_dev.xdevs.com	Feature	Closed	Immediate	Update engine to 2.4.1	tin		12/23/2013
1233	content_mgmt	Feature	Closed	Normal	Перевод https://xdevs.com/article/ddr4s/	tin	Article	09/23/2015
1039	content_mgmt	Feature	Failed	Normal	Статьи на май 2014	tin		05/31/2014
1262	content_mgmt	Feature	Closed	Normal	Publish 3456A	tin	Article	10/25/2015
1200	content_mgmt	Feature	Closed	Normal	Unlocking JLink article	tin	Repairs	
1163	content_mgmt	Feature	Failed	Normal	Статьи к публикации	tin		05/31/2014
1226	content_mgmt	Feature	Closed	Normal	ALTERA MAX II DEVBOARD review	tin	Article	
1198	content_mgmt	Feature	Closed	Normal	Обзор прецизионного мультиметра Keithley 2001-M	tin	Article	
1201	content_mgmt	Feature	Closed	Normal	Fluke 51-II thermometer	tin	Article	
1229	content_mgmt	Feature	Closed	Normal	Article for DMM noise measurement analysis	tin	Article	08/06/2015
1205	content_mgmt	Feature	Closed	Normal	Статья-обзор паяльной станции ERSА I-CON	tin	Article	
1206	content_mgmt	Feature	Closed	Normal	Article-review Parallax SmartPack 672	tin	Article	
1204	content_mgmt	Support	Closed	Normal	Rohde & Schwarz Signal generator SMT03 Repair	tin	Repairs	
1157	content_mgmt	Feature	Closed	Normal	Articles for September 2014	tin		
1130	content_mgmt	Feature	Closed	Normal	Статьи на июль 2014			
1038	content_mgmt	Feature	Closed	Normal	Статьи на апрель 2014	tin		04/30/2014
1227	content_mgmt	Feature	Closed	High	NI HS-GPIB-USB review	tin	Article	08/16/2015