

## Group by project

#	Tracker	Status	Priority	Subject	Assignee	Category	Due date
<b>ALTERA 672 Checkout board repair (8)</b>							
293	Feature	Closed	Normal	Power check - voltage in spec, power good - ok?	Izerg		
680	Feature	Closed	Normal	Project suspend	Izerg		
289	Support	Closed	Normal	Receive board from EMS			08/10/2012
292	Support	Closed	High	Search documentation for "ALTERA 672 Checkout board"	tin		10/10/2012
291	Bug	Closed	High	VCC SSO замкнут на землю?	Izerg		
339	Feature	Closed	High	Восстановление компонентов	Izerg		
341	Feature	Closed	Normal	Проверка программирования платы			
340	Feature	Closed	High	Тестирование платы под полным питанием.	Izerg		
<b>ALTERA SMB2 Repair (1)</b>							
295	Rework	In Progress	Normal	Debug JTAG Stratix communication issue	tin		
<b>AM2 (1)</b>							
119	Bug	Closed	Normal	R7,R8 - fix value to allow generator running	tin		
<b>ARM-camp (4)</b>							
232	Feature	Rejected	Normal	Add Redmine guide and intro based on dev.xdevs.com project	tin		12/30/2011
229	Feature	Rejected	Normal	Add intro page about STM-Discovery to wiki, create first project	tin		01/15/2012
230	Feature	Closed	Normal	Add mercurial DVCS intro to wiki	ARandomOWI		12/14/2011
233	Feature	Rejected	Normal	Send development miniboard on AT91SAM7S128 to Adrian	tin		12/28/2011
<b>E-table 2 (2)</b>							
739	Support	Closed	Normal	Create initial design concept	tin		04/26/2015
740	Feature	Closed	Normal	Onboard workspace PC system	tin		
<b>Fluke 720A repair (1)</b>							
1361	Support	Closed	Normal	Inspection, photos and check	tin		08/09/2016
<b>HP 3245A (5)</b>							
1283	Feature	New	Normal	Recalibrate unit after update to LTZ	tin		
1265	Feature	Resolved	Normal	Receive unit, initial inspection	tin		11/03/2015
1281	Rework	New	Normal	Replace LM399 to LTZ1000	tin		
1270	Feature	New	Normal	Replace capacitors, take more photos of internal parts for article	tin		11/25/2015
1282	Feature	New	Normal	Test calibration, save calibration RAM	tin		
<b>HP 3458A (19)</b>							
1289	Feature	Closed	Normal	1ppm/hour drift on new ADC board	tin		
1258	Feature	New	Normal	Adapter board for LMH6321 buffer	tin		
1257	Feature	In Progress	Normal	Adapter boards for Intersil comparators and EL22xxCM	tin		
1235	Rework	Closed	Normal	Buy and install A9 reference board	tin		
1249	Feature	Closed	Normal	Digikey order 2	tin		
1260	Feature	Closed	Normal	ERROR 114 -- balanced multislope convergence	tin		
1259	Bug	Closed	Normal	ERROR 114 -- multislope rundown convergence	tin		
1272	Feature	Closed	Normal	Install memory option 001 back	tin		11/30/2015
1271	Feature	New	Normal	Install optics on external trigger on A6 PCBA	tin		
1242	Feature	Closed	Normal	Make 3D drawing for LTZ1000 plastic cap	tin		10/05/2015
1248	Rework	Closed	Normal	Make CPLD logic replacement for PAL address decoder 03458-88804	tin		
1261	Feature	Closed	Normal	Make measurement on integrator and reference path on A3 A/D board	tin		10/16/2015
1285	Feature	In Progress	Normal	Measure stability per SN 18	tin		11/26/2015
1237	Feature	Closed	Normal	Order replacement parts from Keysight	tin		
1234	Feature	Closed	Normal	Receive unit, initial inspection	tin		09/17/2015
1238	Feature	Resolved	Normal	Repairs			
1243	Feature	Closed	Normal	Replace capacitors on A6 board.	tin		
1236	Rework	Closed	Normal	Test mains power supply domain & transformer	tin		
1279	Feature	New	Normal	Usage items	tin		
<b>HP 4263B (11)</b>							
907	Feature	Rejected	Normal	Add option updates for 001 and 002	tin		01/12/2014
945	Feature	Closed	Normal	Hack to enable Option 001 and 002	tin		
1059	Support	Closed	Low	Improve LCD to inverse 40x2?	tin		04/30/2014
861	Feature	Closed	Normal	Initial check and repair estimate	tin		01/11/2014
948	Feature	New	Normal	Inputs protection curcuitry	tin		01/22/2014
1065	Support	Closed	Normal	Modify LCR probe according to Agilent connection spec.	tin		04/20/2014
947	Feature	Closed	Normal	PCB daughter board schematics recovery	tin		03/02/2014
860	Feature	Closed	Normal	Pay for LCR meter	tin		12/14/2013
946	Feature	In Progress	Normal	Recover inputs schematics and power modules schematics	tin		03/02/2014
910	Feature	Closed	Normal	Replace damaged components	tin		
906	Feature	In Progress	Normal	Review and teardown article	tin		01/18/2014
<b>HP/Agilent 33120A (2)</b>							
639	Support	Closed	Normal	Add related documentation	tin		11/18/2012
638	Feature	Closed	Normal	Inspect unit, diagnose and isolate problem	tin		
<b>HP3245A (1)</b>							

#	Tracker	Status	Priority	Subject	Assignee	Category	Due date
1266	Feature	Closed	Normal	Receive unit, initial inspection and tests	tin		
<b>KX (26)</b>							
927	Inventory	Closed	Normal	AD7490BRUZ	tin		
1014	Support	In Progress	Low	Components supply for project	tin		
952	Feature	New	Normal	Define spec for project	tin		02/01/2014
1086	Inventory	New	Normal	Film SMD capacitor LDECB3100JA0N00 0.1uF 50VDC 1210	tin		
949	Feature	In Progress	Normal	Front panel design	tin		02/09/2014
950	Inventory	Resolved	Normal	GU256X64-355 display	tin		
883	Support	In Progress	Normal	Keithley 2001 ADC model, Multisim 12 project	tin		01/31/2014
925	Inventory	Closed	Normal	LMV3241	tin		
937	Inventory	In Progress	Normal	LT1097S8	tin		
939	Inventory	Closed	Normal	LT1116CS8	tin		
938	Inventory	Closed	Normal	LT1223CS8	tin		
940	Inventory	Closed	Normal	LTC1043CSWPBF SOW18   Building block SW-CAP DUAL	tin		
926	Inventory	Closed	Normal	LTC1050CS8	tin		
1087	Inventory	Closed	Normal	LTC2057HS8 - 17pcs THD box	tin		
941	Inventory	Closed	Normal	LTZ1000ACH SUPER-ZENER VREF	tin		
1088	Inventory	Closed	Normal	MAX6610AUT temp sensor SOT23-6 THD box 10pcs	tin		
971	Feature	New	Normal	Open-hardware transition	tin		02/23/2014
998	Support	Closed	Normal	Order PCBs for VREF A00 module	tin		03/27/2014
1078	Feature	In Progress	Normal	PCB for low-thermal shorting plug	tin		06/29/2014
934	Inventory	Closed	Normal	PMBFJ111-215 JFET NCH 40V 20mA SOT23-3	tin		
933	Inventory	Closed	Normal	PMBFJ620-115 NJFET DUAL 25V SOT363	tin		
1067	Support	New	Normal	References / 3rd-party resources	tin		
930	Inventory	Closed	Normal	TL7705ACDR	tin		
1066	Feature	Closed	Normal	VPG resistor for prototype build	tin		05/31/2014
1068	Feature	In Progress	Normal	Wire-wound precision resistors samples	tin		
1298	Feature	Closed	Normal	test new draw front panel	tin		01/09/2016
<b>KX-A (1)</b>							
1280	Feature	New	Normal	2A current amp	tin		
<b>KX-DAC (1)</b>							
1191	Feature	In Progress	Normal	Schematics design	tin		05/03/2015
<b>KX-H : Low-noise amp (3)</b>							
1132	Feature	New	Low	Collect existing solutions and applications.	tin		
1165	Feature	New	Normal	PCB layout for amp module KX-H	tin		11/09/2014
1164	Feature	In Progress	Normal	Schematics release for modular prototype	tin		10/31/2014
<b>Keithley 2000 (7)</b>							
1160	Support	Closed	Normal	Backup EEPROM with programm memory A02	tin		
1158	Feature	Closed	Normal	Broken K2000 unit received, need repairs	tin		
1193	Feature	Closed	Normal	Buy parts for repair	tin		05/30/2015
1178	Feature	Closed	Low	Check components on K2000 unit	tin		
1159	Rework	Closed	Normal	Clean board and restore damaged traces from leaked electrolyte	tin		09/22/2014
874	Feature	Closed	Normal	Keithley 2000 schematics	tin		12/23/2013
1162	Support	Closed	Normal	Memory for A20			
<b>Keithley 2001 repair (76)</b>							
840	Support	Closed	Normal	3 ADC modules shipped, receive and test rest units	tin		11/09/2013
895	Feature	Closed	Normal	304.x series self-test errors (Ohm)	lzerg		01/05/2014
535	Bug	Closed	Normal	AC voltage select unit fails	tin		10/21/2012
650	Feature	Closed	High	ADC board	lzerg		
285	Rework	Closed	Normal	All functions and all ranges "Overflow"	tin		08/05/2012
1196	Feature	New	Normal	Analog interface protocol	tin		
868	Feature	Closed	Normal	Assembly meter for function checks.	tin		12/15/2013
273	Support	Closed	Normal	Buy components for repair	tin		07/30/2012
286	Feature	Closed	Normal	Calibrate unit (Tektronix calibration)	tin		01/19/2014
956	Feature	Closed	Normal	Calibration constants for K2001 units	tin		02/15/2014
647	Feature	Closed	Normal	Cook transformer in paraffin to avoid buzzing	lzerg		12/17/2012
819	Support	Closed	Normal	Схема платы передней панели	tin		10/08/2013
278	Feature	Closed	Normal	D2 - checks			
281	Feature	Closed	Normal	Display board move to unit #4	tin		
1188	Feature	Closed	Normal	Dump firmware B17 from 2001M	tin		
276	Bug	Closed	Normal	ERROR 404.1 – Absolute value (x1 gain); -full-scale DAC output	tin		
641	Feature	Closed	Normal	Finish AC input block schematics	tin		12/18/2012
297	Feature	Closed	Normal	Finish ADC board schematics.	tin		12/11/2012
658	Bug	Closed	Normal	Fix 401.1 - Signal switching; zero cal switch	tin		01/13/2013
652	Bug	Closed	Normal	Fix AC input mains curcuitry, replace electrolytic capacitors, replace transformer	tin		12/31/2012
342	Bug	Closed	Normal	Fix FE section on analog board	tin		09/09/2012
659	Bug	Rejected	Normal	Fix Test 412.1 – AC amps switch	tin		01/13/2013
854	Bug	Closed	Normal	Fix error 402.1 - Signal switching; frequency switch	tin		12/14/2013

#	Tracker	Status	Priority	Subject	Assignee	Category	Due date
855	Bug	Closed	Normal	Fix error 403.1 – Signal switching; ground switch	tin		12/21/2013
864	Bug	Closed	Normal	Fix error 406.6 – Voltage comparison	tin		12/22/2013
866	Bug	Closed	Normal	Fix error 409.6 – ÷750 correction factor; signal comparisons	tin		12/22/2013
867	Bug	Closed	Normal	Fix error 410.1, 411.1, 411.2 - TRMS / TRMS Filter	tin		12/29/2013
856	Bug	Closed	Normal	Fix error 412.1 – AC amps switch	tin		12/28/2013
862	Bug	Closed	Normal	Fix errors 404.1, 404.2, 404.3, 404.4, 404.5 - Absolute value (x1 gain);	tin		12/22/2013
863	Bug	Closed	Normal	Fix errors 405.2, 405.4, 405.6, 405.8, - Absolute value x10 gain comparison	tin		12/22/2013
865	Bug	Closed	Normal	Fix errors 407.1, 407.2, 407.3 - Front end 2V/200V/750V	tin		12/22/2013
890	Support	Closed	Normal	Install DS1245Y for MEM2 option	tin		01/04/2014
282	Rework	Closed	Normal	Install display board	tin		
879	Bug	Closed	Normal	Issue list update	tin		
277	Bug	Closed	Normal	K2 - ERROR 405.2 – Absolute value x10 gain comparison; large +DAC output	tin		
275	Bug	Closed	Normal	K2 - Error 402.1 - Frequency switch	tin		
272	Support	Closed	Normal	K2 - repair status.	tin		
268	Bug	Closed	Normal	K2 : ERROR 105.2 - System trigger bus	tin		07/22/2012
271	Feature	Closed	Normal	K2 : ERROR 304 Section	tin		
269	Bug	Closed	Normal	K2 : ERROR 304.6 - Ohms sources; 70nA and 770nA	tin		
270	Bug	Closed	Normal	K2 : ERROR 304.7 - Ohms sources; 4.4nA and 770nA	tin		
274	Bug	Closed	Normal	K2 : ERROR 401.1 - Signal switching; zero cal switch	tin		
974	Support	Closed	Normal	K2001_Amps_out_of_Tol	tin		
288	Bug	Closed	High	K4 - repair status.	tin		02/28/2015
885	Feature	Closed	Normal	Keithley 2001 thermal evaluation	tin		01/01/2014
852	Feature	Closed	Normal	LabView control panel development	tin		02/28/2014
283	Rework	Closed	Normal	No response from analog board	tin		
294	Feature	Closed	Normal	Read and decode firmwares for 2001 DMMs	tin		08/10/2012
1184	Bug	Closed	Normal	Repair status	tin		
1185	Bug	Closed	Normal	Repair status for very first 2001 unit	tin		
871	Bug	Closed	Normal	Replace C108 capacitor	tin		12/31/2013
889	Bug	Closed	Normal	Replace fan	tin		01/05/2014
637	Support	Closed	Normal	Review 2001's inventory	tin		02/16/2014
279	Feature	Closed	Normal	Schematics RE - analog board	tin		07/31/2012
818	Support	Closed	Normal	Schematics for analog board (Keithley 2001-102-04L)	lzerg		07/21/2014
820	Support	Closed	Normal	Schematics for digital board (Keithley 2001-142-06H)	tin		10/31/2013
1131	Support	Closed	Normal	Schematics for voltage reference LM399	tin		07/11/2014
816	Support	Closed	Normal	Schematics recovery for analog board Keithley 2001	tin		07/21/2014
891	Feature	Closed	Normal	Self-test errors diagnosis	tin		01/05/2014
888	Feature	Closed	Normal	Send 2001 DMM for calibration to Tektronix Taiwan	tin		01/12/2014
343	Bug	Closed	Normal	Send K2001 #5 to iZerg	lzerg		10/31/2012
869	Feature	Closed	Normal	Spec test	tin		12/15/2013
284	Rework	Closed	Normal	Test digital board.	tin		
884	Feature	Closed	Normal	UART protocol between front panel board and digital board.	tin		
858	Bug	Closed	Normal	VFD Power supply issues?	tin		
642	Feature	Closed	Normal	Voltage reference block schematics recovery	tin		12/17/2012
839	Feature	Closed	Low	analog board photo	tin		10/26/2013
968	Support	Closed	High	eprom A07543	tin		
894	Support	Closed	Normal	iZerg Keithley serial number request	lzerg		01/05/2014
912	Support	Closed	Low	repo_test	tin		
853	Support	Feedback	Normal	Бюджет проекта	tin		
1138	Feature	Closed	Normal	Восстановление источника тока и диапазонов измерения сопротивления	lzerg		07/21/2014
1141	Feature	Closed	Normal	Восстановление источника тока и диапазонов измерения сопротивления	tin		
1134	Feature	Closed	Normal	Рисовать схему ИОН	tin		07/21/2014
859	Feature	Closed	Normal	Схема аналоговой платы (Keithley 2001-102-04J)	tin		07/11/2014
817	Support	Closed	Normal	Схема платы A/D (Keithley 2001-162-01G)	tin		10/03/2013
<b>Keithley 2002 (13)</b>							
1301	Feature	New	Normal	CAL 2002 to 2001			
963	Feature	New	Normal	Calibration constants for K2002	tin		02/23/2014
901	Support	In Progress	Normal	Collect photos of 2002 internals	tin		
958	Feature	Closed	Normal	Initial inspection for K2002 (331119346214)	tin		02/10/2014
1142	Feature	Closed	Normal	Measure LT1013+LTZ1000A VREF voltages	tin		07/21/2014
1314	Rework	Resolved	Normal	Repair unit 2	tin		03/25/2016
973	Feature	Rejected	Normal	Request correct repair manual for 2002	tin		02/28/2014
964	Support	New	Normal	SCH   Схема аналоговой платы (Keithley 2002-xxx-04x)	tin		06/30/2014
902	Bug	New	Normal	Self-test fails			
1296	Feature	Resolved	Normal	Test with different mains	tin		
972	Feature	In Progress	Normal	Thermal photos for K2002	tin		02/23/2014
965	Support	New	Normal	Восстановить схему для ремонта и отладки Keithley 2002	tin		06/30/2014
966	Support	Resolved	Normal	Схема платы A/D (Keithley 2002-xxx-01x)	tin		03/01/2014
<b>Keithley 2400 repair (4)</b>							
287	Feature	Rejected	Normal	Calibrate outputs	tin		08/11/2012
887	Bug	Closed	Normal	Fix front panel keypad	tin		01/01/2014

#	Tracker	Status	Priority	Subject	Assignee	Category	Due date
908	Bug	Closed	Low	Front panel replacement quote?	tin		
886	Support	Closed	Normal	Send 2400 SMU for calibration to Tektronix Taiwan	tin		01/31/2014
<b>Keithley 2510 (5)</b>							
1170	Feature	Closed	Normal	Calibrate unit	tin		12/06/2014
1168	Feature	Closed	Normal	Get and flash correct firmware for 2510 into AT49F040 (U168)	tin		
1167	Feature	Closed	Normal	Publish repair article about 2510 TEC SMU	tin		12/07/2014
1166	Feature	Closed	Normal	Receive 2510 unit for repair	tin		
1169	Feature	Suspended	Normal	X-K2510RH - resistor heater adapter design	tin		
<b>Keithley 7001 (1)</b>							
893	Support	Rejected	Low	Front board taken for Keithley 2001, get replacement?	tin		
<b>Nikkor lens repair (3)</b>							
766	Bug	Closed	Normal	Buy replacement parts for 17-35	tin		05/31/2013
767	Rework	Closed	Normal	Replace connection aperture ring	tin		
781	Bug	New	Normal	SWM AF mechanism have issues when focusing	tin		
<b>Nikon DSLR (5)</b>							
1080	Feature	Closed	Normal	Adjust EH-4 AC brick for 13VDC output for D3	tin		
1079	Feature	New	Normal	D800 external power hack / ID workaround	tin		
1070	Feature	Closed	Normal	Initial inspection	tin		05/02/2014
1089	Feature	Closed	High	Repair D3	tin		05/11/2014
1112	Feature	Closed	Normal	Schematics for fake EN-EL4a battery	tin		
<b>PWMC (1)</b>							
4	Bug	Closed	Normal	Firmware and hardware check	tin		
<b>R&amp;E (18)</b>							
1010	Support	Resolved	Normal	Aquired ERS A I-CON1 soldering station	tin		03/20/2014
1117	Feature	New	Normal	Article about measuring low capacitance with DMM	tin		05/25/2014
905	Support	Closed	Normal	Buy parts for K2001 project repairs	tin		01/05/2014
1075	Feature	In Progress	Normal	Cadence tutorial feedback & review	tin		
993	Support	In Progress	Normal	Cadence tutorial for Orcad (Component management)	tin		
881	Support	Closed	Normal	EDC MV106 DC Voltage standard backlog	tin		12/31/2013
955	Feature	Closed	Normal	EDC MV106 calibration	tin		
1123	Support	Closed	Normal	Fluke 52 II thermometer calibration - 89020093	tin		06/10/2014
1299	Feature	Closed	Normal	Help sonicyang to repair HP 34401A	tin		01/16/2016
85	Feature	Closed	Normal	Make PCI-E videocard test power assemble kit	tin		11/28/2010
882	Support	Closed	Low	Requested Tektronix quotation for calibration with data	tin		
954	Feature	In Progress	Normal	Resistors test	tin		02/28/2014
1302	Feature	New	Normal	Wolf resistors	tin		
296	Feature	Closed	Normal	iZerg support package	lzerg		10/03/2012
1011	Support	In Progress	Normal	Добавить модели для Solidworks	tin		
1012	Support	Resolved	Normal	Заказать компоненты	tin		
1013	Support	New	Normal	Заказать плату	tin		
1295	Support	In Progress	Normal	Мини-стенд - ворклог	aizen		
<b>REF-R (6)</b>							
1177	Feature	In Progress	Normal	2 x VREFs sale	tin		02/23/2015
970	Feature	New	Normal	Battery power option for references	tin		
1018	Support	In Progress	Normal	Community feedback / units allocation	tin		
1024	Support	In Progress	Normal	Module tracklog	tin		
1128	Feature	New	Normal	Order PCBs for VREF B01 module , VREF RATIO, Shorting plug	tin		06/28/2014
1022	Bug	In Progress	Normal	VREF Board A01 errata	tin		04/05/2014
<b>Raspberry Pi (10)</b>							
1074	Feature	Closed	Normal	3D model of DIMM adapter assembly	tin		
1106	Feature	Closed	Normal	Add checksum checks/validation function	tin		05/19/2014
1107	Feature	New	Low	Add multiple module support on single RPI bus	tin		05/24/2014
1071	Feature	Closed	Normal	Buy Raspberry Pi module	tin		04/27/2014
1092	Feature	Closed	Low	DDR3/DDR4 SPD read tool for RPI+DDR4s	tin		05/25/2014
1073	Feature	Closed	Normal	Initial firmware to read/write SPD EEPROM (EC)	tin		05/21/2014
1090	Feature	Closed	Normal	Install I2C support for RPI	tin		
1072	Feature	Closed	Normal	Make DDR slot adapter for SPD read/write	tin		05/09/2014
1108	Support	Closed	Normal	Update article to version 1.0	tin		05/20/2014
1111	Feature	New	Low	XMP parser / information tool	tin		05/25/2014
<b>TC-M (1)</b>							
1104	Feature	New	Normal	Bought components supply	tin		
<b>Tektronix TDS/CSA7000 (CSA7404) (24)</b>							
773	Rework	Closed	Normal	Buy BR1632 3V battery for NVRAM DALLAS replacement with leads	tin		
857	Support	Closed	Normal	Buy Tek P6205 probe for general voltage measurements (40V pk-pk)	tin		01/31/2014
795	Bug	Closed	Normal	Channel 1 out of cal?	tin		
794	Bug	Closed	Normal	Channel 2 and 3 not powering Tektronix P7380 probe, not working?	tin		

#	Tracker	Status	Priority	Subject	Assignee	Category	Due date
969	Bug	New	Low	Check write-protection switch mode	tin		
892	Feature	New	Normal	Clean and repair P6205 probe	tin		
1155	Feature	In Progress	Normal	DSA71604 option	tin		09/05/2014
1103	Feature	Resolved	Normal	Dead again, software hangs during bootup - fixed with new DS1245YP	tin		
760	Rework	Closed	Normal	Download and write CD-R with Win98/2000	tin		05/22/2013
1197	Support	Closed	Normal	Front panel Led			
772	Rework	Closed	Normal	Install Windows 2000 SP4 Pro for test	tin		
771	Rework	Rejected	Normal	Install Windows 98 on another HDD for test.	tin		
768	Feature	Closed	Normal	Install all system Tektronix drivers for devices on Win2000	tin		06/30/2013
754	Rework	Closed	Normal	Outer covers replacement parts needed	tin		12/31/2013
774	Support	Closed	Normal	Pay for pair of Tektronix P7380 TekConnect differential 8GHz probes	tin		06/04/2013
752	Feature	Closed	Normal	Pay for scope unit for parts	tin		05/20/2013
753	Support	Closed	Normal	Receive scope, initial inspection	tin		05/31/2013
761	Rework	Closed	Normal	Replace CD-ROM with DVD-RW drive	tin		05/23/2013
759	Rework	Closed	Normal	Replace HDD, try fresh install windows and Tek software	tin		05/23/2013
959	Feature	Resolved	Normal	TCA-1MEG review	tin		02/16/2014
807	Support	Closed	High	Tek CSA7404 scope repair article worklog	tin		01/04/2014
880	Bug	Closed	Normal	Trigger encoder shaft damaged - replace encoder Bourns EPS1E-F19 S53	tin		
769	Support	Closed	Normal	Try to run TDS7704B w/o connection between PPC and AQ boards?	tin		06/02/2013
796	Support	Closed	Normal	Upgrade CPU to Pentium III, add extra memory for NLX board, install DVD-RW	tin		
<b>Tektronix TLA714 (14)</b>							
299	Feature	Closed	Normal	Add actual internal pics, add documentation	tin		08/25/2012
808	Feature	Closed	Normal	Backup NVRAM on TLA7AA4	tin		09/20/2013
805	Bug	Closed	Normal	Battery for CMOS died on PC board, date got reset	tin		09/15/2013
693	Feature	Closed	Normal	Firmware binary for TLA7AA4 5.5.003	tin		
692	Feature	Closed	Normal	Firmware binary for TLA7AA4 5.8.001	tin		
980	Feature	In Progress	Normal	I2C decode support library	tin		03/15/2014
747	Feature	New	Normal	Mictor-2.54mm adapter board - LA-TP Board REV 01 www.sar-systems.com	tin		04/09/2013
979	Feature	In Progress	Normal	Report issue regarding TLA Application under Winx64	tin		03/10/2014
981	Feature	Resolved	Normal	SPI Decode support library	tin		03/22/2014
267	Feature	Closed	Normal	TEKTRONIX 020-2457-00 COMPRESSION PCB -to- MICTOR ADAPTER	tin		07/10/2012
815	Feature	Closed	Normal	Unlock more memory for TLA7AA4	tin		
266	Feature	Closed	Normal	[eBay] New in the box Tektronix Tek P6860 Probe Set A2-A3/D2-D3	tin		07/16/2012
872	Feature	Closed	Normal	Бюджет проекта	tin		
1175	Support	In Progress	Normal	Декодирование данных I2C с помощью TLA714	tin		01/31/2015
<b>WARP (1)</b>							
154	Bug	Failed	Normal	VNOM- not connected to ground	tin		
<b>X-CAL (1)</b>							
1336	Feature	Closed	Normal	Software specification			
<b>_dev.xdevs.com (49)</b>							
258	Feature	Closed	Normal	404 when deleting file from wiki	tin		
673	Feature	Closed	Normal	Add Git support	tin		
671	Feature	Planning	Normal	Add RhodeCode to dev.xdevs.com	tin		
898	Feature	Closed	Normal	Added issuefy importer	tin		01/05/2014
333	Bug	Rejected	High	Caching working not right, need refresh page manually	tin		
1007	Bug	Planning	Normal	Contacts plugin cause Internal error	tin		
1126	Bug	Closed	Normal	Deployment issue with redmine engine	tin		
263	Feature	Closed	Urgent	Devsite crashes after few days	tin		10/14/2012
822	Feature	New	Normal	Don't send suspended issues by email notifications	tin		
666	Bug	Closed	Low	F5 required to update issues page in project	tin		
244	Bug	Closed	Normal	Fix Gantt view (stylesheet or plugin)	tin		12/31/2011
243	Feature	Closed	Normal	GZIP and cache static	tin		12/31/2011
662	Bug	Closed	High	Graphviz doesn't show on wiki pages	tin		
298	Feature	Closed	Normal	Graphviz not working, Error 500	tin		
1223	Feature	New	Normal	I18n for custom/user fields in redmine			
877	Feature	Planning	Normal	Implement documetation portal	tin		
878	Feature	Closed	Normal	Improve and bug fix for theme / stylesheets.	tin		12/29/2013
237	Feature	Closed	Normal	Integrate graphviz	tin		12/25/2011
241	Bug	Rejected	Normal	Issue view, top header background upgrade	tin		12/31/2011
654	Feature	Closed	Normal	Knowledge base module added	tin		
240	Feature	Closed	Normal	Mercurial style	tin		12/26/2011
876	Feature	Rejected	Normal	Merge with documentation site	tin		
338	Feature	Closed	High	Monospace font for <pre> and repository source view	tin		12/30/2012
335	Bug	Closed	Normal	Need elevated rights for plugins and attached files, why?	tin		
770	Bug	Closed	Normal	Notification emails are lost/not full	tin		06/03/2013
1077	Feature	Resolved	High	Page style issues for dev.xdevs.com	tin		04/27/2014
1002	Feature	In Progress	Normal	Port articles to django site	tin		03/16/2014
661	Bug	Closed	High	Problems creating new project	tin		
1063	Feature	Planning	Normal	Project index	tin		11/30/2015

#	Tracker	Status	Priority	Subject	Assignee	Category	Due date
670	Bug	Closed	Normal	Redirects to dummy redmine host when modify items using HTTPS	tin		
337	Feature	Planning	Normal	Reformat issue view for easier usage. Slim design	tin		
1139	Feature	Closed	Normal	Reminder issue reminder	tin		
1113	Bug	Closed	Immediate	Repository system security update	tin		05/22/2014
655	Feature	New	Normal	Separate theme/style to separate dedicated xdevs-blue theme module	tin		01/02/2013
257	Bug	Closed	High	Site very slow at times	tin		
1052	Support	Closed	High	Style CSS for font colors	tin		04/27/2014
334	Bug	Closed	Normal	Stylesheet fix and color updates, fix footer, validate important pages	tin		
264	Support	Closed	Normal	Update Redmine engine to 1.4.4	tin		
536	Feature	Closed	Normal	Update engine to 2.1.x branch	tin		
873	Feature	Closed	Immediate	Update engine to 2.4.1	tin		12/23/2013
1217	Support	Planning	Normal	Update header and footer on redmine to match django site.	tin		07/26/2015
999	Support	Closed	Normal	Update redmine to 2.5.0	tin		03/15/2014
1216	Support	Closed	High	Update redmine to latest 3.0.x trunk	tin		07/20/2015
238	Bug	Closed	Normal	Update repository server	tin		12/25/2011
239	Support	Closed	Normal	Update security certificate for crypted access to https://dev.xdevs.com	tin		12/25/2011
236	Feature	Closed	Normal	Upgrade redmine site to latest trunk version	tin		12/25/2011
242	Bug	Closed	High	Users cannot login with current password, must use "lost password feature" due to security enhancement	tin		12/30/2011
336	Feature	New	Normal	autoupdate SCM in redmine for autotrack issues	tin		
899	Support	In Progress	Normal	Отзывы и замечания по новому UI redmine?	tin		
<b>content_mgmt (31)</b>							
1226	Feature	Closed	Normal	ALTERA MAX II DEVBOARD review	tin	Article	
900	Feature	New	Low	Add interactive plugin for common electronics calculations	tin		05/31/2014
1229	Feature	Closed	Normal	Article for DMM noise measurement analysis	tin	Article	08/06/2015
1206	Feature	Closed	Normal	Article-review Parallax SmartPack 672	tin	Article	
1157	Feature	Closed	Normal	Articles for September 2014	tin		
649	Feature	In Progress	High	Cadence 3d - краткий гайд по связи с Solidworks	lzerg		12/13/2012
123	Feature	New	Normal	DIY Shunt article			
1201	Feature	Closed	Normal	Fluke 51-II thermometer	tin	Article	
1202	Feature	Resolved	Normal	HP 11177B - Calibration module from HP 3455A	tin	Article	
122	Feature	In Progress	Normal	Make article-review about voltage references.	tin		
1227	Feature	Closed	High	NI HS-GPIB-USB review	tin	Article	08/16/2015
234	Support	In Progress	Normal	Prepare and release xDevs.com coding standard	tin	Documentation	01/11/2012
1262	Feature	Closed	Normal	Publish 3456A	tin	Article	10/25/2015
1204	Support	Closed	Normal	Rohde & Schwarz Signal generator SMT03 Repair	tin	Repairs	
1199	Feature	Planning	Normal	Second life for dead VGA cards - using as high-power power supply	tin	Article	
1264	Feature	New	Normal	Style improvements for articles	tin	Article	
1288	Feature	Feedback	Normal	TI ADS1262 EVM article series review	tin	Article	01/18/2016
1203	Feature	In Progress	Normal	Taking proper photographs of electronic hardware and PCBAs	tin	Article	
1224	Feature	In Progress	Normal	Translate articles to both languages	tin	Article	08/24/2015
1200	Feature	Closed	Normal	Unlocking JLink article	tin	Repairs	
903	Support	Planning	Normal	Write tutorial about using redmine for projects	tin	Documentation	01/31/2014
1198	Feature	Closed	Normal	Обзор прецизионного мультиметра Keithley 2001-M	tin	Article	
1233	Feature	Closed	Normal	Перевод https://xdevs.com/article/ddr4s/	tin	Article	09/23/2015
1163	Feature	Failed	Normal	Статьи к публикации	tin		05/31/2014
1038	Feature	Closed	Normal	Статьи на апрель 2014	tin		04/30/2014
1130	Feature	Closed	Normal	Статьи на июль 2014			
1039	Feature	Failed	Normal	Статьи на май 2014	tin		05/31/2014
1187	Feature	In Progress	Normal	Статьи на май 2015			
1409	Feature	In Progress	Normal	Статьи по работе с графическими экранами	lzerg	Article	09/06/2018
1205	Feature	Closed	Normal	Статья-обзор паяльной станции ERSА I-CON	tin	Article	
1219	Feature	In Progress	Normal	Статья-руководство для публикаций с использованием textile	lzerg	Article	