

HP 4263B - Support #1059

Improve LCD to inverse 40x2?

04/10/2014 12:08 AM - tin

Status: Closed	Start date: 04/10/2014
Priority: Low	Due date: 04/30/2014
Assignee: tin	% Done: 100%
Category:	Estimated time: 1.00 hour
Target version:	
Description	
Replace HD44780-compatible screen to inverse Hantronix HDM40216L-1-VSOF ?	

History

#1 - 04/17/2014 01:43 AM - tin

- Status changed from New to In Progress
- Priority changed from Normal to Low
- Estimated time set to 1.00 h

Bought LCD, need get invoice and pay.

14 USD + 25 USD shipping.

#2 - 04/17/2014 01:31 PM - tin

Paid.

#3 - 04/30/2014 12:05 PM - tin

- % Done changed from 0 to 50

Received LCD.

#4 - 04/30/2014 09:09 PM - tin

- Status changed from In Progress to Resolved
- % Done changed from 50 to 100

FR006.jpg

[Repository](#)

#5 - 07/09/2014 12:10 AM - tin

- Status changed from Resolved to Closed

Files

12785571904021611.pdf	43.4 KB	04/10/2014	tin
-----------------------	---------	------------	-----