

**Nikon DSLR - Feature #1079**

**D800 external power hack / ID workaround**

05/01/2014 02:21 AM - tin

<b>Status:</b> New	<b>Start date:</b> 05/01/2014
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b> tin	<b>% Done:</b> 0%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b> D800 external power hack	
<b>Description</b>	
Probably got fake EP-5B adapter, which does not work on D800.	
If use ID from real EN-EL15 battery and power 7.400VDC from Keithley 2400 - camera works fine.	
Attached captured data from scope on ID signal between camera and connector.	

<b>Files</b>			
140501_015125.rar	866 KB	05/01/2014	tin