

**Tektronix TDS/CSA7000 (CSA7404) - Feature #1103**

**Dead again, software hangs during bootup - fixed with new DS1245YP**

05/17/2014 05:46 PM - tin

<b>Status:</b>	Resolved	<b>Start date:</b>	05/17/2014
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	tin	<b>% Done:</b>	100%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>			
<b>Description</b>			
Battery fail?			

**History**

**#1 - 10/06/2015 07:56 AM - tin**

- Status changed from *New* to *In Progress*

NVRAM Failed self-test, ordered new NVRAM

**#2 - 10/13/2015 05:54 AM - tin**

New DS1245YP on it's way!

**#3 - 10/14/2015 04:25 AM - tin**

Delivered.

**#4 - 10/14/2015 06:00 PM - tin**

- Status changed from *In Progress* to *Resolved*

- % Done changed from 0 to 100

Replaced chip, works fine!

**#5 - 10/14/2015 06:00 PM - tin**

- Subject changed from *Dead again, software hangs during bootup.* to *Dead again, software hangs during bootup - fixed with new DS1245YP*