

Tektronix TDS/CSA7000 (CSA7404) - Feature #1103

Dead again, software hangs during bootup - fixed with new DS1245YP

17/05/2014 17:46 - tin

Status:	Resolved	Start date:	17/05/2014
Priority:	Normal	Due date:	
Assignee:	tin	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
Battery fail?			

History

#1 - 06/10/2015 07:56 - tin

- Status changed from New to In Progress

NVRAM Failed self-test, ordered new NVRAM

#2 - 13/10/2015 05:54 - tin

New DS1245YP on it's way!

#3 - 14/10/2015 04:25 - tin

Delivered.

#4 - 14/10/2015 18:00 - tin

- Status changed from In Progress to Resolved

- % Done changed from 0 to 100

Replaced chip, works fine!

#5 - 14/10/2015 18:00 - tin

- Subject changed from Dead again, software hangs during bootup. to Dead again, software hangs during bootup - fixed with new DS1245YP