

Keithley 2001 repair - Bug #659

Fix Test 412.1 – AC amps switch

01/13/2013 03:15 PM - tin

Status:	Rejected	Start date:	01/13/2013
Priority:	Normal	Due date:	01/13/2013
Assignee:	tin	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:	Keithley 2001 #6		
Description			
replace CR305 and CR309			

History

#1 - 12/11/2013 08:43 PM - tin

- Status changed from In Progress to Rejected

Duplicate

#2 - 07/13/2014 01:37 AM - tin

- Target version changed from Keithley 2001 #7 to Keithley 2001 #6