

**Keithley 2001 repair - Feature #868****Assembly meter for function checks.**

12/15/2013 04:18 PM - tin

<b>Status:</b> Closed	<b>Start date:</b> 12/15/2013
<b>Priority:</b> Normal	<b>Due date:</b> 12/15/2013
<b>Assignee:</b> tin	<b>% Done:</b> 80%
<b>Category:</b>	<b>Estimated time:</b> 2.00 hours
<b>Target version:</b> Keithley 2001 #7	
<b>Description</b> Chassis: 2001-305E Stock fan: ELINA HDF4012L-12HB 12V 0.1A Power XFRMR: TR280 REV.C GT A641 SN 7579221 Analog board: 2001-102L SN A35772 Analog board bottom shield: 2001-342 B Analog board top shield: 2001-324 B ADC board: 2001-162 H, SN A35824 Scanner card: 2001-TCSCAN SN 1213886 Digital board: 2001-142G, SN A07967 , Firmware A05, memory STD Sony CXK5864BP-12LL Front panel: 2001-302F AMIT Front panel board: 2001-112D, SN A07273, Firmware 7001-800-A01	

**History****#1 - 01/05/2014 04:40 AM - tin***- Status changed from Resolved to Closed*

Digital board: 2001-142G, SN A07967 , Firmware A05, memory MEM2 DALLAS DS1245Y

**#2 - 07/13/2014 01:28 AM - tin***- Category set to 61**- Status changed from Closed to Feedback**- % Done changed from 100 to 80*

Цифровая плата заменена из-за выхода из строя U625. Калибровочные данные перенесены.

S/N прибора - 544257

**#3 - 07/13/2014 01:33 AM - tin***- Target version changed from Keithley 2001 #5 to Keithley 2001 #7***#4 - 06/07/2016 01:36 AM - tin***- Status changed from Feedback to Closed*