

Tektronix TDS/CSA7000 (CSA7404) - Bug #969

Check write-protection switch mode

02/17/2014 07:23 PM - tin

Status: New	Start date: 02/17/2014
Priority: Low	Due date:
Assignee: tin	% Done: 0%
Category:	Estimated time: 0.00 hour
Target version:	
Description	
Currently scope resets all settings back to default on every power off. Maybe back-side switch for write-protect is in wrong position.	
Check it later.	