

Keithley 2002 - Feature #973**Request correct repair manual for 2002**

02/23/2014 08:33 PM - tin

Status:	Rejected	Start date:	02/24/2014
Priority:	Normal	Due date:	02/28/2014
Assignee:	tin	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:	#1		

Description

Designators don't match components in repair manual.

Example ADC board:

RefDes	Repair manual	Board
U231	MAX326CSE	AD706
U232	LN35DM	MAX236
U233	Missing	AD705
U254	74HC165D	OP177
U255	74HC165D	AD707
C801-823	DIODE, ZENER, 6.2V, MMS26V2 SOD-123	?
C824-828	IC, QUAD 2 IN NOR, 74HCT02	?
C829	IC, NCHAN LAT DMOS QUADFET, SD5400CY	?
C830, 831	FERRITE CHIP 600 OHM BLM32A07	?
C832, 833	CAP, 2200P, 10%, 100V CERAMIC	?
C834, 835	IC, 8 STAGE SHIFT/STORE, MC14094BD	?
C836	IC, OP-AMP, AD847JR	?
C837	IC, HI-SPEED BIFET OP-AMP, AD711JR	?

History

#1 - 02/24/2014 11:25 AM - tin

- Description updated

- Status changed from New to In Progress

- % Done changed from 0 to 50

#2 - 07/21/2014 12:49 AM - tin

- Status changed from In Progress to Rejected

- % Done changed from 50 to 100

Unable to get correct manual from Keithley service/Taiwan.