

Nikon DSLR - Feature #1070**Initial inspection**

04/21/2014 08:46 PM - tin

Status: Closed	Start date: 04/21/2014
Priority: Normal	Due date: 05/02/2014
Assignee: tin	% Done: 100%
Category:	Estimated time: 3.00 hours
Target version: D3 Repair	
Description	
Receive unit and initial inspection and condition check.	

History**#1 - 05/05/2014 12:29 PM - tin**

- Status changed from New to In Progress
- % Done changed from 0 to 50

Battery cover/holder damaged
Blown PNP BJT 2SA2023 on DC-DC board
Fuse on DC in board ok

#2 - 05/06/2014 12:47 AM - tin

- File d3w.jpg added
- File _DSC5980.JPG added
- Target version set to D3 Repair
- % Done changed from 50 to 80

PNP replaced.
Camera powers on correctly.

Mirror mechanism locking up from time to time.

#3 - 05/06/2014 01:21 AM - tin

- File D3-1.jpg added
- File D3-1-2.jpg added
- File D3-1-3.jpg added

#4 - 05/25/2014 02:44 AM - tin

- Status changed from In Progress to Closed
- % Done changed from 80 to 100

Files

d3w.jpg	40.4 KB	05/06/2014	tin
_DSC5980.JPG	6.04 MB	05/06/2014	tin
D3-1.jpg	4.73 MB	05/06/2014	tin
D3-1-2.jpg	1.55 MB	05/06/2014	tin
D3-1-3.jpg	4.94 MB	05/06/2014	tin