

Nikon DSLR - Feature #1112

Schematics for fake EN-EL4a battery

05/20/2014 11:47 PM - tin

Status: Closed	Start date: 05/20/2014
Priority: Normal	Due date:
Assignee: tin	% Done: 90%
Category:	Estimated time: 0.00 hour
Target version: D3 fake battery repair	
Description	
Protection of Lithium Ion Batteries - Mitsumi MM1414C	

History

#1 - 05/22/2014 12:16 AM - tin

- Status changed from In Progress to Resolved

- % Done changed from 0 to 90

Battery repaired.

Replaced PFETs.

#2 - 11/05/2015 01:42 AM - tin

- Status changed from Resolved to Closed