

Nikon DSLR - Feature #1112

Schematics for fake EN-EL4a battery

20/05/2014 23:47 - tin

Status:	Closed	Start date:	20/05/2014
Priority:	Normal	Due date:	
Assignee:	tin	% Done:	90%
Category:		Estimated time:	0.00 hour
Target version:	D3 fake battery repair		
Description			
Protection of Lithium Ion Batteries - Mitsumi MM1414C			

History

#1 - 22/05/2014 00:16 - tin

- Status changed from *In Progress* to *Resolved*

- % Done changed from 0 to 90

Battery repaired.

Replaced PFETs.

#2 - 05/11/2015 01:42 - tin

- Status changed from *Resolved* to *Closed*