

**Fluke 720A repair - Support #1361**

**Inspection, photos and check**

08/09/2016 09:58 AM - tin

<b>Status:</b> Closed	<b>Start date:</b> 08/09/2016
<b>Priority:</b> Normal	<b>Due date:</b> 08/09/2016
<b>Assignee:</b> tin	<b>% Done:</b> 0%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b>	
<b>BOX ID:</b>	<b>MFG:</b>
<b>QTY:</b>	
<b>Description</b> Test input and output resistances. Post initial article with photos.	

**History**

#1 - 10/11/2016 01:04 PM - tin

- Status changed from New to Closed